


Rexroth IndraDyn L Ironless Linear Motors MCL

R911330592
Edition 02

Project Planning Manual



Title Rexroth IndraDyn L
Ironless Linear Motors MCL

Type of Documentation Project Planning Manual

Document Typecode DOK-MOTOR*-MCL*****-PR02-EN-P

Internal File Reference RS-82551fe8ab5f14650a6846a001697ff3-5-en-US-5

Record of Revision

Edition	Release Date	Notes
DOK-MOTOR*-MCL*****-PR01-EN-P	2011-01-11	Edition 01
DOK-MOTOR*-MCL*****-PR01-EN-P	2011-06-24	Edition 01.1 (frame size MCL030 added)
DOK-MOTOR*-MCL*****-PR01-EN-P	2011-07-13	Edition 01.2 (technical data updated)
DOK-MOTOR*-MCL*****-PR02-EN-P	2012-07-10	Edition 02 (revision and supplementation MCP070M)

Copyright © Bosch Rexroth AG 2012

This document, as well as the data, specifications and other information set forth in it, are the exclusive property of Bosch Rexroth AG. It may not be reproduced or given to third parties without its consent.

Liability The specified data is intended for product description purposes only and shall not be deemed to be a guaranteed characteristic unless expressly stipulated in the contract. All rights are reserved with respect to the content of this documentation and the availability of the product.

Liability The specified data is intended for product description purposes only and shall not be deemed to be a guaranteed characteristic unless expressly stipulated in the contract. All rights are reserved with respect to the content of this documentation and the availability of the product.

Published by Bosch Rexroth AG
Electric Drives and Controls
Dept. DC-IA/EDM3 (fs, mb)
Postfach 13 57
97803 Lohr, Germany
Buergermeister-Dr.-Nebel-Strasse 2
97816 Lohr, Germany
Tel. +49 93 52 18 0 / Fax +49 93 52 18 8400
<http://www.boschrexroth.com/electrics>

Note This document has been printed on chlorine-free bleached paper.

Table of Contents

	Page
1 Rexroth MCL - Product Presentation.....	9
1.1 Fields of Application Ironless Linear Motors.....	9
1.2 Construction Ironless Linear Motors.....	10
1.3 Comparison Ironless with Ferrous Linear Motors.....	10
1.4 Power Spectrum of MCL Motors.....	11
1.5 About this Documentation.....	12
1.5.1 Document Structure.....	12
1.5.2 Additional Documentation.....	12
1.5.3 Standards.....	13
1.5.4 Additional Components.....	13
1.5.5 Your Feedback.....	13
2 Important Instructions on Use.....	15
2.1 Appropriate Use.....	15
2.1.1 Introduction.....	15
2.1.2 Areas of Use and Application.....	15
2.2 Inappropriate Use.....	16
3 Safety Instructions for Electric Drives and Controls.....	17
3.1 Definition of Terms.....	17
3.2 General Information.....	18
3.2.1 Using the Safety Instructions and Passing Them on to Others.....	18
3.2.2 Requirements for Safe Use.....	18
3.2.3 Hazards by Improper Use.....	19
3.3 Requirements for Safe Use.....	20
3.3.1 Protection Against Contact with Electrical Parts and Housings.....	20
3.3.2 Protective Extra-Low Voltage as Protection Against Electric Shock	21
3.3.3 Protection Against Dangerous Movements.....	21
3.3.4 Protection Against Magnetic and Electromagnetic Fields During Operation and Mounting.....	23
3.3.5 Protection Against Contact With Hot Parts.....	23
3.3.6 Protection During Handling and Mounting.....	24
3.3.7 Battery Safety.....	24
3.3.8 Protection Against Pressurized Systems.....	24
3.4 Explanation of Signal Words and the Safety Alert Symbol.....	25
4 Technical Data.....	27
4.1 Explanation about Technical Data.....	27
4.1.1 Introduction.....	27
4.1.2 Operating Behavior.....	27
4.1.3 Explanation of Stated Sizes.....	29
4.2 General Technical Data.....	31
4.3 Technical Data - Frame Size MCL015.....	32
4.3.1 Data Sheet MCP015.....	32

Table of Contents

	Page
4.3.2	Data Sheet MCS015..... 32
4.3.3	Motor Characteristic Curve Frame Size 015..... 33
4.4	Technical Data - Frame Size MCL020..... 34
4.4.1	Data Sheet MCP020..... 34
4.4.2	Data Sheet MCS020..... 34
4.4.3	Motor Characteristic Curves Frame Size 020..... 35
4.5	Technical Data - Frame Size MCL030..... 38
4.5.1	Data Sheet MCP030..... 38
4.5.2	Data Sheet MCS030..... 38
4.5.3	Motor Characteristic Curves Frame Size 030..... 39
4.6	Technical Data - Frame Size MCL040..... 42
4.6.1	Data Sheet MCP040..... 42
4.6.2	Data Sheet MCS040..... 43
4.6.3	Motor Characteristic Curves Frame Size 040..... 43
4.7	Technical Data - Frame Size MCL070..... 48
4.7.1	Data Sheet MCP070..... 48
4.7.2	Data Sheet MCS070..... 49
4.7.3	Motor Characteristic Curves Frame Size 070..... 49
5	Specifications..... 55
5.1	Installation Tolerances..... 55
5.1.1	General Information..... 55
5.1.2	Frame Size MCL015..... 56
5.1.3	Frame Size MCL020 ... 070..... 57
5.1.4	Parallelism and Symmetry of Machine Parts..... 58
5.2	Dimension Sheets MCL015..... 60
5.3	Dimension Sheets MCL020..... 62
5.4	Dimension Sheets MCL030..... 64
5.5	Dimension Sheets MCL040..... 66
5.6	Dimension Sheets MCL070..... 68
6	Type Codes..... 71
6.1	Type Code Structure and Description 71
6.1.1	General Information..... 71
6.1.2	Type Code Primary Part MCP..... 71
	General Information..... 71
	Product..... 72
	Frame size..... 72
	Frame length..... 72
	Winding..... 72
	Cooling..... 72
	Design 72
	Hall unit 72
	Electrical Connection 72
	Other Design..... 72

Table of Contents

	Page
6.1.3 Type Code Secondary Part MCS.....	73
General Information.....	73
Product.....	73
Frame Size.....	73
Mechanical Design.....	73
Mechanical Protection.....	73
Segment Length.....	73
Other design.....	73
6.2 Type Code Frame Size 015.....	74
6.3 Type Code Frame Size 020.....	76
6.4 Type Code Frame Size 030.....	78
6.5 Type Code Frame Size 040.....	80
6.6 Type Code: Frame Size 070.....	82
7 Accessories and Options.....	85
7.1 Hall Unit	85
7.1.1 General Information.....	85
7.1.2 Hall Unit Functional Principle.....	85
7.1.3 Hall Unit Assembly/Disassembly.....	88
7.1.4 Ordering Designation Separate Hall Unit.....	89
7.2 Hall Unit Adapter Box SHL03.1.....	89
7.2.1 General Functional Principle.....	89
7.2.2 Order Designation Hall Unit Adapter Box	89
8 Electrical Connection.....	91
8.1 Power Connection	91
8.1.1 Connection Cable on Primary Part.....	91
8.1.2 Assembly Connection Cable on Primary Part.....	93
8.1.3 Connection Power	94
8.1.4 Installation of Power Connection.....	96
8.2 Sensors.....	97
8.2.1 Connection Temperature Sensor.....	97
8.2.2 Connection Hall Unit.....	98
8.2.3 Assembly Hall Unit Connection Cable.....	99
8.2.4 Connect Digital Hall Unit.....	100
8.2.5 Connect Analog Hall Unit.....	101
8.3 Length Measuring System	101
9 Application and Construction Instructions.....	103
9.1 Mode of Functioning.....	103
9.2 Motor Design.....	103
9.2.1 Design Primary Part	103
9.2.2 Design Secondary Part	104
9.2.3 Frame Size and Frame Length.....	105
9.3 Requirements on the Machine Design.....	106

Table of Contents

	Page
9.3.1 General Information.....	106
9.3.2 Mass Reduction.....	106
9.3.3 Mechanical Rigidity.....	106
9.3.4 Protection of the Motor Installation Space.....	107
9.3.5 Thermal Motor Connection.....	107
9.4 Arrangement of Motor Components.....	108
9.4.1 Single Arrangement.....	108
9.4.2 Several Motors per Axis.....	108
General Information.....	108
Parallel Arrangement	109
Parallel Arrangement: Double Comb Arrangement.....	110
Parallel Arrangement: Arrangement of Primary Parts in a Row.....	110
Gantry Arrangement	113
9.4.3 Arrangement of Secondary Parts.....	114
9.4.4 Vertical Axis	114
9.5 Feed Force at Reduced Covering Between Primary and Secondary Part.....	115
9.6 Thermal Behavior.....	116
9.7 Motor Temperature Monitoring.....	119
9.8 Setup Elevation and Ambient Conditions.....	120
9.9 Ambient Conditions.....	121
9.10 Degree of Protection.....	122
9.11 Acceptances and Approvals.....	122
9.11.1 CE-Sign.....	122
9.11.2 cURus-Sign.....	123
9.11.3 RoHS Conformity.....	123
9.12 Magnetic Fields	123
9.13 Noise Emission.....	124
9.14 Length Measuring System.....	124
9.14.1 General Information.....	124
9.14.2 Selection Criterias for Length Measuring System	124
General Information.....	124
Manufacturers of Length Measuring Systems.....	125
Measuring System Cables.....	125
9.15 Linear Guiding Systems.....	126
9.16 Manufacturers of Linear Guiding Systems.....	126
9.17 Braking Systems and Holding Devices.....	126
9.18 End Position Shock Absorber	127
9.19 Axis Cover Systems.....	127
9.20 Drive and Control of IndraDyn L motors.....	127
9.20.1 General Information.....	127
9.20.2 Drive Controllers.....	128
9.20.3 Control Systems.....	128
9.21 Deactivation upon EMERGENCY STOP and in the Event of a Malfunction	129
9.21.1 General Information.....	129
9.21.2 Deactivation by the Drive.....	129
9.21.3 Deactivation by a Master Control.....	130

Table of Contents

	Page
Deactivation by Control Functions.....	130
Drive initiated by the Control Shutdown.....	130
9.21.4 Deactivation via Mechanical Braking Device.....	130
9.21.5 Response to a Mains	130
9.21.6 Short-Circuit of DC bus.....	132
9.22 Position and Velocity Resolution.....	132
9.22.1 Drive Internal Position Resolution and Position Accuracy	132
9.22.2 Velocity Resolution.....	133
10 Motor-Controller-Combinations.....	135
10.1 General Information.....	135
10.2 Motor-Controller-Combinations with NYCe 4000.....	135
10.3 Motor-Controller-Combinations with IndraDrive Cs.....	136
11 Motor Dimensioning	137
11.1 General Procedure.....	137
11.2 Basic Formulae.....	138
11.2.1 General Movement Equations	138
11.2.2 Feed Forces.....	139
11.2.3 Average Velocity.....	142
11.2.4 Trapezoidal Velocity Profile.....	143
General Information.....	143
Acceleration, Initial Velocity $v_a = 0$	143
Acceleration, Initial Velocity $v_a \neq 0$	144
Constant Velocity.....	145
Braking, Final Velocity $v_e = 0$	145
Braking, Final Velocity $v_e \neq 0$	146
11.2.5 Triangle-shaped Velocity Profile.....	147
11.2.6 Sinusoidal Velocity Profile	148
11.3 Duty Cycle and Feed Force.....	151
11.3.1 General Information.....	151
11.3.2 Determining the Duty Cycle.....	151
11.4 Determining the Drive Power.....	152
11.4.1 General Information.....	152
11.4.2 Rated Output	152
11.4.3 Maximum Output.....	153
11.4.4 Power Loss	154
11.5 Efficiency.....	154
11.6 Thermal Connection of MCL Motors on the Machine.....	155
12 Handling, Transport and Storage.....	159
12.1 Identification of the Motor Components.....	159
12.1.1 Primary Part.....	159
12.1.2 Secondary Part.....	160
12.2 Delivery Status and Packaging.....	161

Table of Contents

	Page
12.2.1 Primary Parts.....	161
12.2.2 Secondary Parts.....	161
12.3 Checking the Motor Components.....	161
12.3.1 Factory Checks of the Motor Components	161
12.4 Transport and Storage.....	162
12.4.1 Notes about Transport.....	162
12.4.2 Notes about Storage.....	163
Storage Conditions.....	163
Storage Times.....	164
13 Assembly.....	165
13.1 Basic Precondition.....	165
13.2 Arrangement of Motor Components.....	165
13.3 Installation of Motor Components.....	166
13.4 Air-gap, Parallelism and Symmetry of the Motor Components.....	166
13.5 Fastening Secondary Part.....	167
13.6 Fastening the Primary Part.....	169
14 Commissioning, Operation and Maintenance.....	171
14.1 General Information for Startup of Ironless IndraDyn L Motors.....	171
14.2 General Requirements	171
14.2.1 General Information.....	171
14.2.2 Checking All Electrical and Mechanical Components.....	171
14.2.3 Tools.....	172
14.3 General Start-Up Procedure.....	172
14.4 Parameterization.....	173
14.4.1 General Information.....	173
14.4.2 Entering Motor Parameters.....	174
14.4.3 Motor Parameter at Parallel Arrangement.....	174
14.4.4 Entering Length Measuring System Parameter.....	174
14.4.5 Entering Drive Limitations and Application-related Parameters.....	175
14.5 Determining the Polarity of the Linear Scale.....	176
14.6 Commutation Adjustment.....	177
14.6.1 General Information.....	177
14.6.2 Sinusoidal Procedure.....	179
14.6.3 Hall Sensor Procedure.....	179
14.6.4 Measuring Procedure: Measuring the Reference between Primary and Secondary Part.....	181
14.7 Setting and Optimizing the Control Loop.....	183
14.7.1 General Procedure.....	183
14.7.2 Parameterization and Optimization of Gantry Axes.....	185
General Information.....	185
Parameter settings.....	185
14.7.3 Estimating the Moved Mass Using a Velocity Ramp	186
14.8 Maintenance and Check of Motor Components.....	188
14.8.1 General Information.....	188

Table of Contents

	Page
14.8.2 Check of Motor and Auxiliary Components	188
14.8.3 Electrical Check of Motor Components.....	188
14.9 Operation with Third-party Controllers.....	189
14.10 Environmental Protection and Disposal	189
14.10.1 Environmental Protection.....	189
14.10.2 Disposal.....	189
 15 Service and Support.....	 191
 Index.....	 193

1 Rexroth MCL - Product Presentation

1.1 Fields of Application Ironless Linear Motors

Continuously increasing demands on economic benefit of electric machines require new problem-solving approaches to fulfill the requirements on dynamic, accuracy and synchronization. Conventional NC-drives, consisting of a rotary electrical motor and mechanical transmission elements like gearboxes, belt transmissions or gear rack pinions, cannot fulfill these demands or, if only with high effort.

Ironless linear direct drive technique is an extension of the IndraDyn L product family with innovative product characteristics. Due to the wide application range of ironless linear motors, medium to midsize mass can be moved and positioned high-dynamically and high-precisely.

Based on the above-mentioned advantages, typical applications result for example in:

- Electronic, placement technology and manufacturing technology
- Solid state technology (e.g. wafer-inspection and bonding)
- Medicine technology (e.g. transport of pipettes)
- Solar technology (e.g. for laser structuring)
- Precision and ultra-precision machining

Even in other areas, for example, in machine tool industry, printing industry and especially in measuring technology, the advantages of this technology becomes important.

The ironless drive technology offers a lot of significant advantages in opposite to a ferrous motor, without accepting disturbing ancillary effects like cogging. For this reason, it is the optimum option for many applications.

Significant advantages of ironless linear motors are:

- Highest dynamic
- Excellent control quality and synchronization
- No magnetic attractive force, no detent torque
- High-precision positioning behavior
- Direct power transfer – no mechanical transmission elements like ball screw, toothed belt, gear rack, etc.
- High efficiency - low overhead
- Maintenance-free drive (no wearing parts at the motor)
- Simplified machine structure



For a comprehensive overview of all product families of Bosch Rexroth Electric Drives and Controls, please refer to the following link in our online product catalog: <http://www.boschrexroth.com/indradyn>.

1.2 Construction Ironless Linear Motors

Ironless linear motors MCL consist of the components primary and secondary part and have an optional Hall unit .

The ironless primary part bears the electrically active part of the linear motor with a winding, cast in plastics. The primary part carrier made of aluminum serves to assemble the primary part and for heat dissipation out of the primary part. A fastening of an optional Hall unit for position recording is prepared on the primary part. Additionally, a temperature sensor is placed in the winding. Hall unit and temperature sensor are available for all MCL, except for the smallest frame size.

The secondary part consists of an u-shaped iron yoke. The legs of the yoke bear permanent magnets and surround the primary part. The line is built with the secondary parts and can be realized as long as you want.

The motor designation depends on the ironless primary part. The designation is as follows:

- **MCL**: Motor Coreless Linear
- **MCP**: Motor Coreless Primary part
- **MCS**: Motor Coreless Secondary part




Fig. 1-1: Rexroth MCL example

1.3 Comparison Ironless with Ferreous Linear Motors

Ferreous linear motors use the iron, in which the winding is inserted to bundle the magnetic flow. Therewith, a very high force density is reached. Act up to a principle, very high magnetic attractive forces exist among the motor components (primary and secondary part). These lead to detent force and due to saturation effect to other parasitic effects, such as e.g. winding influences for ripple of the operation force.

No attractive forces exist among primary and secondary part towards ferreous linear motors. Detent forces due to a slotting, existing for ferreous linear motors are also not created. These aspects and the relatively small moved mass of the primary part allow a very high dynamic with high precision at the same time.

Additionally wearing mechanical components are not necessary due to direct installation into the machine. Due to not existing mechanical elements, a backlash free, with minimum or without hysteresis afflicted drive train, is available.

1.4 Power Spectrum of MCL Motors

New solutions due to practice-oriented combination of motor technique with digital intelligent drive controllers with ironless linear direct drive technique are available. The spectrum of ironless linear drive technique of Bosch Rexroth realized drives with feed forces of 10 N up to 3,300 N, acceleration up to 250 m/s² and maximum velocity up to 1,400 m/min. The following figure gives an overview over a power spectrum:




Fig. 1-2: Power spectrum Rexroth MCL

Rexroth MCL - Product Presentation

1.5 About this Documentation

1.5.1 Document Structure

This documentation includes safety-related guidelines, technical data and operating instructions. The following table provides an overview of the contents of this documentation.

Chapter	Title	Content			
1	Introduction	Product presentaion / Notes regarding reading			
2	Important Instructions on Use	Important Safety Instructions			
3	Safety				
4	Technical Data	Product descrip- tion	for planners and designers		
5	Specifications				
6	Type Codes				
7	Accessories			Practice	for operating and maintenance personnel
8	Connection Technique				
9	Operating condition and application instructions				
10	Motor-Control-Combination				
11	Motor dimensioning				
12	Handling, Transport and Storage				
13	Installation				
14	Startup, Operation and Mainte- nance				
15	Service & Support	Additional information			
16	Index				

Fig. 1-3: Chapter structure

1.5.2 Additional Documentation

To plan the drive-systems with MCL motors, it is possible that you need additional documentation referring the used devices. Rexroth provides the complete product documentation in PDF format in the following Bosch Rexroth media directory:

<http://www.boschrexroth.com/various/utilities/mediadirectory/index.jsp>

1.5.3 Standards

This documentation refers to German, European and international technical standards. Documents and sheets on standards are subject to copyright protection and may not be passed on to third parties by Rexroth. If need be, please contact the authorized sales outlets or, in Germany, directly:

BEUTH Verlag GmbH

Burggrafenstrasse 6

10787 Berlin, Germany

Tel. +49-(0)30-26 01-22 60

Fax +49-(0)30-26 01-12 60

Internet: <http://www.din.de/beuth>

Email: postmaster@beuth.de

1.5.4 Additional Components

Documentation for external systems which are connected to Bosch Rexroth components are not included in the scope of delivery and must be ordered directly from the corresponding manufacturers.

1.5.5 Your Feedback

Your experiences are an essential part of the process of improving both the product and the documentation.

Please send your remarks to:

Bosch Rexroth AG

Dept. DC-IA/EDM3 (fs, mb)

Buergermeister-Dr.-Nebel-Strasse 2

97816 Lohr am Main, Germany

Email: dokusupport@boschrexroth.de

2 Important Instructions on Use

2.1 Appropriate Use

2.1.1 Introduction

Bosch Rexroth products are designed and manufactured using the latest state-of-the-art-technology. Before they are delivered, they are inspected to ensure that they operate safely.

The products may only be used as intended. If they are not used as intended, situations may arise which result in personal injuries and property damage.



For damage caused by products not being used as intended, Bosch Rexroth gives no warranty, assumes no liability, and will not pay for any damages. Any risks resulting from the products not being used as intended are the sole responsibility of the user.

Before using Bosch Rexroth products, the following conditions must be fulfilled so as to ensure that the products are used as intended:

- Everyone who in any way whatsoever handles one of our products must read and understand the corresponding notes regarding safety and regarding the intended use.
- If the products are hardware, they must be kept in their original state, i.e., no constructional modifications may be made. Software products may not be decompiled, and their source codes may not be modified.
- Damaged or improperly working products may not be installed or put into operation.
- It must be ensured that the products are installed according to the regulations specified in the documentation.

2.1.2 Areas of Use and Application

Coreless linear motors MCL of the IndraDyn L series by Bosch Rexroth are determined to be used as linear servo drive motors.

There are drive controllers with different ratings, different DC bus voltages and different interfaces to allow application-specific use of the motors. To control and monitor the motors, additional sensors must be connected, e.g., length measuring systems.



- The motors may only be used with the accessories specified in this documentation. Components that are not explicitly mentioned may neither be attached nor connected. The same is true for cables and lines.
- The motors may only be operated in the explicitly mentioned configurations and combinations of components and with the software and firmware specified in the corresponding functional description.

Any connected drive controller must be programmed before startup in order to ensure that the motor executes the functions specifically to the particular application.

The motors may only be operated under the assembly, mounting and installation conditions, in the normal position, and under the environmental conditions (temperature, degree of protection, humidity, EMC, etc.) specified in this documentation.

Important Instructions on Use

2.2 Inappropriate Use

Any use of the motors outside of the fields of application mentioned above or under operating conditions and technical data other than those specified in this documentation is considered to be "inappropriate use".

MCL motors may not be used if . . .

- they are exposed to operating conditions which do not comply with the ambient conditions described above; for example, operation under water, under extreme variations in temperature or extreme maximum temperatures is not permitted;
- the intended fields of application have not been expressly released for the motors by Bosch Rexroth.



MCL motors are not suited to be operated directly on the power supply system.

3 Safety Instructions for Electric Drives and Controls

3.1 Definition of Terms

Component	An installation consists of several devices or systems interconnected for a defined purpose and on a defined site which, however, are not intended to be placed on the market as a single functional unit.
Electric Drive System	An electric drive system comprises all components from mains supply to motor shaft; this includes, for example, electric motor(s), motor encoder(s), supply units and drive controllers, as well as auxiliary and additional components, such as mains filter, mains choke and the corresponding lines and cables.
User	A user is a person installing, commissioning or using a product which has been placed on the market.
User Documentation	Application documentation comprises the entire documentation used to inform the user of the product about the use and safety-relevant features for configuring, integrating, installing, mounting, commissioning, operating, maintaining, repairing and decommissioning the product. The following terms are also used for this kind of documentation: User Guide, Operation Manual, Commissioning Manual, Instruction Manual, Project Planning Manual, Application Manual, etc.
Electrical Equipment	Electrical equipment encompasses all devices used to generate, convert, transmit, distribute or apply electrical energy, such as electric motors, transformers, switching devices, cables, lines, power-consuming devices, circuit board assemblies, plug-in units, control cabinets, etc.
Device	A device is a finished product with a defined function, intended for users and placed on the market as an individual piece of merchandise.
Manufacturer	The manufacturer is an individual or legal entity bearing responsibility for the design and manufacture of a product which is placed on the market in the individual's or legal entity's name. The manufacturer can use finished products, finished parts or finished elements, or contract out work to subcontractors. However, the manufacturer must always have overall control and possess the required authority to take responsibility for the product.
Component	A component is a combination of elements with a specified function, which are part of a piece of equipment, device or system. Components of the electric drive and control system are, for example, supply units, drive controllers, mains choke, mains filter, motors, cables, etc.
Machine	A machine is the entirety of interconnected parts or units at least one of which is movable. Thus, a machine consists of the appropriate machine drive elements, as well as control and power circuits, which have been assembled for a specific application. A machine is, for example, intended for processing, treatment, movement or packaging of a material. The term "machine" also covers a combination of machines which are arranged and controlled in such a way that they function as a unified whole.
Product	Examples of a product: Device, component, part, system, software, firmware, among other things.
Project Planning Manual	A project planning manual is part of the application documentation used to support the sizing and planning of systems, machines or installations.
Qualified Personnel	In terms of this application documentation, qualified persons are those persons who are familiar with the installation, mounting, commissioning and operation of the components of the electric drive and control system, as well as with the hazards this implies, and who possess the qualifications their work

Safety Instructions for Electric Drives and Controls

requires. To comply with these qualifications, it is necessary, among other things,

- 1) to be trained, instructed or authorized to switch electric circuits and devices safely on and off, to ground them and to mark them
- 2) to be trained or instructed to maintain and use adequate safety equipment
- 3) to attend a course of instruction in first aid

Control System A control system comprises several interconnected control components placed on the market as a single functional unit.

3.2 General Information

3.2.1 Using the Safety Instructions and Passing Them on to Others

Do not attempt to install and operate the components of the electric drive and control system without first reading all documentation provided with the product. Read and understand these safety instructions and all user documentation prior to working with these components. If you do not have the user documentation for the components, contact your responsible Bosch Rexroth sales partner. Ask for these documents to be sent immediately to the person or persons responsible for the safe operation of the components.

If the component is resold, rented and/or passed on to others in any other form, these safety instructions must be delivered with the component in the official language of the user's country.

Improper use of these components, failure to follow the safety instructions in this document or tampering with the product, including disabling of safety devices, could result in property damage, injury, electric shock or even death.

3.2.2 Requirements for Safe Use

Read the following instructions before initial commissioning of the components of the electric drive and control system in order to eliminate the risk of injury and/or property damage. You must follow these safety instructions.

- Bosch Rexroth is not liable for damages resulting from failure to observe the safety instructions.
- Read the operating, maintenance and safety instructions in your language before commissioning. If you find that you cannot completely understand the application documentation in the available language, please ask your supplier to clarify.
- Proper and correct transport, storage, mounting and installation, as well as care in operation and maintenance, are prerequisites for optimal and safe operation of the component.
- Only qualified persons may work with components of the electric drive and control system or within its proximity.
- Only use accessories and spare parts approved by Bosch Rexroth.
- Follow the safety regulations and requirements of the country in which the components of the electric drive and control system are operated.
- Only use the components of the electric drive and control system in the manner that is defined as appropriate. See chapter "Appropriate Use".
- The ambient and operating conditions given in the available application documentation must be observed.
- Applications for functional safety are only allowed if clearly and explicitly specified in the application documentation "Integrated Safety Technolo-

Safety Instructions for Electric Drives and Controls

gy". If this is not the case, they are excluded. Functional safety is a safety concept in which measures of risk reduction for personal safety depend on electrical, electronic or programmable control systems.

- The information given in the application documentation with regard to the use of the delivered components contains only examples of applications and suggestions.

The machine and installation manufacturers must

- make sure that the delivered components are suited for their individual application and check the information given in this application documentation with regard to the use of the components,
- make sure that their individual application complies with the applicable safety regulations and standards and carry out the required measures, modifications and complements.
- Commissioning of the delivered components is only allowed once it is sure that the machine or installation in which the components are installed complies with the national regulations, safety specifications and standards of the application.
- Operation is only allowed if the national EMC regulations for the application are met.
- The instructions for installation in accordance with EMC requirements can be found in the section on EMC in the respective application documentation.

The machine or installation manufacturer is responsible for compliance with the limit values as prescribed in the national regulations.

- The technical data, connection and installation conditions of the components are specified in the respective application documentations and must be followed at all times.

National regulations which the user must take into account

- European countries: In accordance with European EN standards
- United States of America (USA):
 - National Electrical Code (NEC)
 - National Electrical Manufacturers Association (NEMA), as well as local engineering regulations
 - Regulations of the National Fire Protection Association (NFPA)
- Canada: Canadian Standards Association (CSA)
- Other countries:
 - International Organization for Standardization (ISO)
 - International Electrotechnical Commission (IEC)

3.2.3 Hazards by Improper Use

- High electrical voltage and high working current! Danger to life or serious injury by electric shock!
- High electrical voltage by incorrect connection! Danger to life or injury by electric shock!
- Dangerous movements! Danger to life, serious injury or property damage by unintended motor movements!
- Health hazard for persons with heart pacemakers, metal implants and hearing aids in proximity to electric drive systems!

Safety Instructions for Electric Drives and Controls

- Risk of burns by hot housing surfaces!
- Risk of injury by improper handling! Injury by crushing, shearing, cutting, hitting!
- Risk of injury by improper handling of batteries!
- Risk of injury by improper handling of pressurized lines!

3.3 Requirements for Safe Use

3.3.1 Protection Against Contact with Electrical Parts and Housings



This section concerns components of the electric drive and control system with voltages of **more than 50 volts**.

Contact with parts conducting voltages above 50 volts can cause personal danger and electric shock. When operating components of the electric drive and control system, it is unavoidable that some parts of these components conduct dangerous voltage.

High electrical voltage! Danger to life, risk of injury by electric shock or serious injury!

- Only qualified persons are allowed to operate, maintain and/or repair the components of the electric drive and control system.
- Follow the general installation and safety regulations when working on power installations.
- Before switching on, the equipment grounding conductor must have been permanently connected to all electric components in accordance with the connection diagram.
- Even for brief measurements or tests, operation is only allowed if the equipment grounding conductor has been permanently connected to the points of the components provided for this purpose.
- Before accessing electrical parts with voltage potentials higher than 50 V, you must disconnect electric components from the mains or from the power supply unit. Secure the electric component from reconnection.
- With electric components, observe the following aspects:
Always wait **30 minutes** after switching off power to allow live capacitors to discharge before accessing an electric component. Measure the electrical voltage of live parts before beginning to work to make sure that the equipment is safe to touch.
- Install the covers and guards provided for this purpose before switching on.
- Never touch electrical connection points of the components while power is turned on.
- Do not remove or plug in connectors when the component has been powered.
- Under specific conditions, electric drive systems can be operated at mains protected by residual-current-operated circuit-breakers sensitive to universal current (RCDs/RCMs).

Safety Instructions for Electric Drives and Controls

- Secure built-in devices from penetrating foreign objects and water, as well as from direct contact, by providing an external housing, for example a control cabinet.

High housing voltage and high leakage current! Danger to life, risk of injury by electric shock!

- Before switching on and before commissioning, ground or connect the components of the electric drive and control system to the equipment grounding conductor at the grounding points.
- Connect the equipment grounding conductor of the components of the electric drive and control system permanently to the main power supply at all times. The leakage current is greater than 3.5 mA.
- Establish an equipment grounding connection with a copper wire of a cross section of at least 10 mm² (8 AWG) or additionally run a second equipment grounding conductor of the same cross section as the original equipment grounding conductor.

3.3.2 Protective Extra-Low Voltage as Protection Against Electric Shock

Protective extra-low voltage is used to allow connecting devices with basic insulation to extra-low voltage circuits.

On components of an electric drive and control system provided by Bosch Rexroth, all connections and terminals with voltages between 5 and 50 volts are PELV ("Protective Extra-Low Voltage") systems. It is allowed to connect devices equipped with basic insulation (such as programming devices, PCs, notebooks, display units) to these connections.

Danger to life, risk of injury by electric shock! High electrical voltage by incorrect connection!

If extra-low voltage circuits of devices containing voltages and circuits of more than 50 volts (e.g., the mains connection) are connected to Bosch Rexroth products, the connected extra-low voltage circuits must comply with the requirements for PELV ("Protective Extra-Low Voltage").

3.3.3 Protection Against Dangerous Movements

Dangerous movements can be caused by faulty control of connected motors. Some common examples are:

- Improper or wrong wiring or cable connection
- Operator errors
- Wrong input of parameters before commissioning
- Malfunction of sensors and encoders
- Defective components
- Software or firmware errors

These errors can occur immediately after equipment is switched on or even after an unspecified time of trouble-free operation.

The monitoring functions in the components of the electric drive and control system will normally be sufficient to avoid malfunction in the connected drives. Regarding personal safety, especially the danger of injury and/or property damage, this alone cannot be relied upon to ensure complete safety.

Safety Instructions for Electric Drives and Controls

Until the integrated monitoring functions become effective, it must be assumed in any case that faulty drive movements will occur. The extent of faulty drive movements depends upon the type of control and the state of operation.

Dangerous movements! Danger to life, risk of injury, serious injury or property damage!

A **risk assessment** must be prepared for the installation or machine, with its specific conditions, in which the components of the electric drive and control system are installed.

As a result of the risk assessment, the user must provide for monitoring functions and higher-level measures on the installation side for personal safety. The safety regulations applicable to the installation or machine must be taken into consideration. Unintended machine movements or other malfunctions are possible if safety devices are disabled, bypassed or not activated.

To avoid accidents, injury and/or property damage:

- Keep free and clear of the machine's range of motion and moving machine parts. Prevent personnel from accidentally entering the machine's range of motion by using, for example:
 - Safety fences
 - Safety guards
 - Protective coverings
 - Light barriers
- Make sure the safety fences and protective coverings are strong enough to resist maximum possible kinetic energy.
- Mount emergency stopping switches in the immediate reach of the operator. Before commissioning, verify that the emergency stopping equipment works. Do not operate the machine if the emergency stopping switch is not working.
- Prevent unintended start-up. Isolate the drive power connection by means of OFF switches/OFF buttons or use a safe starting lockout.
- Make sure that the drives are brought to safe standstill before accessing or entering the danger zone.
- Additionally secure vertical axes against falling or dropping after switching off the motor power by, for example,
 - mechanically securing the vertical axes,
 - adding an external braking/arrester/clamping mechanism or
 - ensuring sufficient counterbalancing of the vertical axes.
- The standard equipment **motor holding brake** or an external holding brake controlled by the drive controller is **not sufficient to guarantee personal safety!**
- Disconnect electrical power to the components of the electric drive and control system using the master switch and secure them from reconnection ("lock out") for:
 - Maintenance and repair work
 - Cleaning of equipment
 - Long periods of discontinued equipment use
- Prevent the operation of high-frequency, remote control and radio equipment near components of the electric drive and control system and their

Safety Instructions for Electric Drives and Controls

supply leads. If the use of these devices cannot be avoided, check the machine or installation, at initial commissioning of the electric drive and control system, for possible malfunctions when operating such high-frequency, remote control and radio equipment in its possible positions of normal use. It might possibly be necessary to perform a special electro-magnetic compatibility (EMC) test.

3.3.4 Protection Against Magnetic and Electromagnetic Fields During Operation and Mounting

Magnetic and electromagnetic fields generated by current-carrying conductors or permanent magnets of electric motors represent a serious danger to persons with heart pacemakers, metal implants and hearing aids.

Health hazard for persons with heart pacemakers, metal implants and hearing aids in proximity to electric components!

- Persons with heart pacemakers and metal implants are not allowed to enter the following areas:
 - Areas in which components of the electric drive and control systems are mounted, commissioned and operated.
 - Areas in which parts of motors with permanent magnets are stored, repaired or mounted.
- If it is necessary for somebody with a heart pacemaker to enter such an area, a doctor must be consulted prior to doing so. The noise immunity of implanted heart pacemakers differs so greatly that no general rules can be given.
- Those with metal implants or metal pieces, as well as with hearing aids, must consult a doctor before they enter the areas described above.

3.3.5 Protection Against Contact With Hot Parts

Hot surfaces of components of the electric drive and control system. Risk of burns!

- Do not touch hot surfaces of, for example, braking resistors, heat sinks, supply units and drive controllers, motors, windings and laminated cores!
- According to the operating conditions, temperatures of the surfaces can be **higher than 60 °C (140 °F)** during or after operation.
- Before touching motors after having switched them off, let them cool down for a sufficient period of time. Cooling down can require **up to 140 minutes!** The time required for cooling down is approximately five times the thermal time constant specified in the technical data.
- After switching chokes, supply units and drive controllers off, wait **15 minutes** to allow them to cool down before touching them.
- Wear safety gloves or do not work at hot surfaces.
- For certain applications, and in accordance with the respective safety regulations, the manufacturer of the machine or installation must take measures to avoid injuries caused by burns in the final application. These measures can be, for example: Warnings at the machine or installation, guards (shieldings or barriers) or safety instructions in the application documentation.

3.3.6 Protection During Handling and Mounting

Risk of injury by improper handling! Injury by crushing, shearing, cutting, hitting!

- Observe the relevant statutory regulations of accident prevention.
- Use suitable equipment for mounting and transport.
- Avoid jamming and crushing by appropriate measures.
- Always use suitable tools. Use special tools if specified.
- Use lifting equipment and tools in the correct manner.
- Use suitable protective equipment (hard hat, safety goggles, safety shoes, safety gloves, for example).
- Do not stand under hanging loads.
- Immediately clean up any spilled liquids from the floor due to the risk of falling!

3.3.7 Battery Safety

Batteries consist of active chemicals in a solid housing. Therefore, improper handling can cause injury or property damage.

Risk of injury by improper handling!

- Do not attempt to reactivate low batteries by heating or other methods (risk of explosion and cauterization).
- Do not attempt to recharge the batteries as this may cause leakage or explosion.
- Do not throw batteries into open flames.
- Do not dismantle batteries.
- When replacing the battery/batteries, do not damage the electrical parts installed in the devices.
- Only use the battery types specified for the product.



Environmental protection and disposal! The batteries contained in the product are considered dangerous goods during land, air, and sea transport (risk of explosion) in the sense of the legal regulations. Dispose of used batteries separately from other waste. Observe the national regulations of your country.

3.3.8 Protection Against Pressurized Systems

According to the information given in the Project Planning Manuals, motors and components cooled with liquids and compressed air can be partially supplied with externally fed, pressurized media, such as compressed air, hydraulics oil, cooling liquids and cooling lubricants. Improper handling of the connected supply systems, supply lines or connections can cause injuries or property damage.

Risk of injury by improper handling of pressurized lines!

- Do not attempt to disconnect, open or cut pressurized lines (risk of explosion).
- Observe the respective manufacturer's operating instructions.
- Before dismounting lines, relieve pressure and empty medium.

Safety Instructions for Electric Drives and Controls

- Use suitable protective equipment (safety goggles, safety shoes, safety gloves, for example).
- Immediately clean up any spilled liquids from the floor due to the risk of falling!



Environmental protection and disposal! The agents (e.g., fluids) used to operate the product might not be environmentally friendly. Dispose of agents harmful to the environment separately from other waste. Observe the national regulations of your country.

3.4 Explanation of Signal Words and the Safety Alert Symbol

The Safety Instructions in the available application documentation contain specific signal words (DANGER, WARNING, CAUTION or NOTICE) and, where required, a safety alert symbol (in accordance with ANSI Z535.6-2006).

The signal word is meant to draw the reader's attention to the safety instruction and identifies the hazard severity.

The safety alert symbol (a triangle with an exclamation point), which precedes the signal words DANGER, WARNING and CAUTION, is used to alert the reader to personal injury hazards.

DANGER

In case of non-compliance with this safety instruction, death or serious injury **will** occur.

WARNING

In case of non-compliance with this safety instruction, death or serious injury **could** occur.

CAUTION

In case of non-compliance with this safety instruction, minor or moderate injury **could** occur.

NOTICE

In case of non-compliance with this safety instruction, property damage **could** occur.

4 Technical Data

4.1 Explanation about Technical Data

4.1.1 Introduction

All relevant technical motor data as well as the functional principle of this motors are given on the following pages in terms of tables and characteristic curves. The following interdependence was noticed:

- Size and length of the primary part
- Winding mode primary part
- Available power supply or DC bus voltage



All given data and characteristic curves relate on the following conditions – unless otherwise noted:

- Mounting method B according to [fig. 11-28 " Motor force dependend from the thermal connection" on page 156](#)
- Keeping installation tolerances according to [chapter 5.1 "Installation Tolerances" on page 55](#)
- Keeping environmental conditions according to [chapter 9.8 "Setup Elevation and Ambient Conditions" on page 120](#)
- Motor winding temperature $\leq 110\text{ }^{\circ}\text{C}$

Specified values in the data sheets are effective values acc. to DIN EN 60034-1. The reference value is the maximum DC bus voltage of 420 V_{DC} at MCP020 ... 070 or 48 V_{DC} for MCP015.

4.1.2 Operating Behavior

The characteristic force over speed is given as a limiting curve. The path and the basic data of this characteristic curves are defined by the level of the DC bus voltage and the appropriate motor-specific data as inductivity, resistor and the force constant. By varying the DC bus voltage (different control devices, supply modules and connected loads) and different motor windings result in different characteristic curves.

Technical Data




Fig.4-1: Example motor characteristic curve



The specified characteristic curves can linearly be converted according to the existing voltages if the connection voltages or DC bus voltages are different.

The maximum force F_{\max} is available up to a velocity $v_{F_{\max}}$. When the velocity rises, the available DC bus voltage is reduced by the velocity-dependent back electromotive force of the motor and the voltage drop on resistor and inductivity. This leads to a reduction of the maximum feed force at rising velocity.

The force F_{S6} is the maximum possible force at operation mode S6 acc. to DIN EN 60034-1. It is available up to velocity v_{FS6} . This characteristic curve is application-dependent and can be calculated via the duty cycle (ED). See also ["Relative duty cycle" on page 30](#).

The continuous rated force F_N is available up to the nominal velocity v_N .

The maximum velocity v_{\max} is the maximum reachable velocity of the motor at U_{DC} up to approximately $F_N = 0$ N.




The reachable motor data are significantly depended from the thermal coupling of the motor to the machine (heat loss) and from the drive controller used. The reference value for the details in the technical data and the displayed motor characteristic curves is an uncontrolled DC bus voltage of 300 V_{DC} for MCP020 to MCP070 or 48 V_{DC} for MCP015.

Additional notes about thermal coupling can be found under [chapter 11.6 "Thermal Connection of MCL Motors on the Machine" on page 155](#).

4.1.3 Explanation of Stated Sizes

Maximum force F_{\max}	Maximum feed force of the motor at maximum current I_{\max} . Einheit [N].
Continuous nominal force F_N	Available continuous nominal force of the motor up to v_N for nominal current I_N . Unit [N].
Maximum current I_{\max}	Maximum current of the motor at F_{\max} . Unit [A].
Rated current I_N	Rated current of the motor at continuous nominal force F_N . Unit [A].
Reference voltage DC bus voltage U_{DC}	Reference voltage DC bus voltage to determine the winding velocity. Unit [V].
Maximum allowed DC bus voltage U_{DC_max}	Maximum allowed DC bus voltage Unit [V].
Maximum velocity v_{Fmax}	Maximum velocity at maximum force F_{\max} . Velocity up to the maximum feed-rate of the motor is available. Unit [m/min].
Nominal velocity v_N	Velocity up to the continuous nominal force F_N of the motor is available. Unit [m/min].
Force constant K_{FN}	Relation of force increase to rise the force-forming current. Due to the principle of an ironless primary part, no saturation effects occur. The constant is not current-dependend. Unit [N/A].
Voltage constant K_{EMK} at 20 °C	Induced motor voltage dependend on the travel velocity regarding the velocity 1m/s. unit [Vs/m].
Winding resistance R_{12} at 20 °C	Measured winding resistance between two strands. Unit [Ω].
Winding inductivity L_{12}	Measured winding inductivity between strands 1 and 2. The specifications are typical values, determined with a measuring voltage of 1 mA at a measuring frequency of 1 kHz. Unit [mH].
Winding inductivity $L_{23/31}$	Measured winding inductivity between two strands (strand 2/3 or 3/1). The specified measuring values are different to L_{12} due to boundary effects. The specifications are typical values, determined with a measuring voltage of 1 mA at a measuring frequency of 1 kHz. Unit [mH].
Rated power loss P_{VN}	Power loss in operation mode S1 (continuous operation) at nominal velocity v_N . Unit [W].
Pole width t_p	Distance from pole center to pole center of the magnets on the secondary part. Unit [mm].
Thermal time constant T_{th}	Duration of temperature rise up to 63% of final temperature of the winding at natural convection and load with continuous nominal force in S1 operation.



① Chronological course of the winding temperature
 Θ_{\max} Max. winding temperature
 T_{th} Thermal time constant
 Fig. 4-2: Thermal time constant

Technical Data

Mass primary part m_P	Mass of primary part. Unit [kg].
Mass secondary part m_S	Mass secondary part. Unit [kg].
Relative duty cycle	Duty ratio $ED_{F_{S6}}$ in %, referring to the specified maximum and continuous nominal force. The relative duty cycle $ED_{F_{S6}}$ is determined via:


$$ED_{F_{S6}} \approx \left(\frac{F_N}{F_{S6}} \right)^2 \cdot 100\%$$

F_{dN}
 F_{S6}
Fig. 4-3:

Continuous nominal force of the motor in N
Force F_{S6} in N
Calculation of the potential duty cycle, relating on F_{S6}

A force F_{S6} higher than the continuous nominal force of the motor is only then available, if the continuous voltage of the drive-controller is higher than the continuous nominal voltage of the motor.

Allowed ambient temperature T_{UM} in operation	Permissible ambient temperature. Unit [°C].
Degree of protection	Protection class according to DIN EN 60034-5.
Temperature class	Temperature class according to DIN EN 60034-1.
E-file number	Test number of UL (=Underwriters Laboratories Inc.) certified products.
RoHS conformity	RoHS conformity according to EC guidelines 2002/95/EG



The PWM-Frequency of the drive controller affects the resulting motor data. All data in this documentation refer to a PWM-Frequency of 4 kHz.

4.2 General Technical Data

For the sake of clarity, the following table contains data which is applicable to all motor frame sizes. In this context, however, the comments on the individual items in Chapter Application Notes must be observed.

Designation	Symbol	Unit	MCPxxx	MCSxxx
Maximum allowed DC bus voltage MCP015	U _{DC} , max	V	72	/
Maximum allowed DC bus voltage MCP020 ... 070 (Bleeder-threshold)			420	
Ambient temperature in operation (see also chapter 9.8 "Setup Elevation and Ambient Conditions" on page 120)	T _{amb}	°C	0 ... +40	
Allowed transport temperature (see also chapter 12.4.1 "Notes about Transport" on page 162)	T _T	°C	-20 ... +80	
Allowed storage temperature (see also chapter 12.4.2 "Notes about Storage" on page 163)	T _L	°C	-20 ... +60	
Temperature class according to DIN EN 60034-1	-	-	130 (B)	/
Warning temperature (winding) (see also chapter 9.7 "Motor Temperature Monitoring" on page 119)	T _{warn}	°C	110	/
Shutdown temperature (winding) (see also chapter 9.7 "Motor Temperature Monitoring" on page 119)	T _{shut}	°C	130	/
Degree of protection MCP and MCS according to DIN EN 60034-5	-	-	IP00	
E-file number	-	-	in preparation	
RoHS conformity according to EC guidelines 2002/95/EG	-	-	RoHS conform	
Latest amendment: 2012-03-23				

Fig.4-4: General Technical Data

Technical Data

4.3 Technical Data - Frame Size MCL015

4.3.1 Data Sheet MCP015

Parameter	Symbol	Unit	MCP015	
Frame Length			A	B
Winding			L040	L040
Maximum force	F_{\max}	N	24.0	48.0
Continuous nominal force	F_N	N	6.0	12.0
Maximum current	$I_{\max(\text{rms})}$	A	5.2	9.6
Rated current	I_N	A	1.3	2.4
Reference voltage DC bus voltage	U_{DC}	V	48	
Maximum velocity at F_{\max}	$v_{F\max}$	m/min	90	170
Nominal velocity	v_N	m/min	600	560
Force constant	K_{FN}	N/A	4.6	5.0
Voltage constant	K_{EMK}	Vs/m	2.7	2.9
Winding resistance at 20 °C	R_{12}	Ohm	5.2	2.65
Winding inductivity	L_{12}	mH	0.5	0.24
Winding inductivity	$L_{23,31}$	mH	0.5	0.24
Rated power loss	P_{VN}	W	17.5	30.4
Pole width	t_p	mm	8.25	
Thermal time constant	T_{th}	min	1.0	
Primary part mass	m_P	kg	0.04	0.06
Latest amendment: 2012-06-15				

Fig.4-5: MCP015 - Technical data

4.3.2 Data Sheet MCS015

Designation	Symbol	Unit	MCS015-__-0066	MCS015-__-0099
Secondary part mass	m_S	kg	0.2	0.3
Latest amendment: 2012-06-21				

Fig.4-6: MCS015 - Technical data

4.3.3 Motor Characteristic Curve Frame Size 015




Fig. 4-7: Motor characteristic curve MCP015A-L040 bei 48 V_{DC}




Fig. 4-8: Motor characteristic curve MCP015B-L040 bei 48 V_{DC}

Technical Data

4.4 Technical Data - Frame Size MCL020

4.4.1 Data Sheet MCP020

Parameter	Symbol	Unit	MCP020					
Frame Length			B		C		D	
Winding			V180	V720	V180	V720	V180	V720
Maximum force	F _{max}	N	104.0		160.0		224.0	
Continuous nominal force	F _N	N	26.0		40.0		56.0	
Maximum current	I _{max(rms)}	A	3.2	5.6	5.2	8.8	7.6	14.0
Rated current	I _N	A	0.8	1.4	1.3	2.2	1.9	3.5
Reference voltage DC bus voltage	U _{DC}	V	300					
Maximum velocity at F _{max}	v _{Fmax}	m/min	200	690	150	680	190	760
Nominal velocity	v _N	m/min	560	1,100	590	1,110	620	1,220
Force constant	K _{FN}	N/A	32.5	18.6	30.8	18.2	29.5	16.0
Voltage constant	K _{EMK}	Vs/m	18.8	10.7	17.8	10.5	17.0	9.2
Winding resistance at 20 °C	R ₁₂	Ohm	40.5	13.3	28	8.8	18	5.5
Winding inductivity	L ₁₂	mH	4.4	1.5	2.9	0.9	1.9	0.6
Winding inductivity	L _{23,31}	mH	6.6	2.2	4.3	1.3	2.7	0.9
Rated power loss	P _{VN}	W	51.8	52.2	95.2	85.1	130.5	135.5
Pole width	t _p	mm	15.00					
Thermal time constant	T _{th}	min	1.7		1.9		2.1	
Primary part mass	m _p	kg	0.18		0.28		0.38	
Latest amendment: 2012-06-15								

Fig.4-9: MCP020 - Technical data

4.4.2 Data Sheet MCS020

Designation	Symbol	Unit	MCS020-__-0120	MCS020-__-0180	MCS020-__-0300
Secondary part mass	m_S	kg	0.4	0.7	1.1
Latest amendment: 2012-03-29					

Fig.4-10: MCS020 - Technical data

4.4.3 Motor Characteristic Curves Frame Size 020




Fig.4-11: Motor characteristic curve MCP020B-V180 bei 300 V_{DC}






Fig.4-12: Motor characteristic curve MCP020B-V720 bei 300 V_{DC}

Technical Data

Fig.4-13: Motor characteristic curve MCP020C-V180 bei 300 V_{DC}Fig.4-14: Motor characteristic curve MCP020C-V720 bei 300 V_{DC}




Fig.4-15: Motor characteristic curve MCP020D-V180 bei 300 V_{DC}




Fig.4-16: Motor characteristic curve MCP020D-V720 bei 300 V_{DC}

Technical Data

4.5 Technical Data - Frame Size MCL030

4.5.1 Data Sheet MCP030

Parameter	Symbol	Unit	MCP030					
Frame Length			B		C		D	
Winding			V180	V390	V180	V390	V180	V390
Maximum force	F _{max}	N	192.0		296.0		420.0	
Continuous nominal force	F _N	N	48.0		74.0		105.0	
Maximum current	I _{max(rms)}	A	5.2	6.4	7.2	9.6	10.0	14.0
Rated current	I _N	A	1.3	1.6	1.8	2.4	2.5	3.5
Reference voltage DC bus voltage	U _{DC}	V	300					
Maximum velocity at F _{max}	v _{Fmax}	m/min	180	400	170	370	180	380
Nominal velocity	v _N	m/min	510	680	460	630	440	660
Force constant	K _{FN}	N/A	36.9	30.0	41.1	30.8	42.0	30.0
Voltage constant	K _{EMK}	Vs/m	21.3	17.3	23.7	17.8	24.2	17.3
Winding resistance at 20 °C	R ₁₂	Ohm	27	14.6	20	10.6	14	7.9
Winding inductivity	L ₁₂	mH	10.1	5.6	7.5	4.19	5.56	2.9
Winding inductivity	L _{23,31}	mH	16.2	9.1	11.6	6.16	8.17	4.7
Rated power loss	P _{VN}	W	91.8	74.9	129.4	121.9	176.0	192.1
Pole width	t _p	mm	30.00					
Thermal time constant	T _{th}	min	2.2		2.4		2.6	
Primary part mass	m _p	kg	0.34		0.52		0.70	
Latest amendment: 2012-06-26								

Fig.4-17: MCP030 - Technical data

4.5.2 Data Sheet MCS030

Designation	Symbol	Unit	MCS030-__-0120	MCS030-__-0180	MCS030-__-0300
Secondary part mass	m_S	kg	0.7	1.0	1.6
Latest amendment: 2012-03-29					

Fig.4-18: MCS030 - Technical data

4.5.3 Motor Characteristic Curves Frame Size 030




Fig.4-19: Motor characteristic curve MCP030B-V180 bei 300 V_{DC}






Fig.4-20: Motor characteristic curve MCP030B-V390 bei 300 V_{DC}

Technical Data

Fig.4-21: Motor characteristic curve MCP030C-V180 bei 300 V_{DC}Fig.4-22: Motor characteristic curve MCP030C-V390 bei 300 V_{DC}




Fig. 4-23: Motor characteristic curve MCP030D-V180 bei 300 V_{DC}




Fig. 4-24: Motor characteristic curve MCP030D-V390 bei 300 V_{DC}

Technical Data

4.6 Technical Data - Frame Size MCL040

4.6.1 Data Sheet MCP040

Parameter	Symbol	Unit	MCP040			
Frame Length			B		C	
Winding			V070	V300	V070	V300
Maximum force	F_{\max}	N	292.0		432.0	
Continuous nominal force	F_N	N	73.0		108.0	
Maximum current	$I_{\max(\text{rms})}$	A	4.8	7.6	6.8	11.6
Rated current	I_N	A	1.2	1.9	1.7	2.9
Reference voltage DC bus voltage	U_{DC}	V	300			
Maximum velocity at F_{\max}	$v_{F\max}$	m/min	80	290	60	310
Nominal velocity	v_N	m/min	290	530	290	530
Force constant	K_{FN}	N/A	60.8	38.4	63.5	37.2
Voltage constant	K_{EMK}	Vs/m	35.1	22.2	36.7	21.5
Winding resistance at 20 °C	R_{12}	Ohm	30	11.4	22	7.4
Winding inductivity	L_{12}	mH	14.6	5.6	10.8	3.7
Winding inductivity	$L_{23,31}$	mH	22.6	8.9	15.9	5.6
Rated power loss	P_{VN}	W	86.9	82.4	127.6	124.3
Pole width	t_p	mm	30.00			
Thermal time constant	T_{th}	min	2.3		2.4	
Primary part mass	m_P	kg	0.56		0.81	
Latest amendment: 2012-06-15						

Fig.4-25: MCP040B/C - Technical data

Parameter	Symbol	Unit	MCP040			
Frame Length			E		G	
Winding			V070	V300	V070	V300
Maximum force	F _{max}	N	732.0		1,032.0	
Continuous nominal force	F _N	N	183.0		258.0	
Maximum current	I _{max(rms)}	A	11.6	18.8	15.6	26.4
Rated current	I _N	A	2.9	4.7	3.9	6.6
Reference voltage DC bus voltage	U _{DC}	V	300			
Maximum velocity at F _{max}	v _{Fmax}	m/min	60	260	50	290
Nominal velocity	v _N	m/min	280	510	260	500
Latest amendment: 2012-06-15						

Technical Data

Parameter	Symbol	Unit	MCP040			
Frame Length			E		G	
Winding			V070	V300	V070	V300
Force constant	K _{FN}	N/A	63.1	38.9	66.2	39.1
Voltage constant	K _{EMK}	Vs/m	36.4	22.5	38.2	22.6
Winding resistance at 20 °C	R ₁₂	Ohm	12.7	5	9.7	3.3
Winding inductivity	L ₁₂	mH	6.4	2.4	4.8	1.6
Winding inductivity	L _{23,31}	mH	9.5	3.5	7	2.4
Rated power loss	P _{VN}	W	213.3	221.3	294.7	287.1
Pole width	t _p	mm	30.00			
Thermal time constant	T _{th}	min	2.6		2.8	
Primary part mass	m _P	kg	1.26		1.71	
Latest amendment: 2012-06-15						

Fig.4-26: MCP040E/G - Technical data

4.6.2 Data Sheet MCS040

Designation	Symbol	Unit	MCS040-__-0120	MCS040-__-0180	MCS040-__-0300
Secondary part mass	m_s	kg	1.3	1.9	3.2
Latest amendment: 2012-03-29					

Fig.4-27: MCS040 - Technical data

4.6.3 Motor Characteristic Curves Frame Size 040






Fig.4-28: Motor characteristic curve MCP040B-V070 bei 300 V_{DC}

Technical Data

Fig.4-29: Motor characteristic curve MCP040B-V300 bei 300 V_{DC}Fig.4-30: Motor characteristic curve MCP040C-V070 bei 300 V_{DC}




Fig. 4-31: Motor characteristic curve MCP040C-V300 bei 300 V_{DC}






Fig. 4-32: Motor characteristic curve MCP040E-V070 bei 300 V_{DC}

Technical Data

Fig. 4-33: Motor characteristic curve MCP040E-V300 bei 300 V_{DC}Fig. 4-34: Motor characteristic curve MCP040G-V070 bei 300 V_{DC}

Technical Data




Fig. 4-35: Motor characteristic curve MCP040G-V300 bei 300 V_{DC}

Parameter	Symbol	Unit	MCP070			
Frame Length			F		M	
Winding			V050	V300	V050	V230
Maximum force	F_{\max}	N	1,712.0		3,320.0	
Continuous nominal force	F_N	N	428.0		830.0	
Maximum current	$I_{\max(\text{rms})}$	A	18.4	36.0		62.8
Rated current	I_N	A	4.6	9.0		15.7
Reference voltage DC bus voltage	U_{DC}	V	300			
Maximum velocity at F_{\max}	$v_{F\max}$	m/min	70	290	60	230
Nominal velocity	v_N	m/min	210	460	200	370
Latest amendment: 2012-06-15						

Technical Data

Parameter	Symbol	Unit	MCP070			
Frame Length			F		M	
Winding			V050	V300	V050	V230
Force constant	K _{FN}	N/A	93.0	47.5	92.2	52.9
Voltage constant	K _{EMK}	Vs/m	53.7	26.9	54.7	31.4
Winding resistance at 20 °C	R ₁₂	Ohm	7.5	2.2	3.8	1.25
Winding inductivity	L ₁₂	mH	5.7	1.39	2.66	0.92
Winding inductivity	L _{23,31}	mH	7.8	1.94	3.92	1.23
Rated power loss	P _{VN}	W	317.0	321.0	614.8	590.8
Pole width	t _p	mm	30.00			
Thermal time constant	T _{th}	min	5.0	3.1	3.3	
Primary part mass	m _P	kg	2.85		5.90	
Latest amendment: 2012-06-15						

Fig.4-37: MCP070F/M - Technical data

4.7.2 Data Sheet MCS070

Designation	Symbol	Unit	MCS070-__-0120	MCS070-__-0180	MCS070-__-0300
Secondary part mass	m_s	kg	3.0	4.5	7.4
Latest amendment: 2012-03-29					

Fig.4-38: MCS070 - Technical data

4.7.3 Motor Characteristic Curves Frame Size 070






Fig.4-39: Motor characteristic curve MCP070C-V050 bei 300 V_{DC}

Technical Data

Fig.4-40: Motor characteristic curve MCP070C-V300 bei 300 V_{DC}Fig.4-41: Motor characteristic curve MCP070D-V050 bei 300 V_{DC}




Fig.4-42: Motor characteristic curve MCP070D-V300 bei 300 V_{DC}






Fig.4-43: Motor characteristic curve MCP070F-V050 bei 300 V_{DC}

Technical Data

Fig.4-44: Motor characteristic curve MCP070F-V300 bei 300 V_{DC}Fig.4-45: Motor characteristic curve MCP070M-V050 bei 300 V_{DC}

Technical Data




Fig. 4-46: Motor characteristic curve MCP070M-V230 bei 300 V_{DC}

5 Specifications

5.1 Installation Tolerances

5.1.1 General Information

To ensure a safe operation and constant force over the total traversing range, an air gap between primary and secondary part must exist. Therefore, the single parts of the motor have the corresponding tolerances. The distance of the mounting surface, the parallelism and the symmetry of the primary and secondary part of the linear motor in the machine must be within a certain tolerance above the entire travel path. Any deformations that result from weight, attractive forces and process forces must be taken into account.




The specified installation dimensions with the corresponding tolerances must be kept by the user over the complete travel path. Due to an undersized air gap, the primary part can have contact with the secondary part and can therewith damage or destroy motor components.

For the installation of the motors into the machine structure, Bosch Rexroth specifies a defined installation height with tolerances. Thus, the specified size and tolerances of the air gap are maintained inevitably – even if individual motor components are replaced.


Specifications

5.1.2 Frame Size MCL015



*)
Fig.5-1: Tolerance details see motor dimension sheet
Mounting sizes and tolerances MCL015

5.1.3 Frame Size MCL020 ... 070



Motor dimensions

Motor installation room
(by the customer)

Frame size	Motor height A	Motor width	
		MCP B*	MCS C*
020	52.0 mm	20.5 mm	20.8 mm
030	67.0 mm	24.7 mm	25.0 mm
040	86.4 mm	34.0 mm	34.3 mm
070	124.0 mm	49.2 mm	49.5 mm

*) Tolerance details see motor dimension sheet
Fig.5-2: Mounting sizes and tolerances MCL020 ... 070



The specified installation dimensions with the corresponding tolerances must be kept by the user over the complete travel path.


Specifications

5.1.4 Parallelism and Symmetry of Machine Parts

Before primary and secondary part can be mounted, align the parts of the machine. Especially the machine slide is to be brought into a defined position to the machine bed. When aligning, the installation dimensions and tolerances regarding parallelism and symmetry according to must be kept.

To keep the tolerances, it is necessary that the fastening holes and threads for the primary part and the secondary part in the machine are strictly done according to the dimensions of the particular dimension sheet. The alignment of the motor components must be done according to [fig. 5-3 "Parallelism and symmetry between primary and secondary parts"](#) on page 58.

You will find further notes regarding assembly of primary and secondary parts in the chapter [chapter 13 "Assembly"](#) on page 165.



①

Secondary part

②

Primary part


Fig. 5-3:


Parallelism and symmetry between primary and secondary parts

Specifications

Specifications

5.2 Dimension Sheets MCL015










Fig.5-7: Dimension sheet secondary part MCS020

Specifications

5.4 Dimension Sheets MCL030





Specifications

5.5 Dimension Sheets MCL040





Fig.5-10: Dimension sheet primary part MCP040



5.6 Dimension Sheets MCL070




Fig.5-12: Dimension sheet primary part MCP040




Fig.5-13: Dimension sheet secondary part MCS070

6 Type Codes

6.1 Type Code Structure and Description

6.1.1 General Information

The type code describes the deliverable motor variants. It is the basis for selecting and ordering products from Bosch Rexroth. This applies to new products as well as to spare parts and repairs..

In the following, a type code example is given, where a stipulation of the single components (e.g. for orders) is made possible.

The following description gives an overview over the separate columns of the type code ("abbrev. column") and its meaning.



When selecting a product, always consider the detailed specifications in the chapter "chapter 4 "Technical Data" on page 27" and chapter "chapter 9 "Application and Construction Instructions" on page 103".

6.1.2 Type Code Primary Part MCP

General Information




Fig.6-1: Example of type code MCP040 primary part

Type Codes

Product

Short-text columns 123 **MCP** is the name of an ironless linear motor primary part product group.

Frame size

Short-text columns 456 The motor size is derived from the active motor length and represents different power ranges.

Frame length

Short-text column 7 Within a series, the grading of increasing motor length is indicated by ID letters in alphabetic order.

Winding

Abbrev. column 9 10 11 12 The winding designation is made via the prefix "V" for a DC bus voltage of 300 V_{DC} or a prefix "L" for a DC bus voltage of 48 V_{DC}.

Cooling

Short-text column 14 MCP primary parts are only available with cooling mode natural convection.

Design

Short-text column 15 Depending from the frame size, two different frame sizes are available. The frame size derives from the cross section of the respective primary part and is described by the letters "T" and "I".

Hall unit

Short-text columns 1718 Primary parts of size 020 up to 070 can be optionally fitted with a Hall unit for position detection. Depending from the frame size, the following Hall units with different output signals are available.

- L1 = analog
- L0 = digital
- N0 = none

The cable output direction of the Hall unit is performed to the same front side as for the power connection.

The necessary length measuring system is not in the scope of delivery of Bosch Rexroth and has to be provided and mounted by the machine manufacturer himself.

Electrical Connection

Short-text columns 1920 All primary parts are provided with a flexible and shielded connection cable. The connection cable is firmly connected with the primary part and performed on the front side for MCP020 up to MCP070 and laterally for MCP015.

Other Design

Abbrev. column 22 23 24 25 Those fields are not reserved.

6.1.3 Type Code Secondary Part MCS
General Information




Fig. 6-2: Example of type code MCS040 secondary part

Product

Short-text columns 123 MCS is the name of an ironless linear motor secondary part product group.

Frame Size

Short-text columns 456 The frame size of the secondary part is derived from the active motor length and represents different power ranges.

Mechanical Design

Short-text column 8 The number 3 stands for the fastening of the secondary part with screws.

Mechanical Protection

Short-text column 9 To ensure the best possible operational reliability, the permanent magnets of the secondary part are protected against outer influences like corrosion by coating. Therefore, no additional cover for specified environmental conditions is necessary.

Segment Length

Abbrev. column 11 12 13 14 Depending from the motor frame size, different secondary part lengths are available.

Other design

Abbrev. column 16 17 18 19 Those fields are not reserved.

Type Codes

6.2 Type Code Frame Size 015

© Bosch Rexroth AG 2011

ZN-40037-015_EN_2011-07-22.fh11

Abbrev.	Column	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	
Example:		M	C	P	0	1	5	A	-	L	0	4	0	-	N	T	-	N	0	F	N	-	N	N	N	N																

Product

MCP = MCP

Size

015 = 015

Length

Lengths = A, B

Winding

MCP015A = L040

MCP015B = L040

Cooling

Natural convection = N

Mounting style

T-shape = T

Hall unit

None = N0

Electrical connection

Cable conducted through the side = FN

Other design

None = NNNN

Fig.6-3: Type code MCP015 primary part

Type Codes

ZN-40038-015_NOR_N_EN_2010-02-17.fn11 © Bosch Rexroth AG 2010

Abbrev.	Column	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40		
Example:		M	C	S	0	1	5	-	3	S	-	0	0	6	6	-	N	N	N	N																							

Product
MCS = MCS

Size
015 = 015

Mechanical design
Fixing per screws = 3

Mounting style
Standard = S

Segment length
Secondary part length 66 mm = 0066
Secondary part length 99 mm = 0099

Other design
None = NNNN

Fig. 6-4: Type code MCS015 secondary part

Type Codes

6.3 Type Code Frame Size 020

© Bosch Rexroth AG 2011

ZN-40037-020_EN_2011-07-22.fn11

Abbrev.	Column	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	
Example:		M	C	P	0	2	0	C	-	V	1	8	0	-	N	I	-	N	0	C	N	-	N	N	N	N																

Product

MCP = MCP

Size

020 = 020

Length

Length.....= B, C, D

Winding

MCP020B = V180, V720

MCP020C = V180, V720

MCP020D = V180, V720

Cooling

Natural convection = N

Mounting style

I-shape = I

Hall unit

Digital = L0

Analogue = L1

None = N0

Electrical connection

Cable conducted through front of the primary part = CN

Other design

None = NNNN

Fig.6-5: Type code MCP020 primary part

Type Codes

ZN-40038-020_NOR_N_EN_2010-02-17.fn11© Bosch Rexroth AG 2010

Abbrev.	Column	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	
Example:		M	C	S	0	2	0	-	3	S	-	0	1	2	0	-	N	N	N	N																						

Product
MCS = MCS

Size
020 = 020

Mechanical design
Fixing per screws = 3

Mounting style
Standard = S

Segment length
Secondary part length 120 mm = 0120
Secondary part length 180 mm = 0180
Secondary part length 300 mm = 0300

Other design
None = NNNN

Fig.6-6: Type code MCS020 secondary part

Type Codes

6.4 Type Code Frame Size 030

© Bosch Rexroth AG 2011

ZN-40037-030_EN_2011-07-22.fn11

Abbrev.	Column	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0
Example:		M	C	P	0	3	0	D	-	V	1	8	0	-	N	I	-	N	0	C	N	-	N	N	N	N															

Product
MCP = MCP

Size
030 = 030

Length
Lengths. = B, C, D

Winding
MCP030B = V180, V390
MCP030C = V180, V390
MCP030D = V180, V390

Cooling
Natural convection = N

Mounting style
I-shape = I

Hall unit
Digital = L0
Analogue = L1
None = N0

Electrical connection
Cable conducted through front of the primary part = CN

Other design
None = NNNN

Fig.6-7: Type code MCP030 primary part

Type Codes

ZN-40038-030_NOR_N_EN_2010-10-29.fn11 © Bosch Rexroth AG 2010

Abbrev.	Column	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40		
Example:		M	C	S	0	3	0	-	3	S	-	0	1	2	0	-	N	N	N	N																							

Product
MCS = MCS

Size
030 = 030

Mechanical design
Fixing per screws = 3

Mounting style
Standard = S

Segment length
Secondary part length 120 mm = 0120
Secondary part length 180 mm = 0180
Secondary part length 300 mm = 0300

Other design
None = NNNN

Fig.6-8: Type code MCS030 secondary part

Type Codes

6.5 Type Code Frame Size 040

© Bosch Rexroth AG 2011

ZN-40037-040_EN_2011-07-22.fn11

Abbrev.	Column	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	
Example:		M	C	P	0	4	0	E	-	V	0	7	0	-	N	I	-	N	0	C	N	-	N	N	N	N																

Product
MCP = MCP

Size
040 = 040

Length
Lengths= B, C, E, G

Winding
MCP040B = V070, V300
MCP040C = V070, V300
MCP040E = V070, V300
MCP040G = V070, V300

Cooling
Natural convection = N

Mounting style
I-shape = I

Hall unit
Digital = L0
Analogue = L1
None = N0

Electrical connection
Cable conducted through front of the primary part = CN

Other design
None = NNNN

Fig.6-9: Type code MCP040 primary part

Type Codes

ZN-40038-040_NOR_N_EN_2010-02-17.fh11

© Bosch Rexroth AG 2010

Abbrev.	Column	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0
Example:		M	C	S	0	4	0	-	3	S	-	0	1	2	0	-	N	N	N	N																					

Product
MCS = MCS

Size
040 = 040

Mechanical design
Fixing per screws = 3

Mounting style
Standard = S

Segment length
Secondary part length 120 mm = 0120
Secondary part length 180 mm = 0180
Secondary part length 300 mm = 0300

Other design
None = NNNN

Fig. 6-10: Type code MCS040 secondary part

Type Codes

6.6 Type Code: Frame Size 070

© Bosch Rexroth AG 2011

ZN-40037-070_EN_2012-01-13.fh11

Abbrev.	Column	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	
Example:		M	C	P	0	7	0	D	-	V	0	7	0	-	N	I	-	N	0	C	N	-	N	N	N	N																

Product
MCP = MCP

Size
070 = 070

Length
Lengths = C, D, F, M

Winding
MCP070C = V050, V300
MCP070D = V050, V300
MCP070F = V050, V300
MCP070M = V050, V230

Cooling
Natural convection = N

Mounting style
I-shape = I

Hall unit
Digital = L0
Analogue = L1
None = N0

Electrical connection
Cable conducted through front of the primary part = CN

Other design
None = NNNN

Fig.6-11: Type code MCP070 primary part

Type Codes

ZN-40038-070_NOR_N_EN_2010-02-17.fn11 © Bosch Rexroth AG 2010

Abbrev. Column	1	2	3	4	5	6	7	8	9	1	0	1	2	3	4	5	6	7	8	9	2	0	1	2	3	4	5	6	7	8	9	3	0	1	2	3	4	5	6	7	8	9	4	0	
Example:	M	C	S	0	7	0	-	3	S	-	0	1	2	0	-	N	N	N	N																										

Product
MCS = MCS

Size
070 = 070

Mechanical design
Fixing per screws = 3

Mounting style
Standard = S

Segment length
Secondary part length 120 mm = 0120
Secondary part length 180 mm = 0180
Secondary part length 300 mm = 0300

Other design
None = NNNN

Fig.6-12: Type code MCS070 secondary part

7 Accessories and Options

7.1 Hall Unit

7.1.1 General Information

To drive synchronous motors, an absolute position information regarding pole pair or pole pair width is necessary to recognize the position of the permanent magnets to the motor windings. Only in connection with an electric commutation offset angle, which must be determined at initial start-up, it is possible to impress the voltage with correct phase position to the magnetic field via the controller so that the motor can develop its force.

When using an incremental length measuring system, a commutation of the axes has to result from every step up of the phases of the drive device. This is done by a drive-internal procedure. After this, a force processing of the motor is possible.



The commutation is determined automatically during the phase step up by the Hall unit. Therefore, no power switch-on (no motor movement) is necessary.

The Hall unit offers special advantages, for example at commutation of linear motors ...

- in Gantry arrangement,
- on vertical axes,
- in mechanical safe state,
- which are not allowed to be driven during the commutation process for safety reasons.

7.1.2 Hall Unit Functional Principle

The Hall unit (analog or digital) serves for motionless commutation of ironless linear motors in connection with an incremental measuring system. On IndraDrive Cs, the motor is automatically commutated from phase switch into operating mode. Therefore, no power motion is necessary. The motor can be stalled, for example, or be at the travel length end (end stop).

Rexroth linear motors of MCL020 ... 070 series can be ordered with or without Hall unit (see [chapter 6.1.2 "Type Code Primary Part MCP" on page 71](#)) according to the motor type code.



Independend from the origin order design, the primary parts of 020 ... 070 series can be upgraded or modified with a Hall unit which can be ordered separately.

Accessories and Options

Hall unit analog Analog Hall units for MCL from Rexroth create two sinusoidal signals, which are phase-delayed by 120° . The output voltage is maximum $1 V_{SS}$ depend from the position of the Hall unit via the magnets of the secondary parts and is prepared on the lines according to Fig.7-1. The voltage supply is 7 ... 20 V. The voltage supply must ensure a current consumption of the Hall unit of minimum 40 mA.




Fig.7-1: Signal curve of an analog Hall unit



Bosch Rexroth controllers use a voltage supply of 12 V for analog Hall units.

Accessories and Options

Hall unit digital

Digital Hall units for MCL from Rexroth create three rectangular signals, which are phase-delayed by 120° . The signals of an open-collector-switch are provided on the lines according to Fig. 7-2. The voltage supply is 3 ... 24 V. The voltage supply must ensure a current consumption of the Hall unit of minimum 40 mA.




Fig. 7-2: Signal curve of a digital Hall unit



The signal height of the digital Hall unit is depending on the voltage supply of open-collector-switch. Bosch Rexroth controller use a voltage supply of 5 V.

Accessories and Options

7.1.3 Hall Unit Assembly/Disassembly



The Hall unit is an ESD sensitive device. Before connecting the Hall unit, take appropriate measures for ESD protection (ESD = electrostatic discharge).

If a Hall unit on the primary part must be retrofitted or exchanged, remove a dummy or the Hall unit to be changed from the installation space of the sensor. For easy press out of the dummy or the Hall unit, a small tool is provided with the accessory delivery. The existing fastening screws can be used for assembly of the new Hall unit. Observe the allowed tightening torque (see Fig. 7-4) not to be exceeded, when tightening the fastening screws. A too high tightening torque can damage the fastening thread of the Hall unit and can make it useless, then.




Fig. 7-3: Hall unit assembly / disassembly

1. Loosen both fastening screws. Store them until the new Hall unit must be fastened. When loosening the fastening screws, only use screws of the same design (see Fig. 7-4)!
2. Press the dummy or the Hall unit with the tool out of the installation space and remove it.
3. Assemble the new Hall unit.

Hall unit assembly - tightening torque of screws

Hall unit on	Bolt size-ISO-grade	Property class	Tightening torque
MCP020	M2.5x16 (DIN EN ISO 7045 - Torx)	8.8	0.8 Nm
MCP030	M2.5x5 (DIN EN ISO 7045 - Torx)		
MCP040	M2.5x5 (DIN EN ISO 7045 - Torx)		
MCP070	M2.5x8 (DIN EN ISO 7045 - Torx)		

Fig. 7-4: Tightening torque Hall unit

7.1.4 Ordering Designation Separate Hall Unit

Primary part MCP ...	Ordering designation Hall unit	
	Analog	Digital
015	no Hall unit available	
020	SUP-E01-A15-MCP020 (R911335794)	SUP-E01-D15-MCP020 (R911335797)
030 ... 070	SUP-E01-A30-MCP030/040/070 (R911335796)	SUP-E01-D30-MCP030/040/070 (R911335798)

Fig. 7-5: Ordering designation Hall unit

7.2 Hall Unit Adapter Box SHL03.1

7.2.1 General Functional Principle

Are Rexroth linear motors of the MCL020 ... 070 series operated on the IndraDrive Cs, using a Hall unit adapter box SHL03.1 makes the use of a digital Hall unit and an incremental length measuring system possible at the same time. The SHL03.1 adapter box joins signals of both components and merges them with the provided interface on the IndraDrive Cs.



A possible cabling with Rexroth cables is described under [chapter 8.2.4 "Connect Digital Hall Unit" on page 100](#).

7.2.2 Order Designation Hall Unit Adapter Box

SHL03.1 adapter box	
Short name	SHL03.1-NNN-S-NNN
Part number	R911335257


Fig. 7-6: Order designation SHL03.1 adapter box

8 Electrical Connection

8.1 Power Connection

8.1.1 Connection Cable on Primary Part

Primary parts of MCL motors are fitted with a flexible and totally shielded connection cable. This 1100 mm long connection cable is connected with the primary part.



- ① Primary part MCP
- ② Connection cable power
- ③ Connection cable Hall unit (optional for MCP020 ... 070; see [fig. 8-10 "Wire designation connection cable Hall unit" on page 98](#))
- ④ Wires with wire end ferrules

Fig. 8-1: Design of connection cable (power) on the primary part MCP

The technical data of the connection cable for every single frame size are given in the following overview.

Connection Cable Power

Frame size	Connection cable	Diameter [D in mm]	Cross section Power wires [mm²]	Cross section Control wire [mm²]	Allowed bending radius[R]*
MCP015	REL0010	4.2 ±0.1	3 x 0.14	- / -	- for fix installation 5 x D - for flexible installation 7.5 x D
MCP020	REL0011	7.8 ±0.2	4 x 0,5	2 x 0.14	
MCP030					
MCP040	REL0012	8.3 ±0.2	4 x 0.75	2 x 0.75	
MCP070C/D/F					
MCP070M	INK0650	12.2 ±0.5	4 x 1.5		

*) See notes regarding bending radius under [fig. 8-3 "Example for strain relief of connection cable"](#) on page 92

*) See notes regarding bending radius under [fig. 8-3 "Example for strain relief of connection cable" on page 92](#)

Fig. 8-2: Connection cable power on MCP primary parts

Installation of connection cable


The connection cable is moulded fix with the primary part and ends with open cable ends with wire end ferrules. Basically, we recommend to lead the connection cable in fix installation to a junction, provided by the customer, like e.g. flange sockets or terminal boxes.. From this junction, a suitable power cable can be laid to supply power through the energy chains or the machine construction.

Electrical Connection

NOTICE

Avoid bending, pulling and pushing loads as well as continuous movements of the connection cable at the point where the cable exits from the primary part. Any load of this kind, can lead to irreparable damage (e.g. cable break) on the primary part!

If a fixed installation is not possible, provide the connection cable with a strain relief (see Fig. 8-3) to protect the cable and the primary part from any damage (e.g. cable break).



Dimension "x" Minimum distance 5 mm

① Strain relief of the connection cable on MCP primary part

D Diameter connection cable (see Fig. 8-2)

R Allowed bending radius - see Fig. 8-2

Fig. 8-3: Example for strain relief of connection cable

Ground connection



If the grounding of the secondary parts cannot be ensured with mounting into the customer's machine construction, connect it according to DIN VDE 0100-410 with the potential of the protective conductor.


8.1.2 Assembly Connection Cable on Primary Part

Bosch Rexroth offers ready-made power cables to connect MCP primary part on Rexroth controllers.

Mount the connection cable on the flange socket (RLS1704) to connect the primary part with the power cable. The available power cables of Rexroth can be connected on these flange sockets.



The assignment of the available power cables results from the motor-controller-combination and can be seen in tablefig. 10-2 "Motor-Controller-Combinations with IndraDrive Cs" on page 136.



① Flange socket RLS1704

② Connect total shield over the cable gland with the connector housing.

Fig. 8-4: RLS1704 connection assignment on connection cable MCP




Observe the assembly instruction, which is delivered with the flange socket.

Electrical Connection

8.1.3 Connection Power


Power connection for motor single arrangement




- ① Rexroth drive controller
- ② Junction (e.g. terminal box)
- ③ Temperature sensor and ground wire available only for frame size MCP020 ... 070.

Fig.8-5: Power connection on drive controller - single arrangement

Power connection for motor parallel arrangement

 For parallel arrangement, only identic primary parts may be used.
See also [chapter 9.4.2 "Several Motors per Axis" on page 108](#).



- ① Rexroth drive controller
- ② Junction (e.g. terminal box)
- ③ Shorting and isolating the wires of the temperature sensor KTY84 on the motor 2
- ④ Temperature sensor and ground wire available only for frame size MCP020 ... 070.

Fig.8-6: Power connection on drive controller - parallel arrangement

Connection power cable in dependence from primary part at parallel arrangement

The connection of the power wires of the connection cable on the drive controller at parallel arrangement of the primary parts with outgoing cableKabelabgang in the cross-direction depend on the direction of the outgoing cable.

Drive-controller X5	Cable outlet in the same direction (see Fig.9-12 on page 111)			Cable outlet in the opposite direction (see Fig.9-17 on page 112 and Fig.9-20 on page 112)		
	A1	A2	A3	A1	A2	A3
Primary part 1	U	V	W	U	V	W
Primary part 2	U	V	W	U	W	V

Fig.8-7: Connection of the power wires in case of parallel arrangement of primary parts on a drive controller

Electrical Connection

8.1.4 Installation of Power Connection

Installation method for motor single arrangement


Installation mode for parallel motor connection

Parallel arrangement, install separate power cables

see [fig. 8-13 "Connection overview MCP with digital Hall unit"](#) on page 100 and [fig. 8-14 "Connection overview MCP with analog Hall unit"](#) on page 101.

When connecting a motor parallel on a drive controller, the following possibilities exist to assembly the motor cable.

- Installation with two separate parallel power cables
- Installation with a collective power cable with bigger cross section




- ① Drive controller
- ② Energy chain
- ③ Junctions
- ④ Motor 1
- ⑤ Motor 2

Fig. 8-8: Parallel arrangement, separate power cable

Electrical Connection

Parallel arrangement, install collective power cable with bigger cross section



- ① Drive controller
- ② Energy chain
- ③ Junctions
- ④ Motor 1
- ⑤ Motor 2

Fig. 8-9: Parallel arrangement, collective power cable

8.2 Sensors

8.2.1 Connection Temperature Sensor

All primary parts - except frame size MCP015 - are equipped with a PTC temperature sensor **KTY84-130**. The temperature sensor is fixed within the motor winding and serves for winding temperature measuring. The temperature sensor itself offers no safe protection of the winding from thermal overload. The thermal monitoring of the motor must additionally be done via a working temperature model in the controller.

Heed the right polarity of the connection wires when connecting the KTY84-130. The wire designation can be found under Fig. 8-1.

For additional information on the temperature sensor, please refer to [chapter 9.7 "Motor Temperature Monitoring" on page 119](#).




- Temperature sensor KTY84-130 is a component that might be damaged by ESD! For this reason, the wires of the sensor are protected by a protective foil at the connection cable. Before connecting the sensor, take measures regarding ESD protection. (ESD = electrostatic discharge).
- The used temperature sensors are double or reinforced insulated according to DIN EN 50178, so separation exists according to DIN EN 61800-5-1.

Electrical Connection

8.2.2 Connection Hall Unit

Motors with Hall unit have an additional cable to connect the sensor. This cable is beside the connection cable for the power. After motor installation, the cable of the Hall unit can be shortened to the required length and be assembled with a D-sub connector, 9-pole (pin), for example. See also [chapter 8.2.3 "Assembly Hall Unit Connection Cable" on page 99](#).




Connection cable Hall unit

Motor frame size	Diameter [D]	Cross section Control wire [mm²]	Allowed bending radius[R]*
MCP020 ... 070	4.2 ±0.1	6 x 0.14	- for fix installation 5 x D - for flexible installation 7.5 x D

*) See notes regarding bending radius under [fig. 8-3 "Example for strain relief of connection cable" on page 92](#)

Fig.8-11: Connection cable Hall unit on primary parts MCP020 ... 070

 The Hall unit is a component that might by damaged by ESD! For this reason, the wire ends on the connection cable are protected with a protective foil. Before connecting the Hall unit, take appropriate measures for ESD protection (ESD = electrostatic discharge).

For more information about the Hall unit, please refer to [chapter 7.1 "Hall Unit" on page 85](#).

8.2.3 Assembly Hall Unit Connection Cable

Before the Hall unit can be connected to the SHL03.1 adapter box, the connection cable of the Hall unit must be assembled with a 9-pole D-sub connector. The assignment


	Connection cable Hall unit	
	analog	digital
1	12 V	12 V
2	A +	S1
3	A -	/
4	0 V	S2
5	B +	0 V
6	B -	/
7	/	/
8	/	S3
9	/	/
Plug housing	Outer shield	Outer shield


Fig. 8-12: Connection assignment D-sub connector (9-pole, pin) on Hall unit connection cable

Electrical Connection

8.2.4 Connect Digital Hall Unit

To connect a digital Hall unit in connection with an incremental length measuring system on a controller of the IndraDrive Cs family, use the **SHL03.1 adapter box**.

The SHL03.1 brings both incoming signal cables of Hall unit and length measuring system together and redirects their signals via a single connection cable to the drive controller for encoder evaluation.




- | | |
|---------|---|
| ① | D-sub connector 15-pole (pins) |
| ② | D-sub connector 9-pole (pins) |
| ③ | Flange socket RLS1704 |
| RKL480x | Motor power cable (max. cable length 75 m) |
| RKG0049 | Adapter box ↔ encoder evaluation on drive controller (max. cable length 75 m) |
| RKG0050 | Digital Hall unit ↔ adapter box (max. cable length 30 m) |
| RKG0051 | Length measuring system ↔ adapter box (max. cable length 75 m) |
- Fig. 8-13: Connection overview MCP with digital Hall unit



- The total distance between drive controller and the head of the length measuring system and/or the Hall unit must not exceed a length of 75 m!
- Observe further notes about the SHL03.1 adapter box in the documentaion DOK-INDRV*-HCS01*****-PRxx-xx-P, MNR R911322210 and under [chapter 7.2 "Hall Unit Adapter Box SHL03.1"](#) on page 89.

8.2.5 Connect Analog Hall Unit

To connect an absolute measuring system and an analog Hall unit, a shelf with 2 encoder interfaces in the IndraDrive Cs controller is necessary.



①	D-sub connector 15-pole (pins)
②	D-sub connector 9-pole (pins)
③	Flange socket RLS1704
RKL480x	Motor power cable (max. cable length 75 m)
RKG0052	Analog Hall unit ↔ encoder evaluation on drive controller (max. cable length 75 m)
RKG0051	Length measuring system ↔ adapter box (max. cable length 75 m)
Fig. 8-14:	Connection overview MCP with analog Hall unit



- The total distance between drive controller and the head of the length measuring system must not exceed a length of 75 m!
- Observe further notes about the SHL03.1 adapter box in the documentation DOK-INDRV*-HCS01*****-PRxx-xx-P, MNR R911322210 and under [chapter 7.2 "Hall Unit Adapter Box SHL03.1" on page 89](#).

8.3 Length Measuring System



The length measuring system is not in the scope of delivery of the motor and must be prepared and assembled by the machine manufacturer (see [chapter 9.14 "Length Measuring System" on page 124](#)).

Setting the encoder polarity depends on the direction of rotation of the primary part and must be parameterized at start-up of the controller. Also observe the manufacturer's instruction of the length measuring system.

To connect an incremental length measuring system on Rexroth controller or on the adapter box SHL03.1, Bosch Rexroth offers the connection cable RKG0051 (see [Fig. 8-13](#) and [Fig. 8-14](#)). To use this cable, fit the connection cable on the incremental length measuring system with a compatible flange socket (D-sub connector).

Electrical Connection


 DA000056v01_nn.FH9	Signal	Function
1	Sense	Feedback of reference potential (sense-line)
2	+12V	Encoder supply 12 V
3	n. c.	/
4	R-	Reference track negative
5	B -	Track B negative
6	A -	Track A negative
7	n. c.	
8	+5V	Encoder supply 5 V
9	GND_Encoder	Reference potential voltage supplies
10	n. c.	/
11	n. c.	/
12	R+	Reference track positive
13	B +	Track B positive
14	A +	Track A positive
15	GND_shld	Connection signal shields (inner shields)
Plug housing	/	Outer shield

Fig.8-15: Connection assignment D-sub connector (15-pole, pin) on length measuring system for operation on controllers of IndraDrive Cs family.

9 Application and Construction Instructions

9.1 Mode of Functioning

The force generation for an ironless synchronous-linear motor, is the same as the torque generation at rotary synchronous motors. The ironless primary part (active part) has a winding; the secondary part (passive part) has permanent magnets.

Both, the primary part and the secondary part can be moved.

Realization of any traverse path length can be done by stringing together several secondary parts.

Axis Construction

The MCL motor is a kit motor. The components primary and secondary part(s) are delivered separately and completed by the user via linear guide and the linear measuring system. They are mounted into the machine or system.

The construction of an axis fitted with a linear motor normally consists of

- primary part with Hall unit
- one or more secondary parts with permanent magnets
- linear scale
- linear guide
- energy flow
- slide or machine construction

For force multiplication can be two or more primary parts mechanically coupled, arranged parallel or in-line. For further information see [chapter 9.4.2 "Several Motors per Axis" on page 108](#).




Only the primary and the secondary part(s) belong to the scope of delivery of the motor. Linear guide and length scale as well as further additional components have to be made available by the user.

9.2 Motor Design

9.2.1 Design Primary Part

The primary part consists of an u-shaped aluminum primary part carrier which bears the coil body and is molded with plastic resin. This mold serves for mechanical property of the MCP. It is no protection against humidity, foreign bodies or touch of electrically active parts. Due to the mold process, sometimes small blowholes can occur on the surface of the mold. They are not relevant for the function and mechanical property of the motor. The motor cooling happens due to the thermal coupling of the primary part on the machine and via the natural convection.

Application and Construction Instructions




① Primary part carrier out of aluminum
② Form of molded motor winding in design **I form** (MCP020 ... 070)
③ Form of molded motor winding in design **T form** (MCP015)
Fig.9-1: Design MCP primary part

9.2.2 Design Secondary Part

The MCS consists of an u-shaped screwed steel base plate with adhered permanent magnets. All fastening holes are in the fastening rail along the secondary part.

To ensure a high corrosion protection , the iron parts of the secondary part are nickel-plated and the permanent magnets are coated with epoxy.



① Permanent magnets
② Screwed secondary part body
Fig.9-2: Secondary part MCS040

Available lengths secondary parts

Secondary parts are available in different lengths. Please also refer to the data in the type code under [chapter " Segment Length" on page 73.](#)

Required length of the secondary parts

The required length L of the secondary part can be defined as follows:

$$L_{\text{Secondary part}} \geq L_{\text{Traversepath}} + L_{\text{Primary part}}$$

Fig.9-3: Defining the required length of the secondary part

9.2.3 Frame Size and Frame Length

For adjusting on different feed force requirements, Bosch Rexroth offers MCL motors in a modular system in different sizes and lengths.

Frame sizes The designation of frame size is derived from the active height I_{Fe} and power of MCL.




Fig.9-4: I_{Fe} = Active magnet height

According to this system, the MCL modular construction system contains the following motor frame sizes:

- MCP015 / MCS015
- MCP020 / MCS020
- MCP030 / MCS030
- MCP040 / MCS040
- MCP070 / MCS070

Sizes Primary and secondary parts of one size are graduated additionally to different frame sizes. The length designation of the primary part in the type code is done via code letters, like A, B, C. The length designation of the secondary part in the type code is given directly by the length in mm.



For detailed information about available frame sizes and lengths refer to the type code of the motor in [chapter 6 "Type Codes" on page 71](#).

Application and Construction Instructions

9.3 Requirements on the Machine Design

9.3.1 General Information

Derived from design and properties of linear direct drives, the machine construction must meet various requirements. For example, the moved masses should be minimized whilst the rigidity is kept at a high level.

9.3.2 Mass Reduction

To ensure a high acceleration capability, the mass of the moved machine elements must be reduced to a minimum. This can be done by using materials of a low specific weight (e.g. aluminum or compound materials) and by design measures (e.g. skeleton structures).

If highest acceleration is not required, even relative big mass can be moved. Precondition therefore is, a very rigid coupling of the motor to the weight.

9.3.3 Mechanical Rigidity

In conjunction with the mass and the resulting resonant frequency, the rigidity of the individual mechanical components within a machine chiefly determines the quality a machine can reach. The rigidity of a motion axis is determined by the overall mechanical structure. The goal of the construction must be to obtain an axis structure that is as compact as possible.

Natural Frequency

The increased loop bandwidth of linear drives required higher mechanical natural frequencies of the machine structure in order to avoid the excitation of vibrations.

To ensure a sufficient control quality, the lowest natural frequency that occurs inside the axis should not be less than approximately 200 Hz. The natural frequencies of axes with masses that are not constantly moving (e.g. due to workpieces that must be machined differently) change, so that the natural frequency is reduced with, as the mass increases.

$$f \approx \sqrt{1/m} \text{ auftritt.}$$

Mechanically coupled axes

The elasticity's of the axes (both, the mechanical and the control-engineering component) add up. This must be taken into account with respect to the rigidity of cinematically coupled axes.

If several axes must cinematically be coupled in order to produce path motions (e.g. cross-table or gantry structure), the mutual effects of the individual axes on each other should be minimized. Thus, cinematic chains should be avoided in machines with several axes. Axis configurations with long projections that change during operation are particularly critical.

Reactive Forces

Initiated by acceleration, deceleration or process forces of the moved axis, reactive forces can deform the stationary machine base or cause it to vibrate.




Fig.9-5: Deformation of the machine base caused by the reactive force during the acceleration process

$$\Delta s = \frac{m \cdot a}{c} = \frac{1 \text{ kg} \cdot 1000 \text{ m/s}^2}{1000 \text{ N/}\mu\text{m}} = 1 \mu\text{m}$$

Δs	Deformation of displacement of the machine base in μm
m	Mass in kg
a	Acceleration in m/s^2
c	Rigidity of the machine base in $\text{N/}\mu\text{m}$

Fig.9-6: Calculation example of the machine base deformation

Integrating the linear scale

The rigidity of the length measuring system integration is particularly important. For explanations refer to [chapter 9.14 "Length Measuring System" on page 124](#).

9.3.4 Protection of the Motor Installation Space

Due to protection mode IP00 of the motor components, the protection of the motor installation space need especial observance. To avoid that dirt comes into the air gap between primary and secondary part (e.g. due to any kind of residues, swarfs, resirable dust, etc.) during motor operation, the motor installation space must be designed according to the environmental conditions. The motor installation space must be designed in such a way, that the protection class IP65 according to DIN EN 60034-5 equivalent environmental conditions are ensured (see [chapter 9.9 "Ambient Conditions" on page 121](#)).

Heed appropriate protection measures when designing the machine construction. If dirt penetrates between the motor components due to insufficient protection measures, this can lead during operation to ...

- an increased heat introduction due to friction between the motor components. Thereby, temperatures can arise, which can cause a motor damage.
- Grinding traces and /or scratch-formation on the motor components can lead, for example to destroying of casting compound on the primary part, to motor breakdown, due to high mechanical force effect.

Please observe that dirt can also be brought indirectly into via pressure air or due to other machine parts (e.g. grease of the guides). This must be prevented.

Make sure by regularly maintenance of the safety measures that their function is still kept and the motor components could not be damaged.

9.3.5 Thermal Motor Connection

See information in [chapter 11.6 "Thermal Connection of MCL Motors on the Machine" on page 155](#).

Application and Construction Instructions

9.4 Arrangement of Motor Components

9.4.1 Single Arrangement

The single arrangement - independent operation of single primary parts - of the primary part is the most common arrangement. In such an arrangement, the length measuring system can also be equipped with two or more scanning heads.





Fig.9-7: Single axis arrangement of primary parts



- ① Control unit
- ② Control device
- ③ linear scale

Fig.9-8: Controlling a linear motor with single arrangement of the motor components

9.4.2 Several Motors per Axis

General Information

The arrangement of several motors per axis provides the following benefits:

- Multiplied feed forces
- Optimized utilization of available installation space

Application and Construction Instructions





Fig. 9-9: Arrangement of several motors per axis

Depending on the application, the motors can be controlled in two different ways:

- Two motors at one drive controller and one linear scale (parallel arrangement)
- Two motors at two drive controllers and two linear scales (Gantry arrangement)

Parallel Arrangement

The arrangement of two or more primary parts on one drive controller in conjunction with a linear scale is known as parallel arrangement. Parallel arrangement is possible if the coupling between the motors can be very rigid.




- ① Control unit
- ② Control device
- ③ linear scale

Fig. 9-10: Parallel arrangement of two primary parts on one drive controller in conjunction with a length measuring system

To ensure successful operation, the axis must fulfill the following requirements in parallel arrangement:

- Use identical primary parts MCP and same line length MCS
- Very stiff motor coupling within the axis
- Position offset among the primary parts <1 mm in feed direction
- Position offset between the secondary parts <1 mm in feed direction
- If possible, load stationary and arranged symmetrically with respect to the motors

Application and Construction Instructions



① Power connection of primary parts in same direction

② Position offset between the primary parts ≤ 1 mm

③ Position offset between the secondary parts ≤ 1 mm

Fig. 9-11: Alignment of motor components in parallel arrangement



The mounting holes of the primary parts are used for defining the correct position of the paralleled motors. Use always the same hole in the grid of both primary parts (see 9-11). An offset of the hole grid between the primary parts is only permitted in the structures shown in 9-13 or Fig. 9-14.

The face ends of the primary parts may alternatively be used if the mounting holes cannot be employed as position reference. The motor parts have the corresponding tolerances.

Parallel Arrangement: Double Comb Arrangement

In a parallel arrangement – also within a Gantry arrangement – the primary parts in feed direction can be mechanically coupled and arranged in the form of a double comb arrangement.



Double comb arrangement (acc. to Fig. 9-9 right-hand side) does **not** require a minimum distance to be kept between the two secondary part mounting surfaces.

Parallel Arrangement: Arrangement of Primary Parts in a Row

In a parallel arrangement – also within a Gantry arrangement – the primary parts in feed direction can be mechanically coupled and arranged in succession (see Fig. 9-9, center).

To ensure successful operation, the primary parts must be arranged in a specific grid. The determination of the grid size that must be adhered, depends on the direction of the cable entry and the permissible bending radius of the power cable.

Cable entry in the same direction

If the primary parts are arranged behind each other with the cable entries in the same direction acc. to Fig. 9-12, an integer multiple of twice the electrical pole pitch must be adhered to:

Application and Construction Instructions




Fig.9-12: Arrangement of the primary parts behind each other and cable entry in the same direction



When you determine the correct primary part distance with cable entries in the same direction acc. to Fig. 9-12, you must always use the same reference point for both primary parts (e.g. the same fastening hole).

$$\Delta x_p = n \cdot 2 \cdot \tau_p$$

- Δxp Required grid spacing between the primary parts in mm
- n Integer factor (depends on mounting distance)
- τp Electric pole pitch MCP015 = 8.25 mm; MCP020 = 15 mm; MCP030 ... 070 = 30 mm

Fig.9-13: Determining the grid size between the primary parts with cable entries in the same direction

Minimum distances between the primary parts

According to Fig. 9-12 and Fig. 9-13 result size-related minimum distances between the primary parts at a motor arrangement with cable output into the same direction:

$$x_p = n \cdot 2 \cdot \tau_p + x_{pmin}$$

- xp Required grid spacing between the primary parts in mm
- n Integer factor (depends on mounting distance)
- τp Electric pole pitch MCP015 = 8.25 mm; MCP020 = 15 mm; MCP030 ... 070 = 30 mm
- xpmin smallest allowed distance between the primary parts.

Fig.9-14: Determining the distance between the primary parts with cable entries in the same direction

Conditions to be kept:

$$x_{pmin} > \text{permitted bending radius motor cable in fixed installation}$$

Fig.9-15: Minimum distance xpmin to be kept between the two primary parts with cable entries in opposite direction

Motor version	xpmin in mm
MCP015	32
MCP020 ... 070	53

Fig.9-16: Minimum distance xpmin to be kept between the two primary parts with cable entries in the same direction

Application and Construction Instructions

Cable entry in opposite direction
(variant 1)

If the primary parts are arranged behind each other and with cable entries in opposite directions to Fig. 9-17, a defined distance must be kept between the primary parts according to Fig. 9-18 and Fig. 9-19.




Fig.9-17: Option 1: Arrangement of primary parts behind each other with cable entries in opposite directions



When you determine the correct primary part distance with cable entries in opposite directions according to Fig. 9-17 and Fig. 9-20, you can only use the distance between the primary part end faces x_p as reference point.

$$x_p = n \cdot 2 \cdot \tau_p + x_{pmin}$$

- x_p

Required grid spacing between the primary parts in mm
- n

Integer factor (depends on mounting distance)
- τ_p

Electric pole pitch MCP015 = 8.25 mm; MCP020 = 15 mm; MCP030 ... 070 = 30 mm
- x_{pmin}

smallest allowed distance between the primary parts.

Fig.9-18: Determining the grid distance between primary parts with cable entries in opposite directions

Minimum distances between the primary parts
(variant 1)

For a motor arrangement with cable entries at opposite directions, the following size-related minimum distances between primary parts result from:

Motor version	x_{pmin} in mm
MCP015	15.5
MCP020	29
MCP030 ... 070	59

Fig.9-19: Distance x_{pmin} to be kept between the two primary parts with cable entries in opposite direction

Cable entry in opposite direction
(variant 2)

If the primary parts are arranged behind each other and with cable entries in opposite directions to Fig. 9-20, a defined distance must be kept between the primary parts according to Fig. 9-21 and Fig. 9-23.




Fig.9-20: Option 2: Arrangement of primary parts behind each other with cable entries in opposite directions



When you determine the correct primary part distance with cable entries in opposite directions according to Fig. 9-17 and Fig. 9-20, you can only use the distance between the primary part end faces x_p as reference point.

$$x_p = n \cdot 2 \cdot \tau_p + x_{pmin}$$

- x_p Required grid spacing between the primary parts in mm
- n Integer factor (depends on mounting distance)
- τ_p Electric pole pitch MCP015 = 8.25 mm; MCP020 = 15 mm; MCP030 ... 070 = 30 mm
- x_{pmin} smallest allowed distance between the primary parts.

Fig.9-21: Determining the grid distance between primary parts with cable entries in opposite directions

Minimum distances between the primary parts (variant 2)

For a motor arrangement with cable entries at opposite directions, the following size-related minimum distances between primary parts result from:

Conditions to be kept

$$x_{pmin} > \text{permitted bending radius motor cable in fixed installation}$$

Fig.9-22: Distance x_{pmin} to be kept between the two primary parts with cable entries in opposite direction

Motor version	x_{pmin} in mm
MCP015	32
MCP020 ... 070	47

- n The integer factor n must be chosen in that way, so that the following conditions can be kept.
- τ_p Electric pole pitch MCP015 = 8.25 mm; MCP020 = 15 mm; MCP030 ... 070 = 30 mm

Fig.9-23: Distance x_{pmin} to be kept between the two primary parts with cable entries in opposite direction

Connection power cable

At parallel arrangement of primary parts, the connection of the power wires of the connection cable on the drive controller depends from the direction of the cable output.



The primary part 1 according to Fig. 9-17 and Fig. 9-20 is always the reference motor that is used for determining the sensor polarity and for commutation setting (refer also to "Connection power cable in dependence from primary part at parallel arrangement" on page 95).


Gantry Arrangement

Operation with two linear scales and drive controllers (Gantry arrangement) should be planned if there are load conditions that are different with respect to place and time, and sufficient rigidity between the motors cannot be ensured. This is frequently the case with axis in a Gantry structure, for example.



Parallel motors may also be used with a Gantry arrangement.

Application and Construction Instructions



- ① Control unit
 ② Controller (2 pcs.)
 ③ Length measuring system (2 pcs.)

Fig. 9-24: Gantry arrangement

With Gantry arrangements it must be remembered that the motors may be stressed unsymmetrically, although the position offset is minimized. As a consequence, this permanently existing bias load may lead to a generally higher stress than in a single arrangement. This must be taken into account when the drive is selected.



The asymmetric capacity can be reduced to a minimum by exactly aligning the length measuring system and the primary and secondary parts to each other, and by a drive-internal axis error compensation.

9.4.3 Arrangement of Secondary Parts

During assembly, you must not heed the arrangement of the secondary parts. Due to construction of MCS, a "polarity reversal" - arrangement of several secondary parts within a path is prevented. The order of magnetization is unchanged by a 180° - rotation of secondary parts.

9.4.4 Vertical Axis

⚠ CAUTION

Uncontrolled movements! Risk of injury!

When linear motors are used in vertical axes, it must be taken into account that the motor is not self-locking when power is switched off. Any lowering of the axis must be prevented by means of appropriate holding devices.



- On vertical axis, the use of an absolute measuring system is recommended.
- Incremental measuring systems can only be used, if a Hall unit is additionally used beside the holding device.

Weight Compensation

An additionally used weight compensation ensures that the motor is not exposed to an unnecessary thermal stress that is caused by the holding forces and the acceleration capability of the axis is independent of the motion direction. The weight compensation can be pneumatic or hydraulic. Weight compensation with a counterweight is not suitable since the counterweight must also be accelerated.

9.5 Feed Force at Reduced Covering Between Primary and Secondary Part

When moving in the end position range of an axis, it can be necessary that the primary part moves beyond the end of the secondary part. This results in a partial coverage between primary and secondary part.

If primary and secondary part are only partially covered, a reduced feed force and attractive force results.

Inserted force reduction

Outside the beginning and end areas (s_{R1} or s_{R2}), the force is reduced linearly as a function of the reduced coverage area.

The following diagram illustrates the correlation between the coverage between primary and secondary part and the resulting force reduction.



Are primary parts operated parallel on a controller acc. to Fig. 9-12, Fig. 9-17 and Fig. 9-20, deceleration forces can occur when primary parts are retracted out of the path due to a partial covering.




Fig. 9-25: Force reduction with partial coverage of primary and secondary part

Application and Construction Instructions


Motor version	S _{R1} [mm]	S _{R2} [mm]
without Hall unit	Installation position 1	
MCL015	0.5	0.5
MCL020 ... 070	6.5	0.5
	Installation position 2	
MCL015	0.5	0.5
MCL020 ... 070	0.5	6.5
with Hall unit		
If a Hall unit is used for commutation, the primary part on the cable output side must be completely within the secondary part. During operation, which is normally without analysis of the Hall unit, the primary part can be operated as described under "without Hall unit".		

Fig.9-26: Partial coverage vs. installation position

The partial coverage of primary and secondary parts must not be used in continuous operation since there is an increased current consumption of the motor due to control strategies. Instabilities in the control loop can be expected from a certain reduction of the degree of coverage onwards.

9.6 Thermal Behavior

Power loss The rated feed force of a synchronous linear motor can be achieved is mainly determined by the power loss P_V produced during the energy conversion process. The power loss fully dissipates in form of heat. Due to the limited permissible winding temperature it must not exceed a specific value.

 The allowed winding temperature of the motors is 130 °C.

The total loss of synchronous linear motors are significantly defined by the short-circuit loss of the primary part.

$$P_V \approx P_{VI} = \frac{3}{2} \cdot I^2 \cdot R_{12} \cdot f_T$$
$$f_T = R_{12} \cdot (1 + \Delta T \cdot \alpha_{20})$$

- P_V Total loss in W
- P_{VI} Short-circuit loss in W
- I Current in motor cable in A
- R₁₂ Electrical resistance of the motor at 20°C in Ohm
(see Chapter 4 Technical Data)
- f_T Factor temperature-related resistance raise
- ΔT Temperature increase in K
- α₂₀ Temperature coefficient of copper in 1/K

Fig.9-27: Power loss of synchronous linear motors



When you determine the power loss according to Fig. 9-27 you must take the temperature-related rise of the electrical resistance into account. At a temperature rise of 100 K (from 20 °C up to 120 °C), for example, the electrical resistance goes up by the factor $f_T = 1.39$.

Thermal time constant

The temperature variation vs. the time is determined by the produced power loss and the heat-dissipation and –storage capability of the motor. The heat-dissipation and –storage capability of an electrical machine is (combined in one variable) specified as the thermal time constant.

The following figure (Fig. 9-28) shows a typical heating and cooling process of an electrical machine. The thermal time constant is the period within which 63% of the final over temperature is reached.

Together with the duty cycle, the correlation to Fig. 9-29 and Fig. 9-31 are used to define the operating modes, e.g. acc. to DIN EN 60034-1.




Fig.9-28: Heating up and cooling down of an electrical machine

Heating Up

$$\vartheta(t) = \vartheta_e \cdot \left(1 - e^{-\frac{t}{t_{th}}} \right) + \vartheta_a \cdot e^{-\frac{t}{t_{th}}}$$

ϑ_e Final over temperature in K
 ϑ_a Initial over temperature in K
 t Time in min
 t_{th} Thermal time constant in min (see motor data sheet)

Fig.9-29: Heating (overtemperature) of an electric machine

Application and Construction Instructions

Final over temperature Since the final over temperature is proportional to the power loss, the expected final over temperature ϑ_e can be estimated according to:

$$\vartheta_e = \frac{P_{ce}}{P_{vN}} \cdot \vartheta_{e\max} = \frac{F_{eff}^2}{F_{dN}^2} \cdot \vartheta_{e\max}$$

P_{ce} Continuous power loss or average power loss over cycle duration in W (see [chapter 11.4 "Determining the Drive Power" on page 152](#))

P_{vN} Nominal power loss of the motor in W

$\vartheta_{e\max}$ Maximum final over temperature of the motor in K

F_{eff} Effective force in N (from application)

F_{dN} Continuous nominal force of motor in N (see motor data sheet)

Fig. 9-30: Expected final over temperature of the motor

Cooling down

$$\vartheta(t) = \vartheta_e \cdot e^{-\frac{t}{t_{th}}}$$

ϑ_e Final over temperature or shutdown temperature in K

t Time in min

t_{th} Thermal time constant in min (see motor data sheet)

Fig. 9-31: Cooling down of an electrical machine

9.7 Motor Temperature Monitoring

Primary parts of frame sizes MCP020 ... 070 are standardly fitted with an integrated temperature sensor (KTY84-130) for measuring the winding temperature in a phase.

To connect temperature sensors heed the details under [chapter 8.2.1 "Connection Temperature Sensor"](#) on page 97.

Temperature sensor KTY84-130

KTY84-130	Value
Resistance at 25 °C	min. 577 ... max. 629 Ohm
Resistance at 100 °C	min. 970 ... max. 1000 Ohm
Continuous current at 100 °C	2 mA

Fig. 9-32: Standard values on temperature sensors KTY84-130

The response temperatures of the sensor are

⇒ 110 °C prewarning temperature

⇒ 130 °C Shut-off temperature




Fig. 9-33: Characteristic temperature sensor KTY84-130




Temperature sensor KTY84-130 is a component that might be damaged by ESD! For this reason, the wires of the sensor are protected by a protective foil at the connection cable. Before connecting the sensor, take appropriate measures for ESD protection (ESD = electrostatic discharge).

9.8 Setup Elevation and Ambient Conditions

The motor performance data specified are applicable for

- Ambient temperatures 0 ... +40 °C
- Setup elevation of 0 m to 1,000 m above sea level.

Different conditions lead to a departing of the data according to the following diagrams. Do occur deviating ambient temperatures and higher installation altitude at the same time, both utilization factors must be multiplied.



① Usability to capacity, depending on the surrounding air temperature

② Usability to capacity, depending on the installation altitude

f_T Temperature utilization factor

t_A Ambient temperature in degrees Celsius

f_H Height utilization factor

h Installation altitude in meters

Fig. 9-34: Derating of ambient temperature, installation altitude (in operation)

Calculation of performance data in case the limits specified are exceeded:

Ambient temperature > 40 °C

$$M_{0_red} = M_0 \times f_T$$

Installation altitude > 1,000 m

$$M_{0_red} = M_0 \times f_H$$

Ambient temperature > 40 °C and setup elevation > 1,000 m

$$M_{0_red} = M_0 \times f_T \times f_H$$



The details for the utilization depending from the installation altitude and environmental temperature do not only apply to the motor, but on the whole drive system, consisting of motor, drive controller and mains supply. Ensure that the reduced data are not exceeded by your application.

9.9 Ambient Conditions

Environmental conditions are defined according to DIN EN 60721-3-3 in different classes. They are based on long-term experiences and take all influencing variables into account, e.g., air temperature and air humidity.

Overview of allowed classes of ambient conditions according to DIN EN 60721-3-3 during operation

Classification type	Allowed class
Classification of climatic ambient conditions	3K2
Classification of biological ambient conditions	3B1
Classification of chemically active materials	3C2
Classification of mechanically active materials	3S2
Classification of mechanical ambient conditions	3M1

Fig. 9-35: Allowed classes of ambient conditions during operation

Based on DIN EN 60721-3-3, some limit values are partially defined in the following, which our products are allowed to be used during operation. Observe the detailed description of the classifications to take all of the factors which are specified in the particular class into account.

Allowed operation conditions

Environmental factor	Unit	Value
Air temperature	°C	+5 ... +40 ¹⁾
Air humidity (relative)	%	5 ... 95
Air humidity (absolute)	g/m ³	1 ... 29
max. temperature change velocity	°C/min	0,5
Occurrence of salt mist		Not permitted ²⁾
Sand in air		Not permitted ³⁾

1) Rexroth permits 0 °C as the lowest air temperature.

2) Deviating from class 3C2 of DIN EN 60721-3-3

3) Deviating from class 3S2 of DIN EN 60721-3-3

Fig. 9-36: Operating conditions

Unless otherwise specified, the values given are the values of the particular class. However, Bosch Rexroth reserves the right to adjust these values at any time based on future experiences or changed ambient factors.

9.10 Degree of Protection

The design of MCL motors is according to protection mode according to DIN EN 60034-5.

Motor component	Degree of protection
Primary part (Front face MCP020 ... 070)	IP00 (IP20)
Secondary part	IP00
Hall unit	IP00

Fig.9-37: Protection modes on MCL motors



- The mold of primary parts serves for mechanical property. This is no protection against humidity. Due to the coating thickness of the mold for MCP020 ... 070, only a small protection against foreign bodies or touch of dangerous electric voltage is ensured on the front sides (cable output and opposite side). Therfrom, the protection mode IP20 is derived on the front.
- Observe the notes under [chapter 9.3.4 "Protection of the Motor Installation Space"](#) on page 107 regarding protection modes.

CAUTION

Any failure to observe the degree of protection of the motor may damage or destroy the motor components or result in personal injury!

The motors or components may only be used in environments where the degree of protection specified is adequate.

9.11 Acceptances and Approvals

9.11.1 CE-Sign

Declaration of conformity

Certificate of conformity certifying the structure of and the compliance with the valid EN standards and EC guidelines are available for all MCL motors. If necessary, these declarations of conformity can be requested from the responsible sales office.

The CE mark is applied to the motor type label of the MCL motors.



Fig.9-38: CE mark

9.11.2 cURus-Sign

At the moment, the approval of the motors at UL is in preparation

Motors authorized by the UL authorization (Underwriters Laboratories Inc.®) are labeled with the following sign on the motor type plate, the authorization number of the motors (file number) is given in the technical data.



Fig. 9-39: cURus sign

9.11.3 RoHS Conformity

For all MCL motors and components, Bosch Rexroth ensures conformity, according to EG directive 2002/95/EG to limit the use of certain dangerous materials in electro and electronic devices.

9.12 Magnetic Fields

The secondary parts of synchronous linear motors are equipped with permanent magnets, which are not magnetically shielded.

WARNING

Health risk for persons with pacemaker, metallic implants and hearing devices in direct environment of electric components!

- Persons with pacemakers and metallic implants are not allowed to have access to the following areas:
 - Areas in which components of electric drive and control systems are mounted, commissioned and operated.
 - Areas in which motor parts with permanent magnets are stored, repaired or assembled
- If it is necessary for persons with pacemakers to step into such areas, let this decide by a doctor first. The stability of implanted pacemakers is very different. So no general valid rules exist.
- Persons with metal implants or metal chips and with hearing devices must ask the doctor before they have access to such areas.

To be able to assess EMC -problems (e.g. the influence on inductive switches or inductive measuring systems), chip attraction, and for personal protection, the values of the magnetic induction as a function of the distance to the secondary part are specified below. The limit values for active body aids and for dispatch as air freight are stipulated in the professional association regulation BGR11 and in the IATA 953. The highest flow density (inductions) occur at the secondary parts of frame size MCS070. In April 2011, the valid references to standards result in the listed distances or inductive values for the secondary part MCS070-3S-0300-NNNN in the following table [fig. 9-40 "Magnetic field strength on secondary part MCS070" on page 124](#). For shipment of MCS as air freight, no further measures according to IATA 953 must be done.

Application and Construction Instructions

Magnetic field strength Induction values depending from the distance

Frame size	Distance 0 mm	Distance 2,100 mm	Distance up to ≤ 0.5 mT
MCS070	≤ 150 mT	0.04 μ T	35 mm

Fig.9-40: Magnetic field strength on secondary part MCS070

9.13 Noise Emission

The noise emission of synchronous linear drives can be compared with conventional inverter-operated feed drives. Empirically, it is dependend from the following factors:

- the employed linear guides (velocity-related travel noise),
- use length measuring system,
- mechanical construction (rotating covers, a.s.o.)
- the settings of drive and controller (e.g. switching frequency)

9.14 Length Measuring System

9.14.1 General Information

A linear measuring system is required for measuring the position and the velocity. Particularly high requirements are placed upon the linear scale and its mechanical connection. The linear scale serves for high-resolution position sensing and to determine the current speed.



The necessary length measuring system is not in the scope of delivery of Bosch Rexroth and has to be provided and mounted from the machine manufacturer himself (fig. 9-42 "Manufacturers of length measuring systems" on page 125).




Fig.9-41: Classification of linear scales

Particularities of Synchronous Linear Motors

It is necessary at synchronous linear motors to receive the position of the primary part relating on the secondary part by return after start or after a malfunction (pole position recognition). Using an absolute linear scale is the optimum solution here.

9.14.2 Selection Criteria for Length Measuring System

General Information

Depending on the operating conditions, open or encapsulated linear scales with different measuring principles and signal periods can be used. The selection of a suitable linear scales mainly depends on:

- the maximum feed rate (model, signal period)

Application and Construction Instructions

- the maximum travel (measuring length, model)
- if applicable, utilization of coolant lubricants (model)
- produced dirt, chips etc. (model)
- the accuracy requirements (signal period)

Manufacturers of Length Measuring Systems

In the following you will find an incomplete list of manufacturers of suitable length measuring systems for linear motors: Furthermore, other manufacturers are available which cannot be listed all.

Bosch Rexroth AG Linar and Assembly Technique	Maria-Theresien-Straße 23 97816 Lohr am Main, Germany info@boschrexroth.de http://www.boschrexroth.com/business_units/brl/de/ (Integrated measuring system for profiled rail guide)
Renishaw GmbH	Karl-Benz Strasse 12 72124 Pliezhausen, Germany http://www.renishaw.com
SIKO GmbH	Weihermattenweg 2 79256 Buchenbach, Germany info@siko.de http://www.siko.de/
NUMERIK JENA GmbH	Ilmstraße 4 07743 Jena, Deutschland applikation@numerikjena.de http://www.numerikjena.de/
SICK AG	Erwin-Sick-Straße 1 79183 Waldkirch, Germany http://www.sick.com/
AMO Automatisierung Messtechnik Optik GmbH	NÖFING 4 A-4963 ST. PETER AM HART office@amo.at http://www.amo-gmbh.com
DR. JOHANNES HEIDENHAIN GmbH	P. O. Box 1260 83292 Traunreut, Germany info@heidenhain.de http://www.heidenhain.de/

Fig. 9-42: Manufacturers of length measuring systems



- To ensure maximum interference immunity, Rexroth recommends the voltage interface with 1 V_{SS}.
- Please refer to the documents from the corresponding manufacturer for detailed and updated information.

Measuring System Cables

Ready-made cables of Rexroth are in preparation for the electrical connection between the output of the linear scale and the input of the scale inter-

face. To ensure maximum transmission and scale interference safety, you should preferably use these ready-made cables.

9.15 Linear Guiding Systems

Linear guiding systems for linear motors are, depending from the motor arrangement, are necessary due to feed forces and process forces and reachable velocity. The used linear guiding system must be able to adjust process and acceleration force.

Depending on the application, the following linear guides are employed:

- Ball or roll rail guides
- Slideways
- Hydrostatic guides
- Aerostatic guides

The following requirements should be taken into account when a suitable linear guide system is selected:

- High accuracy and no backlash
- Low friction and no stick-slip effect
- High rigidity
- Steady run, even at high velocities
- Easy mounting and adjustment

9.16 Manufacturers of Linear Guiding Systems



Linear guiding systems are not in the scope of delivery of the motor and must be ordered separately. The selection of a suitable linear guiding system is in the sole responsibility of the machine manufacturer. When selecting linear measuring systems please observe that this system uses sinusoidal instead of rectangular output signals. With sinusoidal output signals, a significantly higher position resolution and better position accuracy is reached via special evaluation revolution of our controllers. See also [chapter 9.22 "Position and Velocity Resolution"](#) on page 132.

In the following you will find an incomplete list of manufacturers of suitable length measuring systems for linear motors: Furthermore, other manufacturers are available which cannot be listed all.

Bosch Rexroth AG Linear and Assembly Technique	Maria-Theresien-Straße 23 97816 Lohr am Main, Germany info@boschrexroth.de http://www.boschrexroth.com/business_units/brl/de/ (Integrated measuring system for profiled rail guide)
--	--

Fig.9-43: Manufacturers of length measuring systems

9.17 Braking Systems and Holding Devices

The following systems can be used as braking systems and/or holding devices for linear motors:

- External braking devices
- Clamping elements for linear guides

- Holding brakes integrated in the weight compensation



Further designs about stand-still of linear motors are given in [chapter 9.18 "End Position Shock Absorber "](#) on page 127 and [chapter 9.21 "Deactivation upon EMERGENCY STOP and in the Event of a Malfunction "](#) on page 129 as well as in the appropriate functional description of the drive controller.

9.18 End Position Shock Absorber

WARNING

Damage on machine or motor components when driving against hard stop!

- ⇒ Use suitable energy-absorbing end position shock absorber
- ⇒ Adhere to the specified maximum decelerations

Suitable energy-absorbing end position shock absorber must be provided in order to protect the machine during uncontrolled coasting of an axis.

If this maximum deceleration is exceeded, this can lead to loosening the primary part and to damaging of motor components.



- Using a suitable end stop shock absorber, the maximum permissible deceleration for moving against an end stop must be limited to **250 m/s²**.
- The necessary spring excursion of the shock absorbers must be taken into account when the end position shock absorber are integrated into the machine (in particular when the total travel path is determined).

9.19 Axis Cover Systems

Depending on the application, design, operational principle and features of synchronous linear motors the following requirements on axis cover systems apply:

- High dynamic properties (no overshoot, little masses)
- Accuracy and smooth run
- Protection of motor components against chips, dust and contamination (in particular ferromagnetic parts),
- Resistance to oil and coolant lubricants
- Robustness and wear resistance

Different covering systems can be used, like bellow covers, telescopic covers or roller covers. A suitable axis cover system should be configured, if possible, during the early development process of the machine or system – supported by the corresponding specialized supplier (see).

9.20 Drive and Control of IndraDyn L motors

9.20.1 General Information

The following figures shows a complete linear direct drive, consisting of a synchronous linear motor, length scale system, drive controller and superordinate control.

Application and Construction Instructions




Fig.9-44: Linear direct drive

9.20.2 Drive Controllers

To control IndraDyn L motors, different digital drive controllers and power supply modules are available. (see [chapter 10 "Motor-Controller-Combinations"](#) on page 135)

9.20.3 Control Systems

A master control is required for generating defined movements. Depending on the functionality of the whole machine and the used control systems, Bosch Rexroth offers different control systems..

9.21 Deactivation upon EMERGENCY STOP and in the Event of a Malfunction

9.21.1 General Information

The deactivation of an axis, equipped with an IndraDyn L motor, can be initiated by

- EMERGENCY STOP,
- drive fault (e.g. response of the encoder monitoring function) or
- mains failure

ausgelöst werden.

For the options of deactivation an IndraDyn L motor in the event of a malfunction, distinction must be made between

- Deactivation by the drive,
- Deactivation by a master control and
- Deactivation by a mechanical braking device.

getroffen werden.

9.21.2 Deactivation by the Drive

As long as there is no fault or malfunction in the drive system, shutdown by the drive is possible. The shutdown possibilities depend on the occurred drive error and on the selected error response of the drive. Certain faults (interface faults or fatal faults) lead to a force disconnection of the drive.

WARNING

Death, serious injuries or damage to equipment may result from an uncontrolled coasting of a switched-off linear drive!

- ⇒ Construction and design according to the safety standards
- ⇒ Protection of people by suitable barriers and enclosures
- ⇒ Use external mechanical braking facilities
- ⇒ Use suitable energy-absorbing end position shock absorber

The parameter values of the drive response to interface faults and non-fatal faults can be selected. The drive switches off at the end of each fault response.

The following fault responses can be selected:

0 – Setting velocity command value to zero

Setting force command value to zero

Setting velocity command value to zero with command value ramp and filter

3 - Retraction



Please refer to the corresponding firmware function description for additional information about the reaction to faults and the related parameter value assignments.

Application and Construction Instructions

9.21.3 Deactivation by a Master Control

Deactivation by Control Functions

Deactivation by the master control should be performed in the following steps:

1. The machine PLC or the machine I/O level reports the fault to the CNC control
2. The CNC control deactivate the drives via a ramp in the fastest possible way
3. The CNC control causes the power at the power supply module to be shut down.

Drive initiated by the Control Shutdown

Deactivation by the master control should be performed in the following steps:

1. The machine I/O level reports the fault to the CNC control and SPS
2. The CNC control or the PLC resets the controller enabling signal of the drives. If SERCOS interface is used, it deactivates the "E-STOP" input at the SERCOS interface module.
3. The drive responds with the selected error response.
4. The power at the power supply module must be switched off 500 ms after the controller enabling signal has been reset or the "E-STOP" input has been deactivated.



The delayed power shutdown ensures the safe shutdown of the drive by the drive controller. With an undelayed power shutdown, the drive coasts in an uncontrolled way once the DC bus energy has been used up.

9.21.4 Deactivation via Mechanical Braking Device

Shutdown by mechanical braking devices should be activated simultaneously with switching off the power at the power supply module. Integration into the holding brake control of the drive controllers is possible, too. The following must be observed:

- Braking devices with electrical 24V DC control (electrically-released) and currents < 2 A can directly be triggered.
- Braking devices with electrical 24V DC control and currents > 2 A can be triggered via a suitable contractor.

Once the controller enabling signal has been removed, the holding brake control has the following effect:

- Fault reaction "0", "1" and "3".
The holding brake control drops to 0 V once the velocity is less than 10 mm/min or a time of 400 ms has elapsed.
- Fault reaction "2":
The holding brake control drops to 0 V immediately after the drive enabling signal has been removed.

9.21.5 Response to a Mains

In order to be able to shut down the linear drive as fast as possible in the event of a mains failure,

Application and Construction Instructions

- either an uninterruptible power supply or
- additional DC bus capacities (capacitors), and /or
- mechanical braking facilities

must be provided.

Determining the required additional DC bus capacity

Additional capacities in the DC bus represent an additional energy store that can supply the brake energy required in the event of a mains failure.



The control voltage must be available even at a power failure for the time of braking! If needed, buffer the control voltage supply or feed the control voltage from the DC intermediate circuit if possible!

The additional capacity required for a deactivation upon a mains failure can be determined as follows:

$$C_{add} = \frac{m \cdot v_{max}}{U_{DCmax}^2 - U_{DCmin}^2} \cdot \left[3,5 \cdot \frac{F_{max}}{k_{iF}^2} \cdot R_{12} - v_{max} \cdot \left(\frac{F_R}{F_{max}} + 0.3 \right) \right]$$

C_{add}	Required additional DC bus capacitor in mF
m	Moved mass in kg
v_{max}	Maximum velocity in m/s
U_{DCmax}	Maximum DC bus voltage in V
U_{DCmin}	Minimum DC bus voltage in V
F_{max}	Maximum braking force of the motor in N
k_{iF}	Motor constant (force constant) in N/A
R_{12}	Winding resistance at 20°C
F_R	Frictional force in N

Fig.9-45: Determining the required additional DC bus capacitor

Prerequisites:

- Final velocity = 0
- Velocity-independent friction
- Constant deceleration
- Winding temperature 135 °C



The maximum possible DC bus capacity of the employed power supply module must be taken into account when additional capacities are used in the DC bus. Do not initiate a DC voltage short-circuit when additional capacitors are employed.

Application and Construction Instructions

9.21.6 Short-Circuit of DC bus

Most of the power supply modules of Bosch Rexroth permit the DC bus to be shortened when the power is switched off, which also establishes a short-circuit between the motor phases. When the motor moves, this causes a braking effect according to the principle of the induction; thereby the motor phases are shorted. The reachable braking force is not very high and velocity-dependent. The DC bus short-circuit can therefore only be used to support existing mechanical braking devices.

9.22 Position and Velocity Resolution

9.22.1 Drive Internal Position Resolution and Position Accuracy

In linear direct drives, a linear scale is used for measuring the position. The linear scale for linear motors supply sinusoidal output signals. The length of such a sine signal is known as the signal period. It is mainly specified in mm or μm .

With the drive controllers from Bosch Rexroth, the sine signals are amplified again in the drive (see Fig.9-47). The drive-internal amplification also depends on the maximum travel area and the signal period of the length measuring system. It always employs 2^n vertices (e.g. 2048 or 4096).

$$f_{\text{int}} = 2^{31} \cdot \frac{s_p}{x_{\text{max}}} \quad \text{rounding to } 2^n$$

f_{int} Multiplication factor (S-0-0256, Multiplication 1)

s_p Linear scale system signal period in mm (S-0-0116 resolution of encoder 1)

x_{max} Maximum travel (S-0-0278, maximum travel)

Fig.9-46: Multiplication factor




Fig.9-47: Drive-internal multiplication and/or interpolation of the measuring system signals

With a known signal period and a drive-internal multiplication, the drive-internal position resolution results as:

Application and Construction Instructions

$$\Delta x_d = \frac{s_p}{f_{int}}$$

Δx_d	Drive-internal position resolution
s_p	Linear scale system signal period (S-0-0116 resolution of encoder 1)
f_{int}	Multiplication factor (S-0-0256, Multiplication 1)
<i>Fig. 9-48:</i>	<i>Drive-internal position resolution</i>



The drive-internal position resolution is not identical to the reachable positioning accuracy.

Reachable positioning accuracy

The reachable position accuracy depends on the mechanical and control-engineering total system and is not identical to the drive-internal position resolution.

The reachable position accuracy can be estimated as follows (using empirical values):

$$\Delta x_{abs} = \Delta x_d \cdot 30...50$$

Δx_d	Drive-internal position resolution
Δx_{abs}	Position accuracy
<i>Fig. 9-49:</i>	<i>Estimating the reachable position accuracy</i>

Prerequisites: Optimum controller setting



The expected position accuracy cannot be better than the smallest position command increment of the superordinate control.

9.22.2 Velocity Resolution

The resolution of the velocity is proportional to the position resolution and inversely proportional to the sample time t_{AD} from:

$$\Delta v_d = \frac{\Delta x_d}{t_{AD}}$$

Δv_d	Velocity resolution in m/s
Δx_d	Drive-internal position resolution
t_{AD}	Sample time in s (IndraDrive: Basic Performance 250 μ s / Advanced 125 μ s)
<i>Fig. 9-50:</i>	<i>Velocity resolution</i>

10 Motor-Controller-Combinations

10.1 General Information

Technical data and figures of motor characteristic curves of the respective motors are shown in chapter [chapter 4 "Technical Data" on page 27](#).



Dimensioning and selection for separate motors results from the Gantry-arrangement .

Maximum allowed DC bus voltage

For MCL motors are, depending on their size, maximum DC bus voltages defined. Please also observe the information provided in [fig. 4-4 "General Technical Data" on page 31](#).

10.2 Motor-Controller-Combinations with NYCe 4000

Motor	NYCe 4120		NYCe 4140
	48 V	72 V	150 V
MCP015A-L040 MCP015B-L040	■	■	-
MCP020x-Vxxx		x	x
MCP030x-Vxxx		x	x
MCP040x-Vxxx		x	x
MCP070x-Vxxx		x	x

- Optimal combination
- x Allowed combination - reduced velocity, as the DC bus voltage is reduced in opposite to the nominal voltage
- Combination not allowed

Fig. 10-1: Motor-Controller-Combinations with NYCe 4000

Motor-Controller-Combinations

10.3 Motor-Controller-Combinations with IndraDrive Cs

		HCS01.1E-Wxxxx-A-02-...					HCS01.1E-Wxxxx-A-03-...				
		3x AC 110 ... 230 V / 1x AC 110 ... 230 V					3x AC 200 ... 230 V				
		W003	W006	W009	W013	W018	W005	W008	W018	W028	W054
necessary power cable		RKL4800				RKL4801	RKL4800		RKL4801		RKL4803
Motor											
MCP020	020B-V180	■					□				
	020B-V720		■				x	□			
	020C-V180		■				x	□			
	020C-V720			■				x	□		
	020D-V180			■				□			
	020D-V720				x	■			□		
MCP030	030B-V180		■				x	□			
	030B-V390		x	■				□			
	030C-V180			■				□			
	030C-V390			x	■				□		
	030D-V180				■				□		
	030D-V390				x	■			□		
MCP040	040B-V070		■				□				
	040B-V300			■				□			
	040C-V070		x	■				□			
	040C-V300				■				□		
	040E-V070				■				□		
	040E-V300					x			x	■	
	040G-V070					■			□		
	040G-V300									■	
MCP070	070C-V050			■				x	□		
	070C-V300					x			x	■	
	070D-V050				■				□		
	070D-V300									■	
	070F-V050					x			x	■	
	070F-V300									x	■
	070M-V050									x	■
	070M-V230										x

- Optimal combination
 □ allowed combination
 x allowed combination - but maximum force reduces, as controller is under-dimensioned.

Fig. 10-2: Motor-Controller-Combinations with IndraDrive Cs

11 Motor Dimensioning

11.1 General Procedure

The dimensioning and design of linear drives is significantly defined by the application-related profiles of velocity, feed force and the thermal connection. The basic sequence of sizing linear drives is shown in the figure below.




Fig.11-1: Basic procedure of sizing linear drives

Motor Dimensioning

11.2 Basic Formulae

11.2.1 General Movement Equations

The variables required for sizing and selecting the motor are calculated using the equations shown in the following.



When linear direct drives are configured, the process-related feed forces and velocities are used directly and without conversion for selecting the drive.

Velocity	$v(t) = \frac{s(t)}{dt}$
Acceleration:	$a(t) = \frac{v(t)}{dt}$
Force:	$F(t) = a(t) \cdot m + F_0(t) + F_p(t)$
Effective force:	$F_{eff} = \sqrt{\frac{1}{T} \cdot \int_0^T F(t)^2 dt}$
Average velocity:	$v_{avg} = \frac{1}{T} \cdot \int_0^T v(t) dt$

$v(t)$	Velocity profile vs. time in m/s
$s(t)$	Path profile vs. time in m
$a(t)$	Acceleration profile vs. time in m/s ²
$F(t)$	Force profile vs. time in N
m	Moved mass in kg
$F_0(t)$	Base force and friction in N
$F_p(t)$	Process or machining force in N
F_{eff}	Effective force in N
v_{avg}	Average velocity in m/s
t	Time in s
T	Total time in s

Fig. 11-2: General equations of motion

In most cases the mathematical description of the required positions vs. the time is known (NC-program, electronic cam disk). Using the preparatory function, velocity, acceleration and forces can be calculated. Standard software (such as MS Excel or MathCad) can be used for calculating the required variables, even with complex motion profiles.



The following Chapter provides a more detailed correlation for trapezoidal, triangular or sinusoidal velocity characteristics.

11.2.2 Feed Forces




Fig.11-3: Determining the feed forces

Acceleration force : $F_{ACC} = m \cdot a$

Force due to weight : $F_W = m \cdot g \cdot \sin \alpha \cdot (1 - \frac{f_{cb}}{100})$

Frictional force: $F_F = \mu \cdot (m \cdot g \cdot \sin \alpha + F_{ATT}) + F_0$

Maximum force : $F_{MAX} = F_{ACC} + F_F + F_W + F_P$

Effective force: $F_{EFF} = \sqrt{\frac{F_1^2 \cdot t_1 + F_2^2 \cdot t_2 + \dots}{t_{all}}}$

F_{ACC}	Acceleration force in N
F_W	Force due to weight in N
F_F	Frictional force in N
F_0	Additional frictional or base force in N (e.g. by seals of linear guides)
F_{MAX}	Maximum force in N
F_{EFF}	Effective force in N
F_P	Processing force in N
a	Acceleration in m/s^2
m	Moved mass in kg
g	Gravitational acceleration ($9.81 m/s^2$)
α	Axis angel in degrees (0° : horizontal axis; 90° : vertical axis)
f_{CB}	Weight compensation in %
t_{all}	Total duty cycle time in s
F_{ATT}	Attractive force between primary and secondary part in N
μ	Friction coefficient

Fig.11-4: Determining the feed forces

Motor Dimensioning



For sizing calculations of linear motor drives, the moved mass of the motor component must be taken into account (in particular, if the slide masses are relatively small). The moved mass is only noted after successful motor selection. Thus, first make assumptions for these variables and verify these values after the motor has been selected.




Fig. 11-5: Determining the resulting feed forces according to motion type and direction

Motor Dimensioning

(1)	Acceleration (up) :	$F = F_{ACC} + F_F + F_W$
(2)	Const. velocity (up) :	$F = F_F + F_W$
(3)	Deceleration (up) :	$F = -F_{ACC} + F_F + F_W$
(4)	Acceleration (down) :	$F = F_{ACC} + F_F - F_W$
(5)	Const. velocity (down) :	$F = F_F - F_W$
(6)	Deceleration (down) :	$F = -F_{ACC} + F_F - F_W$
(7)	Idle time:	$F = F_W$

F	Resulting force in N
F _{ACC}	Acceleration force in N
F _W	Force due to weight in N
F _F	Frictional force in N

Fig. 11-6: Determining the resulting feed forces according to motion type and direction



With horizontal axis arrangement, the weight is $F_W = 0$.

Further directional base and process forces must be taken into account.

Motor Dimensioning

11.2.3 Average Velocity

The average velocity is required for determining the mechanical continuous output of the drive. [fig. 11-2 "General equations of motion" on page 138](#) shows the general way of determining the average velocity. The following calculation can be used for a simple determination in trapezoidal or triangular velocity profiles:




Fig.11-7: Triangular or trapezoidal velocity profile

$$v_{avg i} = \frac{|v_a| + |v_e|}{2}$$

$$v_{avg} = \frac{\sum v_{avg i} \cdot t_i}{t_{all}}$$

$v_{avg i}$	Average velocity for a velocity segment of the duration t_i in m/s
v_a	Initial velocity of the velocity segment in m/s
v_e	Final velocity of the velocity segment in m/s
v_{avg}	Average velocity over total duty cycle time in m/s
t_i	Duration of velocity segment in s
t_{all}	Total duty cycle time, including breaks and/or standstill time, in s

Fig. 11-8: Determining the average velocity with triangular or trapezoidal velocity profile

11.2.4 Trapezoidal Velocity Profile

General Information

This mode of operation is characteristic for the most applications. After a constant acceleration phase, a motion with constant velocity up to the deceleration phase with constant deceleration follows.




Fig. 11-9: Trapezoidal velocity profile

To determine the respective parameters acceleration a , velocity v , path s and time t for the trapezoidal drive, do a case differentiation regarding velocity:

- Initial velocity $v_a = 0$ or $v_a \neq 0$
- Final velocity $v_e = 0$ or $v_e \neq 0$

Acceleration, Initial Velocity $v_a = 0$



- Velocity $v \neq \text{constant}$
- Initial velocity $v_a = 0$
- Acceleration $a = \text{constant and positive}$

Motor Dimensioning

Acceleration:	$a = \frac{v_c}{t_a} = \frac{2 \cdot s}{t_a^2} = \frac{v_c^2}{2 \cdot s}$
Final velocity:	$v_c = a \cdot t_a = \sqrt{2 \cdot a \cdot s} = \frac{2 \cdot s}{t_a}$
Travel:	$s = \frac{v_c}{2} \cdot t_a = \frac{v_c^2}{2 \cdot a} = \frac{a \cdot t_a^2}{2}$
Time:	$t_a = \frac{v_c}{a} = \frac{2 \cdot s}{v_c} = \sqrt{\frac{2 \cdot s}{a}}$

a Acceleration in m/s²

v_c Final velocity in m/s

t_a Acceleration time in s

s Travel covered during acceleration in m

Fig. 11-10: Constantly accelerated movement, initial velocity $v_a = 0$ (for trapezoidal velocity profile)

Acceleration, Initial Velocity $v_a \neq 0$ 

- Velocity $v \neq$ constant
- Initial velocity $v_a \neq 0$
- Acceleration $a =$ constant and positive

Motor Dimensioning

Acceleration:	$a = \frac{v_c - v_a}{t_a} = \frac{2 \cdot s}{t_a^2} - \frac{2 \cdot v_a}{t_a} = \frac{v_c^2 - v_a^2}{2 \cdot s}$
Velocity:	$v_c = v_a + a \cdot t_a = \sqrt{2 \cdot a \cdot s + v_a^2} = \frac{2 \cdot s}{t_a} - v_a$
Travel:	$s = \frac{v_c + v_a}{2} \cdot t_a = \frac{v_c^2 - v_a^2}{2 \cdot a} = v_a \cdot t_a + \frac{a \cdot t_a^2}{2}$
Time:	$t_a = \frac{v_c - v_a}{a} = \frac{2 \cdot s}{v_c + v_a} = \frac{\sqrt{2 \cdot a \cdot s + v_a^2} - v_a}{a}$

a Acceleration in m/s²

v_c Final velocity in m/s

v_a Initial velocity in m/s

t_a Acceleration time in s

s Travel covered during acceleration in m

Fig. 11-11: Constantly accelerated movement, initial velocity $v_a \neq 0$ (for trapezoidal velocity profile)

Constant Velocity



- Velocity $v = \text{constant}$
- Acceleration $a = 0$

Acceleration:	$v_c = \frac{s_c}{t_c}$
Travel:	$s_c = v_c \cdot t_c$
Time:	$t_c = \frac{s_c}{v_c}$

v_c Average velocity in m/s

t_c Time during constant velocity in s

s_c Travel covered constant velocity in m

Fig. 11-12: Constant velocity (for trapezoidal velocity profile)

Braking, Final Velocity $v_e = 0$



- Velocity $v \neq \text{constant}$
- Final velocity $v_e = 0$
- Acceleration $a = \text{constant and negative}$

Motor Dimensioning

Acceleration:	$a = \frac{v_c}{t_b} = \frac{2 \cdot s}{t_b^2} = \frac{v_c^2}{2 \cdot s}$
Velocity:	$v_c = a \cdot t_b = \sqrt{2 \cdot a \cdot s} = \frac{2 \cdot s}{t_b}$
Travel:	$s = \frac{v_c}{2} \cdot t_b = \frac{v_c^2}{2 \cdot a} = \frac{a \cdot t_b^2}{2}$
Time:	$t_b = \frac{v_c}{a} = \frac{2 \cdot s}{v_c} = \sqrt{\frac{2 \cdot s}{a}}$

a Acceleration in m/s²

v_c Final velocity in m/s

t_b Braking time in s

s Travel covered during acceleration in m

Fig. 11-13: Constantly accelerated movement, initial velocity $v_e = 0$ (for trapezoidal velocity profile)

Braking, Final Velocity $v_e \neq 0$ 

- Velocity $v \neq \text{constant}$
- Final velocity $v_e \neq 0$
- Acceleration $a = \text{constant and negative}$

Acceleration:	$a = \frac{v_c - v_e}{t_b} = \frac{2 \cdot v_c}{t_b} - \frac{2 \cdot s}{t_b^2} = \frac{v_c^2 - v_e^2}{2 \cdot s}$
Velocity:	$v_e = v_c - a \cdot t_b = \sqrt{v_c^2 - 2 \cdot a \cdot s} = \frac{2 \cdot s}{t_b} - v_c$
Travel:	$s = \frac{v_c + v_e}{2} \cdot t_b = \frac{v_c^2 - v_e^2}{2 \cdot a} = v_c \cdot t_b + \frac{a \cdot t_b^2}{2}$
Time:	$t_a = \frac{v_c - v_e}{a} = \frac{2 \cdot s}{v_c + v_e} = \frac{v_c - \sqrt{v_c^2 - 2 \cdot a \cdot s}}{a}$

a Acceleration in m/s²

v_c Initial velocity in m/s

v_e Final velocity in m/s

t_b Braking time in s

s Travel covered during acceleration in m

Fig. 11-14: Constantly accelerated movement, initial velocity $v_e \neq 0$ (for trapezoidal velocity profile)

11.2.5 Triangle-shaped Velocity Profile

In contrast to the trapezoidal characteristic, this velocity profile does not have a phase of constant velocity. The acceleration phase is immediately followed by the deceleration phase. This characteristic can frequently be found in conjunction with movements of short strokes.




Fig. 11-15: Triangular velocity profile

Motor Dimensioning

Acceleration:	$a = \frac{2 \cdot v_{\max}}{t} = \frac{4 \cdot s_{\text{all}}}{t^2} = \frac{v_{\max}^2}{s}$
Velocity:	$v_{\max} = \frac{a \cdot t}{2} = \sqrt{a \cdot s_{\text{all}}} = \frac{2 \cdot s_{\text{all}}}{t}$
Travel:	$s_{\text{all}} = \frac{v_{\max} \cdot t}{2} = \frac{v_{\max}^2}{4 \cdot a} = \frac{a \cdot t^2}{4}$
Time:	$t = \frac{2 \cdot v_{\max}}{a} = \frac{4 \cdot s_{\text{all}}}{v_{\max}} = \sqrt{\frac{4 \cdot s_{\text{all}}}{a}}$

v_{\max} Maximum velocity in m/s
 a Acceleration in m/s²
 s_{all} Total motion travel in m
 t Positioning time in s

Fig. 11-16: Determine triangular velocity profile

11.2.6 Sinusoidal Velocity Profile

This velocity profile results, for example, from the circular interpolation of two axes (circular movement) or the oscillating movement of one axis (grinding, for example).

The specified variables are chiefly the motion travel s or the circle diameter $2r$ and the period T .




Fig. 11-17: Insert motion profiles of an axis at sinusoidal velocity.

Travel profile:	$s(t) = r_1 \cdot \sin(\omega \cdot t)$
Velocity profile:	$v(t) = r_1 \cdot \cos(\omega \cdot t) \cdot \omega$
Acceleration profile:	$a(t) = -r_1 \cdot \sin(\omega t) \cdot \omega^2$
Jerk profile:	$r(t) = -r_1 \cdot \cos(\omega t) \cdot \omega^3$
	$\omega = \frac{2 \cdot \pi}{T} = 2 \cdot \pi \cdot f$

s(t)	Chronological development of the path
r ₁	Radius
r(t)	Chronological path of velocity
t	Time
a(t)	Acceleration
ω	Circular frequency
T	Cycle duration
f	Frequency

Fig. 11-18: Calculation formula for motion profiles of an axis at sinusoidal velocity.

The following calculation bases on [fig. 11-17 "Insert motion profiles of an axis at sinusoidal velocity." on page 148](#) and [fig. 11-18 "Calculation formula for motion profiles of an axis at sinusoidal velocity." on page 149](#):

Motor Dimensioning

Maximum acceleration :	$a_{\max} = r \cdot \left(\frac{2 \cdot \pi}{T} \right)^2$
Maximum velocity :	$v_{\max} = r \cdot \frac{2 \cdot \pi}{T}$
Average velocity:	$v_{\text{avg}} = \frac{2 \cdot v_{\max}}{\pi} = \frac{4 \cdot r}{T}$
Acceleration force :	$F_{\text{ACC}} = a_{\max} \cdot m$
Effective force :	$F_{\text{EFF}} = \sqrt{\frac{F_{\text{acc}}^2}{2} + F_0^2}$
Vertical axis arrangement:	$F_{\text{EFFv}} = \sqrt{\frac{F_{\text{acc}}^2 + F_{0 \text{ up}}^2 + F_{0 \text{ down}}^2}{2}}$
Base force up movement:	$F_{0 \text{ up}} = F_0 + F_w$
Base force down movement:	$F_{0 \text{ down}} = F_0 - F_w$

a_{\max}	Maximum acceleration in m/s ²
v_{\max}	Maximum velocity in m/s
r	Motion travel in one direction (or circle radius) in m
T	Period in s
m	Moved mass in kg
F_{ACC}	Acceleration force in N
F_{EFF}	Effective force in N
F_{EFFv}	Effective force at vertical or inclined axis arrangement in N
F_0	Base force, e.g. frictional force in N
F_w	Force due to weight in N

Fig. 11-19: Calculation formulae for sinusoidal velocity profile



Further directional base and process forces must additionally be taken into account.

11.3 Duty Cycle and Feed Force

11.3.1 General Information

The relative duty cycle ED specifies the duty cycle percentage of the load with respect to a total duty cycle time, including idle time. The thermal load capacity of the motor limits the duty cycle. Capacity the motor with rated force is possible over the entire duty cycle time. The duty cycle must be reduced at $F > F_{dN}$ (see [fig. 11-20 "Correlation between duty cycle and feed force" on page 151](#)) in order to not thermally overload the motor at higher feed forces.




Fig. 11-20: Correlation between duty cycle and feed force

11.3.2 Determining the Duty Cycle

Due to the linear correlation of force and current, the detection of relative duty cycle ED_{ideal} happens via the correlation:

$$ED_{ideal} = \left(\frac{F_{EFF}^2}{F_{MAX}^2} \right) \cdot 100$$

ED_{ideal} Cyclic duration factor in %
 F_{EFF} Effective force or rated force in N
 F_{MAX} Maximum feed force

Fig. 11-21: Approximate determination of duty cycle ED

Use [fig. 11-22 "Determining the duty cycle ED" on page 151](#) to determine the possible relative duty cycle.

$$ED_{real} = \frac{P_{vN}}{P_{AVG a}} \cdot 100$$


ED_{real} Possible relative duty cycle in %
 P_{vN} Maximum dissipated rated power loss of the motor in W (for continuous power loss see Chapter 4 "Technical Data")
 $P_{AVG a}$ Average motor power loss in application over a duty cycle time including idle time in W

Fig. 11-22: Determining the duty cycle ED

11.4 Determining the Drive Power

11.4.1 General Information

To size the power supply module or the mains rating, you must determine the rated (continuous) and maximum power of the linear drive.



Take the corresponding simultaneity factor into account when determine the total power of several drives that are connected to a single power supply module.

11.4.2 Rated Output


The rated output corresponds to the sum of the mechanical and electrical motor power.

Total rated output:
$$P_c = P_{cm} + P_V$$

Mechanical rated output:
$$P_{cm} = F_{eff} \cdot v_{avg}$$

Rated electrical output:
$$P_V = \left(\frac{F_{eff}}{F_N} \right)^2 \cdot P_{VN} \quad \text{with } F_{eff} \leq F_N$$

P _c	Rated power in W
P _{cm}	Mechanical rated output in W
P _V	Electrical continuous power loss of motor in W
F _{eff}	Effective force in N (from application)
v _{avg}	Average velocity in m/s
F _N	Rated force of the motor in N (see Chapter 4 "Technical data")
P _{VN}	Rated power loss of the motor in W (see Chapter 4 "Technical data")
Fig. 11-23: Rated power of the linear motor	



The rated electrical output (see [fig. 11-23 "Rated power of the linear motor" on page 152](#)) is reduced when the rated force is reduced.

11.4.3 Maximum Output

The maximum output is also the sum of the mechanical and electrical maximum output. It must be made available to the drive during acceleration and deceleration phase or for very high machining forces, for example.

Total maximum power:
$$P_{\max} = P_{\max m} + P_{\max e}$$


Mechanical maximum power:
$$P_{\max m} = F_{\max} \cdot v_{F \max}$$

- P_{\max} Total maximum power in W
- $P_{\max m}$ Mechanical maximum power in W
- $P_{\max e}$ Electrical maximum power in W (see the following diagram)
- F_{\max} Maximum feed force in N
- $v_{F \max}$ Maximum velocity with F_{\max} in N

Fig.11-24: Maximum power of the linear motor



When the maximum feed force is reduced against the achievable maximum force of the motor, the electrical maximum output $P_{\max e}$ is reduced, too. To determine the reduced electrical maximum output $P_{\max e}$ use fig. 11-25 "Diagram used for determining the reduced electrical power loss" on page 153.



- F_{\max} Maximum force of the motor in N
- F Maximum force application in N
- $P_{v \max}$ Maximum power loss of the motor in W
- P_v Power loss of the motor application in W

Fig. 11-25: Diagram used for determining the reduced electrical power loss

Motor Dimensioning

11.4.4 Power Loss

The power loss corresponds the electric continuous power loss of the motor.

$$\text{Required cooling capacity: } P_{ce} = \left(\frac{F_{eff}}{F_N} \right)^2 \cdot P_{vN} \quad \text{with } F_{eff} \leq F_N$$

P_V Electrical power loss of motor in W

F_{eff} Effective force in N

F_N Rated force of the motor in N (see Chapter 4 "Technical data")

P_{vN} Rated power loss of the motor in W (see Chapter 4 "Technical data")

Fig. 11-26: Required cooling capacity of the linear motor

11.5 Efficiency

The efficiency of electrical machines is the ration between the motor output and the power fed to the motor. With linear motors, it is determined by the application-related traverse rates and forces, and the corresponding motor losses.

[fig. 11-27 "Determining the efficiency of linear motors" on page 154](#) can be used for determining and/or estimating the motor efficiency.

$$\eta = \frac{P_{mech}}{P_{mech} + P_V} = \frac{F \cdot v}{(F \cdot v) + P_V} = \frac{1}{1 + \frac{P_V}{F \cdot v}}$$

η Efficiency

P_{mech} Mechanical output in W

P_V Power loss in W

F Feed force in N

v Velocity in m/s

Fig. 11-27: Determining the efficiency of linear motors

11.6 Thermal Connection of MCL Motors on the Machine

An effective power loss dissipation is precondition to reach the specified motor data. The height of the power loss in the motor is significantly defined by the utilization capacity of the motor. The motor performance depends from as good as or as fast as the power loss can be dissipated.

If the existing power loss of the motor cannot be sufficiently dissipated via the natural convection, the heat introduction via the screw on surfaces into the machine construction increases. A very good heat dissipation is reached, if the screw on surfaces of the primary part and the screw on surfaces of the secondary part are both connected with a heat-dissipating machine construction.

Please observe that an increased heat introduction into the machine construction reduced the reachable accuracy. The operating temperature of the motor winding has a vital importance when dimensioning the system with highest exactness.

With increasing winding temperature, the dissipated heat amount increases on the machine, too. If the temperature niveau of the machine must be constantly kept, the motor should be a little overdimensioned or a cooling prepared on the machine side.




When the screw on surfaces of the motor components, especially the screw on surface of the primary part, is made of a badly heat-dissipating material (like plastics), it must be reckoned with a reduced power data of the motor.

As a general rule, the heat dissipation must increase proportional to size and length and thus the higher power loss of the motor, if the same motor utilization must be reached.

Please observe a optimal heat dissipation possibility of the motor components when dimensioning the machine. Only then, a power loss of the motor via adjacent machine parts can be guaranteed optimally.



The following details should help to estimate the reachable motor power data in dependence of the thermal connection of the motor. The figured installation modes can be selected and observed at motor-controller-dimensioning in IndraSize and at commissioning in IndraWorks.

Motor Dimensioning



① Available motor force
② Mounting method
Fig. 11-28: Motor force dependend from the thermal connection

Explanation of installation modes

Mounting method	Schematic display	Description
A		Installation mode A requires a good thermal connection of the motor together with an additional cooling , e.g. by using a fan or by cooling the screw on surfaces. A metallic conducting surface is required as consistency of the screw on surfaces on the machine.
B		Installation mode B (preferred solution) requires a good thermal connection . A metallic conducting surface is required as consistency of the screw on surfaces on the machine. Technical data for this installation mode are specified in chapter 4 "Technical Data" on page 27.

Motor Dimensioning



Mounting method	Schematic display	Description
C		Installation mode C assumes that a motor component, either primary or secondary part, is thermally isolated and other components must be well-dissipating connected onto the machine. In this case, reckon with a reduced output of the motor, due to moderate possibility of heat dissipation of this motor component.
D		Installation mode D This kind of assembly is the worst case and you must reckon with a significant reduced output of the motor.


Fig. 11-29: Explanation of installation modes

12 Handling, Transport and Storage

12.1 Identification of the Motor Components

12.1.1 Primary Part

An engraved type designation is on the primary part.




① Type designation (not for MCP015)

② Serial number

Fig. 12-1: Position of type designation and serial number of primary part

Additionally, the primary part has two identical type plates at delivery. The type plates allow an univocal identification of the primary part and can be fixed on the machine or used elsewhere by the user.




- 1 Motor type
- 2 Type designation
- 3 Designation of origin
- 4 UL sign
- 5 Factory number
- 6 Mass of primary part
- 7 CE sign
- 8 Rated power
- 9 Maximum input voltage
- 10 Company address
- 11 Insulation system
- 12 Thermal temperature class
- 13 Protection class by housing
- 14 Production date
- 15 Pole graduation
- 16 Rated current
- 17 Serial number
- 18 Rexroth bar code
- 19 Part number

Fig. 12-2: Type plate example of primary part

Handling, Transport and Storage

12.1.2 Secondary Part


The type designation with serial number is at the bottom of the secondary part.



- ① Type designation
- ② Serial number

Fig. 12-3: Position of type designation and serial number of secondary part

Additionally, the secondary part has two identical type plates at delivery. The type plates allow an univocal identification of the secondary part and can be fixed on the machine or used be used elsewhere by the user.



- 1 Motor type
- 2 Type designation
- 3 Designation of origin
- 4 UL mark
- 5 Factory number
- 6 Secondary part mass
- 7 CE sign
- 8 Maximum input voltage
- 9 Company address
- 10 Insulation system
- 11 Thermal temperature class
- 12 Protection class by housing
- 13 Production date
- 14 Serial number
- 15 Rexroth bar code
- 16 Part number

Fig. 12-4: Example of a secondary part type plate

12.2 Delivery Status and Packaging

12.2.1 Primary Parts

The primary parts are separately packed in a cardboard box. To identify the primary part, a type designation exist on the packaging.

12.2.2 Secondary Parts

The secondary parts are separately packed in a cardboard box. To identify the secondary part, a type designation exist on the packaging.

Warnings on the packaging of the secondary parts

On the packaging of the secondary parts is a self-adhesive warning sign which indicates with the following warning notes to the dangers after opening the package and further handling of secondary parts.




	<p>⚠ WARNING</p> <p>Health hazard to people with heart pacemakers, metal implants and hearing aids when in proximity to these parts!</p> <p>Strong magnetic fields due to permanent motor magnets!</p> <p>⇒ Anyone with pacemakers, metal implants or hearing aids are not permitted to approach or to handle these motor parts.</p> <p>⇒ If you have such conditions, consult with a physician prior to handling these parts.</p>	<p>⚠ WARNING</p> <p>Gesundheitsgefahr für Personen mit Herzschrittmachern, metallischen Implantaten oder Splintern und Hörgeräten in unmittelbarer Umgebung dieser Teile!</p> <p>Starkes Magnetfeld durch Permanentmagnete der Motorteile!</p> <p>⇒ Personen mit Herzschrittmachern, metallischen Implantaten oder Hörgeräten dürfen sich nicht diesen Motorteilen nähern oder damit umgehen.</p> <p>⇒ Besteht die Notwendigkeit für solche Personen, sich diesen Teilen zu nähern, so ist das zuvor von einem Arzt zu entscheiden.</p>
	<p>⚠ CAUTION</p> <p>Hazardous to fingers and hands due to high attractive forces of permanent motor magnets!</p> <p>Strong magnetic fields due to permanent motor magnets!</p> <p>⇒ Handle only with protective gloves! Handle with extreme care.</p>	<p>⚠ VORSICHT</p> <p>Quetschgefahr von Finger und Hand durch starke Anziehungskräfte der Magnete!</p> <p>Starkes Magnetfeld durch Permanentmagnete der Motorteile!</p> <p>⇒ Nur mit Schutzhandschuhen anfassen. Vorsichtig handhaben.</p>
	<p>⚠ CAUTION</p> <p>Hazardous to sensitive parts!</p> <p>⇒ Keep watches, credit cards, identification cards with magnetic strips, magnetic tape and ferromagnetic material (such as iron, nickel, and cobalt) away from magnetic parts.</p>	<p>⚠ VORSICHT</p> <p>Zerstörungsgefahr empfindlicher Teile!</p> <p>⇒ Uhren, Kreditkarten, Scheckkarten und Ausweise mit Magnetstreifen sowie alle ferromagnetische Metallteile wie Eisen, Nickel und Cobalt von den Permanentmagneten der Motorteile fernhalten.</p>

Fig. 12-5: Warning label on the packaging of secondary parts



The self-sticking warning label (sizes approx. 110 mm x 150 mm) can be ordered from Rexroth (MNR R911278745).

12.3 Checking the Motor Components

12.3.1 Factory Checks of the Motor Components

Electrical inspections

The Bosch Rexroth linear motors undergo the following electrical checks at the factory:

- High voltage test according to DIN EN 60034-1
- Insulation resistance test acc. to DIN EN 60204-1
- Verification of the specified electrical characteristics

Mechanical inspections

The Bosch Rexroth linear motors undergo the following mechanical tests:

- Form and location tolerances acc. to ISO 1101
- Construction and fits acc. to DIN 7157
- Surface structure acc. to DIN ISO1302

Handling, Transport and Storage

- Thread test acc. to DIN 13, Part 20



Each motor is accompanied by a corresponding test certificate.

⚠ CAUTION

**Destruction of motor components due to im-
properly repeated high-voltage inspection! In-
validation of warranty!**

- ⇒ Avoid repeated tests.
- ⇒ Observe the guidelines of DIN EN 60034-1

EMV radia interference suppres-
sion

The linear motor components of Bosch Rexroth have been subjected to an EMV type test and have been certified as complying
EN 55011 Limit Class B, VDE 0875 Part 11

12.4 Transport and Storage
12.4.1 Notes about Transport

Transport our products only in their original package. Also observe specific ambient factors to protect the products from transport damage.

⚠ CAUTION

**Risk of injury and / or damage when using
secondary parts!**

The inner side of the secondary parts is adhered with permanent magnets. Please observe, that no ferro-magnetic parts, like screws can fall into the air gap. Observe the warning notes on [fig. 12-5 "Warning label on the packaging of secondary parts" on page 161](#), too.

Based on DIN EN 60721-3-2, the tables below specify classifications and limit values which are allowed for our products while they are transported by land, sea or air. Observe the detailed description of the classifications to take all of the factors which are specified in the particular class into account.

Allowed classes of ambient conditions during transport acc. to DIN EN 60721-3-2

Classification type	Allowed class
Classification of climatic ambient conditions	2K2
Classification of biological ambient conditions	2B1
Classification of chemically active materials	2C2
Classification of mechanically active materials	2S2
Classification of mechanical ambient conditions	2M1

Fig. 12-6: Allowed classes of ambient conditions during transport

For the sake of clarity, a few essential environmental factors of the aforementioned classifications are presented below. Unless otherwise specified, the values given are the values of the particular class. However, Bosch Rexroth reserves the right to adjust these values at any time based on future experiences or changed ambient factors.

Handling, Transport and Storage

Allowed transport conditions

Environmental factor	Symbol	Unit	Value
Temperature	T_T	°C	-20 ... +80 ¹⁾
Air humidity (relative air humidity, not combinable with quick temperature change)	φ	%	75 (at +30 °C)
Occurrence of salt mist			Not permitted ¹⁾

1) Differs from DIN EN 60721-3-2

Fig. 12-7: Allowed transport conditions

Air freight

⚠ CAUTION

Possible influence of plane electronic on board through magnet fields!

⇒ Heed the packaging and transport instructions (IATA 953)

12.4.2 Notes about Storage

Storage Conditions

Generally, Bosch Rexroth recommends to store all components until they are actually installed in the machine as follows:

- In their original package
- At a dry and dustfree location
- At room temperature
- Free from vibrations
- Protected against light or direct insolation

On delivery, protective sleeves and covers may be attached to our motors. They must remain on the motor for transport and storage. Do not remove these parts until shortly before assembly.

Based on DIN EN 60721-3-1, the tables below specify classifications and limit values which are allowed for our products while they are stored. Observe the detailed description of the classifications to take all of the factors which are specified in the particular classification into account.

Allowed classes of ambient conditions during transport acc. to DIN EN 60721-3-1

Classification type	Class
Classification of climatic ambient conditions	1K2
Classification of biological ambient conditions	1B1
Classification of chemically active materials	1C2
Classification of mechanically active materials	1S1
Classification of mechanical ambient conditions	1M2

Fig. 12-8: Allowed classes of ambient conditions during storage

For the sake of clarity, a few essential environmental factors of the aforementioned classifications are presented below. Unless otherwise specified, the values given are the values of the particular class. However, Bosch Rexroth reserves the right to adjust these values at any time based on future experiences or changed ambient factors.

Handling, Transport and Storage

Allowed classes of ambient conditions during storage acc. to DIN EN 60721-3-1

Environmental factor	Symbol	Unit	Value
Air temperature	T_L	°C	-20 ... +60 ¹⁾
Relative air humidity	φ	%	5 ... 95
Absolute air humidity	ρ_w	g/m ³	1 ... 29
Condensation	- -	- -	Not allowed
Ice formation/freezing	- -	- -	Not allowed
Direct solar radiation	- -	- -	Not allowed ¹⁾
Occurrence of salt mist	- -	- -	Not allowed ¹⁾

1) Differs from DIN EN 60721-3-1

Fig. 12-9: Allowed storage conditions

Storage Times

Additional measures must be taken on commissioning to preserve proper functioning – irrespective of the storage time which may be longer than the warranty period of our products. However, this does not involve any additional warranty claims.

Motors

Storage time	Measures for commissioning
< 1 year	Visual inspection of all parts to be damage-free Check the electric contacts to verify that they are free from corrosion
1 ... 5 years	
> 5 years	

Fig. 12-10: Measures before commissioning motors that have been stored over a prolonged period of time

Cables and Connectors

Storage time	Measures before commissioning
< 1 year	None
1 ... 5 years	Check the electric contacts to verify that they are free from corrosion
> 5 years	If the cable or the cable jacket has porous parts, change it; otherwise check the electric contacts to verify that they are free from corrosion

Fig. 12-11: Measure before commissioning cables and connectors that have been stored over a prolonged period of time

13 Assembly

13.1 Basic Precondition


Before you begin with the assembly, you must observe or check the following points:

- Observation of the necessary installation sizes (see [chapter 5.1 "Installation Tolerances" on page 55](#))
- Machine construction fulfills the requests for mounting (stiffness, attractive force, feed force and acceleration force, etc.) and is prepared for installation of the motor components.
- Clean screw-on surfaces between machine and motor components
- Installation of motor components by skilled personnel only
- Compliance of danger and safety notes is guaranteed.

13.2 Arrangement of Motor Components

When planning the machine observe and specify in which position the motor components are assembled into the machine. The stop or screw on surfaces must be prepared by the machine manufacturer for assembly of the motor components.

Basically, is no limitation regarding motor component arrangement. It can be an advantage to mount the secondary part sideways (see [fig. 13-1 "Possible arrangement of motor components" on page 165](#)) or to the bottom that no dirt, proceeding residues, a.s.o. can fall from above into the air gap between primary and secondary part. In this context, please observe the notes under [chapter 9.3.4 "Protection of the Motor Installation Space" on page 107](#) how to mold the installation space that the motor components are optimally protected. The following figure shows a possibility how a motor can be installed. Depending from the utilization, another arrangement can be preferred.



- ① Secondary part MCS
- ② Primary part MCP
- ③ Measuring system
- ④ Machine slide
- ⑤ Guides / profile rails

Fig. 13-1: Possible arrangement of motor components

13.3 Installation of Motor Components

The order of installation of motor components is depending from the machine construction or the available space in the machine. Thereby, the arrangement of the motor components play a significant role.

The following assembly examples always assume that the motors are assembled in single arrangement. For parallel arrangement of the motos, a respectively adjusted procedure must be considered, which can be basically derived from the following possibilities of assembly.

- **Possibility A**

First, assemble the secondary parts. Then, slide the primary part from the side into the secondary parts and fasten it on the machine. The primary parts of the MCP015 can be inserted from above into the secondary part due to their construction (T-shape).

- **Possibility B**

First, assemble only one secondary part. Insert the primary part on the front-side (or MCP015 from above) into the secondary part and fasten it on the machine. Then, assemble the remaining secondary parts.

- **Possibility C**

First, assemble the primary part and then the secondary part(s).


13.4 Air-gap, Parallelism and Symmetry of the Motor Components

Parallelism and Symmetry

When mounting primary and secondary parts, their position is specified by the holes or threads within the machine slide and within the machine bed (see).

Due to the clearance, which exists within the holes of the screw connections, the motor components must be adjusted correctly acc. to [fig. 13-2 "Aligning the motor components" on page 167](#) before the screws are tightened. This can be done via pressing the motor components on the screw-on surfaces and stop faces. If the installation dimensions in [fig. 5-1 "Mounting sizes and tolerances MCL015" on page 56](#) and [fig. 5-2 "Mounting sizes and tolerances MCL020 ... 070" on page 57](#) were kept, the correct arrangement of both motor components to each other result automatically.

Assembly



- ① Secondary part
② Primary part

Fig. 13-2: Aligning the motor components

Air gap

NOTICE

Motor damage due to insufficient air gap between primary and secondary part!

After assembly, check the free movement of the motor components to each other immediately. Therefore, move the versatile motor components by hand over the complete traverse path. The versatile motor components must be freely moveable at each position over the total traverse path - without any contact to fixed motor components. Furthermore, with this test you will detect a faulty assembly (e.g. due to dirt under the mounting surface, faulty installation dimension, insufficient machine rigidity etc.) in time.

13.5 Fastening Secondary Part


Observe absolute cleanliness during assembly. No dirt should exist on the screw-on surface and stop faces and no dirt or other parts (e.g. screws, washers, etc.) should reach the area of magnetic pull on the secondary part. Any kind of foreign bodies in this area could damage the primary or secondary part at the first traverse of the motor components.



- For safety reasons, the user or machine manufacturer is NOT allowed to dismount the secondary part in its separate parts!
- To fasten the secondary parts, it is only allowed to use new, unused screws.
- Tighten all screws with the specified tightening torque. Additionally secure the screw connection, e.g. with Loctite 243.
- After assembly, check if any foreign bodies exist in the secondary part.

The secondary parts can be connected with the machine via two different ways.

Assembly



① Fastening type variant 1
② Fastening type variant 2
Fig. 13-3: Secondary part fastening types

The screw-on surfaces and stop faces must be cleaned and be free of grease before the secondary parts can be screwed on the machine construction. For suitable screw selection and its tightening torques refer to the following table.

NOTICE Motor damage due to insufficient air gap between primary and secondary part!

Observe during fastening of the secondary parts according to variant 2 that the maximum screw-in depth specified in the table, is kept. In the case of defiance, the primary part can be irreparably damaged due to collision with overhanging screws.

Fastening type - variant 1

Secondary part MCS ...	Drilling diameter within the secondary part	Maximum screw-in depth	Bolt size-ISO-grade (DIN EN ISO 4762)	Property class	Tightening torque (+/-10 %)
		Variant 1			
015	4.5 mm	depending from the customer's application	M4	8.8	3.1 Nm
020	4.3 mm		M4		3.1 Nm
030	4.3 mm		M4		3.1 Nm
040	6.4 mm		M6		10.4 Nm
070	8.5 mm		M8		25 Nm

Fig. 13-4: Fastening mode (variant 1) with tightening torques for MCS

Fastening type - variant 2

Secondary part MCS ...	Thread diameter with-in secondary part	Maximum screw-in depth	Bolt size-ISO-grade (DIN EN ISO 4762)	Property class	Tightening torque (+/-10 %)
		Variant 2			
015	M4	9 mm	M4	8.8	3.1 Nm
020	M5	9 mm	M5		6.1 Nm
030	M5	9 mm	M5		6.1 Nm
040	M6	11 mm	M6		10.4 Nm
070	M8	12 mm	M8		25 Nm


Fig. 13-5: Fastening mode (variant 2) with tightening torques for MCS

The calculation of the screw connection to fasten the secondary parts is based on the presumption that both, the screw-on surfaces of the secondary part and on the machine are cleaned and the secondary part is directly screwed with the machine.



- In certain cases, the secondary part cannot be screwed directly with the machine, because additional materials like distance plates, heat-conductive paste etc. are between the secondary part and the machine. Therefore, a sufficient property of the screw-connection must be ensured by the machine manufacturer.
- The effect of liquid screw locking is damaged due to loosening or re-tightening of the screws (e.g. due to torque check) and must be carried out again.
- To fasten the secondary parts, use all fastening points.

13.6 Fastening the Primary Part



- ① Fastening type variant 1
② Fastening type variant 2

Fig. 13-6: Primary part fastening type

Assembly

Primary part MCP ...	Bolt size- ISO-grade (DIN EN ISO 4762)	Screw-in depth		Property class	Tightening torque (+/-10 %)
		Variant 1	Variant 2		
015	M3	see chapter chapter 5 "Specifications" on page 55		8.8	1.3 Nm
020	M4				3.1 Nm
030					
040					
070	M6				10.4 Nm

Fig. 13-7: Tightening torque for the fastening screws of the primary parts

The screw-on surfaces and stop faces must be cleaned and be free of grease before the primary parts can be screwed on the machine construction. Secure all screwed connections with screw connection, e.g. Loctite 243.

Mounting instructions:

- 1. Prepare threaded holes and screws for assembly.
- 2. Fasten the primary part with screws 1, 2, 3...x until the primary part lies on the slide.

Fasten screws - from inside to outside - 1, 2, 3 ... x with nominal tightening torque:




Fig. 13-8: Tightening row of screws



- To fasten the primary parts, use **all fastening points**.
- The effect of liquid screw locking Loctite 243 is damaged due to loosening or re-tightening of the screws (e.g. due to torque check) and must be carried out again.

14 Commissioning, Operation and Maintenance

14.1 General Information for Startup of Ironless IndraDyn L Motors

The startup of linear motors is different to the rotary servo motors. The following points have to be especially noticed when startup synchronous-linear motors.

Parameters	Synchronous-linear motors are kit motors whose single components are – completed by an encoder system – directly installed into the machine by the manufacturer. As a result, kit motors do not feature any data memory to provide motor parameters, standard controller settings, etc. All parameters must be manually entered or loaded to the drive during commissioning. The start-up-program IndraWorks makes all motor parameters of Bosch Rexroth available.
Controller Optimization	The procedure used for optimizing the control loops (current, velocity and position controllers) of linear direct drives corresponds to the one used for rotary servo drives. At linear drives are only the adjustment limits higher. At linear direct drives compared with rotary servo drives can be, for example, a 10-fold higher kv-factor adjusted. Precondition therefore is an appropriate machine construction (see chapter 9.3 "Requirements on the Machine Design" on page 106).
Moving Masses	At controlled rotary servo drives are automatic-control engineering modifications at the rate of motor-moment of inertia to demand-moment of inertia. Such a modification is not available for direct drives with linear motors. The moved foreign mass is independent from the motor self-mass.
Encoder Polarity	The polarity of the actual-speed (length measuring system) must agree with the force polarity of the motor. This connection has to be established before commutation-adjustment.
Commutation Adjustment	It is necessary at synchronous linear motors to receive the position of the primary part relating on the secondary part by return after start or after a malfunction. This is referred to as pole position detection or commutation adjustment. This means that the commutation adjustment is the establishment of a position reference to the electrical or magnetic model of the motor. The commutation adjustment can be done after installation of the motor components and length measuring system. The way of doing the commutation adjustment complies with the measuring principle of the length measuring system.

14.2 General Requirements

14.2.1 General Information

The following requirements must be met to ensure successful commissioning:

- Compliance with safety-related guidelines and instructions
- Check of electrical and mechanical components for reliable functioning
- Availability and provision of required tools
- Adherence to the commissioning procedure described below

14.2.2 Checking All Electrical and Mechanical Components

Check all electrical and mechanical components prior to commissioning and pay particular attention to the following issues:

Commissioning, Operation and Maintenance



- Ensure safety for man and machine
 - Properly install the motor
 - Properly establish the power connection of the motor
 - Correct connection of the length measuring system
 - Ensure proper function of existing safety limit switches, door switches, etc.
 - Ensure proper function of the emergency stop circuit and emergency stop.
 - Ensure proper and complete machine construction (mechanical installation)
 - Availability and function of suitable end-of-stroke damper.
 - Ensure proper connection and function of drive controller and control unit
-

14.2.3 Tools

a start-up software IndraWorks

The motors can be commissioned either directly via an NC terminal or via special commissioning software. The IndraWorks commissioning software allows menu-driven, custom-designed and motor-specific parameterization and optimization.

PC

When commissioning, IndraWorks requires a commercial Windows PC.

Commissioning via NC

Commissioning via the NC control unit requires access to all drive parameters and functionalities.

Multimeter

At troubleshooting and check of the components can be a multimeter with the possibility to voltage metering and resistor measuring helpful.

14.3 General Start-Up Procedure

In the following flow-chart is the general start-up procedure at synchronous linear motors MCL shown. The individual items are explained in more detail in the chapters following thereafter.

Commissioning, Operation and Maintenance




Fig. 14-1: General start-up procedure at synchronous linear motors

14.4 Parameterization

14.4.1 General Information

IndraWorks allows entering or editing certain parameters and executing commands during commissioning by means of menu-driven dialogs and list representations or, optionally, via the control terminal.

14.4.2 Entering Motor Parameters



Motor parameters are specified by Rexroth and may not be changed by the user. Commissioning is not possible, if these parameters are not available. In this case, please contact your Rexroth Sales and Service Facility.

⚠ WARNING

Activation of the motor immediately after motor parameter input may result in injury and mechanical damage! The motor is not yet ready for operation after the motor parameters have been entered!

- ⇒ Enter the parameters for the linear scale.
- ⇒ Check and adjust the measuring system polarity.
- ⇒ Adjust the commutation

The motor parameters can be entered in the following way:

- Use IndraWorks to load all the motor parameters.
- Enter the individual parameters manually via the controller.
- With series machines, load a complete parameter record via the controller or IndraWorks

14.4.3 Motor Parameter at Parallel Arrangement

Are two linear motors operated in a control device, the following parameters have to be adjusted when commissioning:

Parameter	Designation	Matching coefficient
P-0-4016	Direct-axis inductance of motor	x 0.5
P-0-4017	Quadrature-axis inductance of motor	x 0.5
P-0-4048	Stator resistance	x 0.5
S-0-0106	Current loop proportional gain 1	x 0.5
S-0-0109	Motor peak current	x 2
S-0-0111	Motor current at standstill	x 2

Fig. 14-2: Parameter adjustment at parallel arrangement



If not the maximum possible continuous nominal force or the maximum possible peak load of the motor is necessary, a smaller drive device can be used. In this case, the setting of the mentioned currents must be adjusted to the selected drive device.

14.4.4 Entering Length Measuring System Parameter

- Encoder type** The type of the linear scale must be defined. Therefore serves the parameter P-0-0074, Encoder type 1.

Commissioning, Operation and Maintenance

Encoder type	P-0-0074
Incremental measuring system	2
Absolute encoder with ENDAT interface	8
Incremental encoder with Hall sensor	14 or 15 (depending from hardware configuration)

Fig. 14-3: Defining the encoder type



Detailed information can be found in the project planning manual of the used drive controller and/or firmware

- Rexroth IndraDrive MPx-xx Parameter description, MNR R911328651
- Rexroth IndraDrive MPx-xx Parameter description, MNR R911297317
- Rexroth IndraDrive Firmware MPx-xx Functional description, MNR R911328670
- Rexroth IndraDrive MPx-xx Parameter description, MNR R911326767

Signal period

Linear scale for linear motors generate and interpret **sinusoid signals**. The signal period must be entered in parameter S-0-0116, Resolution of feedback 1.

Please observe the details of the measuring system manufacturer regarding resolution of encoder signals.

14.4.5 Entering Drive Limitations and Application-related Parameters

Drive limitations

The possible selectable drive limitations include:

- Current limitation
- Force limitation
- Velocity limitations
- Travel range limitations

Application-related parameters

Application-related drive parameters include, for example, parameterization of the drive fault reaction.



Detailed information can be found in the project planning manual of the used drive controller and/or firmware See also [chapter 14.4.4 "Entering Length Measuring System Parameter" on page 174](#).

14.5 Determining the Polarity of the Linear Scale

In order to avoid direct feedback in the velocity control loop, the effective direction of the motor force and the count direction of the linear scales must be the same.

⚠ WARNING

Different effective directions of motor force and count direction of linear scale cause uncontrolled movements of the motor upon power-up!


⇒ Secure the motor against uncontrolled movement

⇒ Adjust effective direction of motor force equal to linear scale count direction.

Effective direction of motor force

To set the correct sensor polarity:

The effective direction of the motor force is always positive in the direction of the cable connection of the primary part.




① Force direction

Fig. 14-4: Effective direction of motor force

Effective direction motor force =
linear scale count direction

When the primary part is moved in the direction of the cable connection, the count direction of the linear scale must consequently be positive:



① Force direction

② Counting direction

③ linear scale

Fig. 14-5: Effective direction motor force = linear scale count direction



The encoder polarity is selected via the primary part (cable connection). The installation direction or the pole sequence of the secondary part does not have any influence on the selection of the sensor polarity.

The encoder polarity is selected via the parameter

S-0-0277, position encoder type 1 (Bit 3)

Position, velocity and force data must not be inverted when the linear scale count direction is set:

S-0-0085, Torque/force polarity parameter 0000000000000000

S-0-0043, Velocity polarity parameter 0000000000000000

S-0-0055, Position polarities 0000000000000000

14.6 Commutation Adjustment

14.6.1 General Information

Setting the correct commutation angle is a prerequisite for maximum and constant force development of the synchronous linear motor.



Commutation adjustment must always be performed in the following cases:

- ⇒ Initial start-up
- ⇒ After the mechanical attachment of the length measuring system has been modified
- ⇒ Replacement of the linear scale
- ⇒ Modification of the mechanical attachment of the primary and/or secondary part

This procedure ensures that the angle between the current vector of the primary part and the flux vector of the secondary part is always 90°. The motor supplies the maximum force in this state.

Adjustment procedure

Different commutation adjustment procedures have been implemented in the firmware. The figure below shows the correlation between the employed linear scale and the method that is to be used.

Commissioning, Operation and Maintenance




Fig. 14-6: Commutation adjustment method for ironless synchronous linear motors



Observe the following requirements for commutation adjustment:

- ⇒ Effective direction motor force = linear scale count direction
- ⇒ Ensure correct motor and encoder parameterization
- ⇒ Follow the adjustment procedures described
- ⇒ Ensure reasonable parameterization of the current and velocity control loops
- ⇒ Correctly connect the motor power cable
- ⇒ Ensure protection against uncontrolled movements

DANGER

Errors in commutation adjustment may result in malfunctions and/or uncontrolled movements of the motor!

Do the commutation adjustment very carefully! Please observe the detailed notes about commutation in the documentation under [chapter 14.4.4 "Entering Length Measuring System Parameter"](#) on page 174.

Commissioning, Operation and Maintenance

Motor connection The individual phases of the motor power connection must be assigned correctly. See also ["Connection power cable" on page 113](#).

Parameter verification To ensure a correct commutation adjustment, the following parameters should be checked again:

Identity number	Description	Description / function
S-0-0085	Torque/force polarity parameter	See parameter description <ul style="list-style-type: none"> Rexroth IndraDrive MPx-xx, MNR R911328651 Rexroth IndraDrive MPx-xx, MNR R911297317
S-0-0043	Velocity polarity parameter	
S-0-0055	Position polarities	
P-0-4014	Type of construction of motor	
P-0-0018	Number of pole pairs/pole pair distance	
S-0-0116	S-0-0016, Feedback 1 Resolution	
P-0-0522	Control word for commutation setting	
P-0-0074	Encoder type 1 (motor encoder)	

Fig. 14-7: Parameters that must be checked prior to commutation adjustment

14.6.2 Sinusoidal Procedure

Limitations and detailed notes about sinusoidal procedure can be found in

- Rexroth IndraDrive Firmware MPx-xx Funktionsbeschreibung, MNR R911328670
- Rexroth IndraDrive MPx-xx Parameter description, MNR R911326767

14.6.3 Hall Sensor Procedure

The Hall sensor procedure is used when an incremental measuring system in connection with a Hall unit within the primary part is operated. Please also observe the information about the Hall unit provided in [chapter 7.1 "Hall Unit" on page 85](#).

Commutation via analog Hall unit The following sercos parameter must be described before commissioning when a Rexroth IndraDrive Cs is operated.

Commissioning, Operation and Maintenance

Identity number	Description	Value	
P-0-0508 (for MCP020)	Commutation - Offset ¹⁾	594 (Encoder rotational direction not inverted ²⁾	97 (Encoder rotational direction inverted ²⁾
P-0-0508 (for MCP030 ... 070)	Commutation - Offset ¹⁾	922 (Encoder rotational direction not inverted ²⁾	176 (Encoder rotational direction inverted ²⁾
P-0-0074	Encoder type 1 (motor encoder)	15	

- 1) The parameter is used to enter the motor dependend constant. It is not the real commutation offset. This is displayed after automatic calculation in parameter P-0-0521 "Effective commutation offset".
- 2) For adjusted encoder rotational direction see S-0-0277, Bit 3

Fig. 14-8: Parameters that must be checked prior to commutation adjustment

With the aforementioned adjustments, the effective commutation offset (P-0-0521) is calculated automatically when switching into the operating mode. The drive is ready for power switch-on



The procedure "Reference point - optimal commutation offset" cannot be used for analog Hall units, as the necessary parameter P-0-0508 is already used for the procedure "Commutation via analog Hall units".

Commutation via digital Hall unit

The following sercos parameter must be described before commissioning when a Rexroth IndraDrive Cs is operated:

Identity number	Description	Value
P-0-0509 (for MCP020)	Commutation - Offset, abrasive ¹⁾	434
P-0-0509 (for MCP030 ... 070)	Commutation - Offset, abrasive ¹⁾	62
P-0-0074	Encoder type 1 (motor encoder)	23

- 1) The parameter is used to enter the motor dependend constant. It is not the real commutation offset. This is displayed after automatic calculation in parameter P-0-0521 "Effective commutation offset".

Fig. 14-9: Parameters that must be checked prior to commutation adjustment



When commissioning with IndraWorks, the value for operation with not inverted encoder rotational direction is provided in parameter P-0-508. For inverted encoder rotational direction, adjust the value according to Fig. 14-8.

With the aforementioned adjustments, the effective commutation offset (P-0-0521) is calculated automatically when switching into the operating mode. By commutation via digital Hall unit, only an exactness of +/- 30° is electrically reached. Thereby, reckon with a maximum power loss of 14%.

The "Reference point - optimal commutation offset must be prepared that the maximum motor force is available.

Procedure on IndraDrive Cs:

Commissioning, Operation and Maintenance

1. Activate initial commissioning mode (P-0-0522, Bit 15)
2. Do the commutation adjustment via sinusoidal procedure.
3. Switch axis in "AF".
4. Start fine commutation.
5. Activate reference point drive.

When the reference point is reached, the "Reference-point optimal commutation-offset" (P-0-0508) is stored.

6. Deactivate initial commissioning mode.

For every restart of the machine, the abrasive definition of the commutation offset (+30°) is done by switching into the operating mode. The drive can drive to the reference point with reduced force, now. As soon as the reference point is reached or passed, the drive resumes the reference point- optimal commutation offset and the maximum force is available for the axis.

14.6.4 Measuring Procedure: Measuring the Reference between Primary and Secondary Part


If this procedure is used for commutation adjustment, the relative position of the primary part with respect to the secondary part must be determined. The benefit of this procedure is that the commutation adjustment requires neither the power to be switched on nor the axes to be moved. Commutation adjustment need only be performed during the first-time commissioning.



This procedure requires an absolute length measuring system.

Measuring the relative position between primary and secondary part

Depending on the accessibility of primary and secondary part in the machine or system, the relative position between primary and secondary part can be measured in different ways.



- l Relative position reference point ①
- b Relative position reference point ②
- l_p Length primary part

Fig. 14-10: Measuring the relative position between primary and secondary part



From now on, the position of the primary part must not be changed until the commutation adjustment procedure is terminated!

Calculation of P-0-0523, commutation adjustment measured value

The input value for P-0-0523 that is required for calculating the commutation offset, is determined from the measured relative position of the primary part with respect to the secondary part (Fig. 14-10, distance d, e, f or g, depending on accessibility), and a motor-related constant k_{mx} (see Fig. 14-11 and Fig. 14-12).

Commissioning, Operation and Maintenance

$$\text{Reference point 1: } P-0-0523 = a - k_{mx}$$

$$\text{Reference point 2: } P-0-0523 = -b - l_p - k_{mx}$$

P-0-0523 Commutation adjustment measured value in mm

l Relative position reference point ① in mm (Fig. 14-10)

b Relative position reference point ② in mm (Abb. 14-10)

k_{mx} Motor constant for commutation adjustment in mm

l_p Length of primary part in mm

Fig. 14-11: Calculation of P-0-0523, commutation adjustment measured value



Ensure that the sign is correct when you determine P-0-0523, commutation adjustment measured value. If P-0-0523 is determined with a negative sign, this must be entered when the setup procedure is started.

Motor constant k_{mx} for commutation adjustment

Primary part	k_{mx} in mm
MCP020	9,1
MCP030 / 040 / 070	49,6

Fig. 14-12: Motor constant k_{mx} for commutation adjustment

Example on MCP040C for reference point ①

$a = 100 \text{ mm}$, $k_{mx} = 49.6 \text{ mm}$

$P-0-0523 = a - k_{mx} = 100 \text{ mm} - 49.6 \text{ mm} = 50.4 \text{ mm}$

Example on MCP040C for reference point ②

$b = 20 \text{ mm}$, $k_{mx} = 49.6 \text{ mm}$, $l_p = 187 \text{ mm}$

$P-0-0523 = -b - l_p - k_{mx} = -20 \text{ mm} - 187 \text{ mm} - 49.6 \text{ mm} = -256.6 \text{ mm}$

Activation of commutation adjustment command

Prerequisites:

1. The drive must be in the A0-13 state during the subsequent adjustment procedure (=ready for power connection).
2. The position of the primary part and/or the slide must not have changed since the relative position of the primary part with respect to the secondary part has been measured.

Once the determined value P-0-0523, Commutation setting measured value, has been entered, the command P-0-0524 (D300 commutation setting command) must be started. The commutation offset is calculated in this step.



If the drive is in command start "AB" (drive ready for operation), the commutation offset with the selected procedure (saturation or sinusoidal procedure) is determined for automatic commutation.

The command must subsequently be cleared.

14.7 Setting and Optimizing the Control Loop

14.7.1 General Procedure

The control loop settings in a digital drive controller have an essential importance for the properties of the servo axis. The control loop structure consists of a cascaded position, velocity and current controller. Which of the controllers is active is defined by the operation mode.



Defining the control loop settings requires the corresponding expertise.

The procedure used for optimizing the control loops (current, velocity and position controllers) of linear direct drives corresponds to the one used for rotary servo drives. At linear drives are only the adjustment limits higher.




Fig. 14-13: Setting and optimizing the control loop of synchronous linear drives.

Commissioning, Operation and Maintenance



For more detailed information refer to

- Rexroth IndraDrive Firmware MPx-xx Funktionsbeschreibung, MNR R911328670
- Rexroth IndraDrive MPx-xx Parameter description, MNR R911326767

Automatic control loop setting

Rexroth drive controllers are able to perform automatic control loop adjustment.

Filtering mechanical resonance vibrations

Digital drives from Rexroth are able to provide a narrow-band suppression of vibrations that are produced due to the power train between motor and mechanical axis system. This results in increased drive dynamics with good stability.

The position or velocity feedback in the closed control loop excites the mechanical system of the slide that is moved by the linear drive to perform mechanical vibrations. This behavior, known as "Two-mass vibrational system", is mainly in the frequency range from 400 to 800 Hz. It depends on the rigidity of the mechanical system and the spatial expansion of the system.

In most cases, this "Two-mass vibrational system" has a clear resonant frequency that can be selectively suppressed by a rejection filter installed in the drive.

When the mechanical resonant frequency is suppressed, the dynamic properties of the velocity control loop and of the position control loop may, under certain circumstances, be improved as compared with closed-loop operation without rejection filter.

This leads to an increased profile accuracy and shorter cycle times for positioning processes at a sufficient distance to the stability limit.

Rejection frequency and bandwidth of the filter can be selected. The highest attenuation takes effect on the rejection frequency. The bandwidth defines the frequency range at which the attenuation is less than -3 dB. A higher bandwidth leads to less attenuation of the rejection frequency!




Fig. 14-14: Amplitude response of the rejection filter in relation to the bandwidth, qualitative

14.7.2 Parameterization and Optimization of Gantry Axes

General Information

Prerequisites:

- The parameter settings of the axes are identical
- Parallelism of the guides of the Gantry axes
- Parallelism of the linear scale
- In the controller, the axes are registered as individual axes



Drive-internal axis error compensation procedures can be used for compensating the misalignments between two linear scales as or the mechanical system. Please refer to the corresponding description of functions of the drive controller for a description of the operational principle and the parameter settings.




Fig. 14-15: Possible misalignment with the linear scale of a Gantry axes

Parameter settings

When using Gantry axes, you must ensure that the parameter settings of the following parameters are identical:

- Motor parameter
- Polarity parameters for force, velocity and position
- Control loop parameters

We have:

$$k_{v1} = k_{v2}$$

$$k_{p1} = k_{p2}$$

k_v Position controller kv-factor S-0-0104

k_p Velocity controller proportional gain S-0-0100

Fig. 14-16: Proportional gains in the position and velocity control loop of both axes.

Velocity controller integral time (integral part)

The following possibilities must be taken into account for the velocity controller integral time (integral part):

Commissioning, Operation and Maintenance

	Possibility 1	Possibility 2	Possibility 3	Possibility 4
Alignment of length linear scale and guides	ideal	not ideal	not ideal	not ideal
Integral Part	in both axes	in both axes	in one axis only	in no axis
Behaviour of the axes	Since both motors follow the position command value ideally, there will not be a distortion of the mechanical system	Both axes work against each other until there is an equalization via the mechanical coupling or until the maximum current of one or both drive controller(s) has been reached and a control effect is no longer possible.	The axis without integral-part permits a continuous position offset. The size of the position offset depends on the rigidity of the mechanical coupling of both axes and of the proportional gains in the position and velocity control loop.	Both axes permit a continuous position offset. The size of the position offset depends on the proportional gains in the position and velocity control loop.

Fig.14-17: Parameterization of the velocity controller integral time S-0-0101 for Gantry-axes.

Optimization The previously described procedure must be followed for optimizing the position and velocity loop.



Any parameter modifications that are made during the optimization of Gantry axes must always be made in both axes simultaneously. If this is not possible, the parameter changes should be made during optimization in smaller subsequent steps in both axes.

14.7.3 Estimating the Moved Mass Using a Velocity Ramp

Often, the exact moving mass of the machine slide is not known. Determining this mass can be made difficult by moving parts, additionally mounted parts, etc.

The procedure explained below permits the moving axes mass to be estimated on the basis of a recorded velocity ramp. This permits, for example, the acceleration capability of the axis to be estimated.

Preparation This procedure requires the oscillographic recording of the following parameters:

- S-0-0040, actual velocity value
- S-0-0080, torque/force command value

You can either use an oscilloscope or the oscilloscope function of the drive in conjunction with IndraWorks or NC.




Fig. 14-18: Oscillogram of velocity and force

$$m = 30 \cdot F_N \cdot \left(\frac{F_{ACC} + F_{DEC}}{100\%} \right) \cdot \frac{\Delta t}{\Delta v}$$

m	Moved axis mass in kg
F_N	Continuous nominal force of the motor in N
F_{ACC}	Force command value during acceleration in %
F_{DEC}	Force command value during braking in %
Δv	Velocity change during constant acceleration in m/min Acceleration in m/min
Δt	Time change during constant acceleration in s

Fig. 14-19: Determining the moved axis mass on the basis of a recorded velocity ramp

Prerequisites:

1. Correct parameter settings of the rated motor current (basis of representation S-0-0080)
2. Frictional force not directional
3. Recording of Δv and Δt at constant acceleration
4. Do measuring with a motor force between F_N and F_{max} .



Due to possible direction-related force variations, this procedure cannot or only conditionally be used for vertical axes.

Commissioning, Operation and Maintenance

14.8 Maintenance and Check of Motor Components

14.8.1 General Information

The motor components of IndraDyn L do not need any maintenance. Due to external influence, the motor components can be damaged during operation. There should be a preventive maintenance of the linear motor components within the service intervals of the machine or system.

14.8.2 Check of Motor and Auxiliary Components

The following points should be observed and if necessary restored during the preventive check of motor and auxiliary components:

- Noticeable sound during operation
- Scratches on primary and secondary part
- Dirt (e.g. shavings, swarfs, grease by guides etc.) within the air gap between primary and secondary part
- State of power and encoder cables in a drag chain.
- State of linear scale (e.g. soiled)
- State of guides (e.g. deterioration of linear guides)

14.8.3 Electrical Check of Motor Components

The electrical defect of a primary part can be checked by measuring electrical characteristics. The following variables are relevant:

- Resistance between motor connecting wires 1-2, 2-3 and 1-3
- Inductance between motor connecting wires 1-2, 2-3 and 1-3
- Insulation resistance between motor connecting wires and guides

Resistance and inductance

The measured values of resistance and inductance can be compared with the values specified in Chapter "Technical Data". The individual values of resistance and inductance measured between the connections 1-2, 2-3 and 1-3 should be identical – within a tolerance of $\pm 5\%$. There can be a phase short circuit, a fault between windings, or a short circuit to ground if one or more values differ significantly. If so, the primary part must be exchanged.

Isolation resistance

The insulation resistance – measured between the motor connecting leads and ground – should be at least 1 M Ω (MegaOhm) The primary part must be replaced in this case.



If there are and doubts during the electrical verification, please consult Rexroth Service.

14.9 Operation with Third-party Controllers

Rate of rise of voltage The electrical insulation system of the motor is subject to a higher dielectric load in converter mode than when it is operated with a merely sinusoidal source voltage. The voltage load of the winding insulation in converter mode is mainly defined by the following factors:

- Crest value of voltage
- Rise time of pulses at the motor terminals
- Switching frequency of final converter stage
- Length of power cable to the motor

Main components are the switching times of the final converter stage and the length of the power cable to the motor. The rates of rise of the voltage occurring at the motor may not exceed the pulse voltage limits specified in **DIN VDE 0530-25 (VDE 0530-25):2009-08 (picture 14, limit curve A)**, measured at the motor terminals of two strands in relation to the rise time.



The final stages of IndraDrive converters keep this limits.

14.10 Environmental Protection and Disposal

14.10.1 Environmental Protection

Production Processes The products are made with energy- and resource-optimized production processes which allow re-using and recycling the resulting waste. We regularly try to replace pollutant-loaded raw materials and supplies by more environment-friendly alternatives.

No Release of Hazardous Substances Our products do not contain any hazardous substances which may be released in the case of appropriate use. Normally, our products will not have any negativ influences on the environment.

Significant Components Basically, our products contain the following components:

Electronic devices

- steel
- aluminum
- copper
- synthetic materials
- electronic components and modules

Motors

- steel
- aluminum
- copper
- brass
- magnetic materials
- electronic components and modules

14.10.2 Disposal

Return of Products Our products can be returned to our premises free of charge for disposal. It is a precondition, however, that the products are free of oil, grease or other dirt. Furthermore, the products returned for disposal must not contain any undue foreign material or foreign components.

Send the products "free domicile" to the following address:

Bosch Rexroth AG
Electric Drives and Controls
Buergermeister-Dr.-Nebel-Strasse 2
97816 Lohr am Main, Germany

Packaging The packaging materials consist of cardboard, wood and polystyrene. These materials can be recycled anywhere without any problem.

Commissioning, Operation and Maintenance

For ecological reasons, please refrain from returning the empty packages to us.

Batteries and Accumulators

Batteries and accumulators can be labeled with this symbol.



The symbol indicating "separate collection" for all batteries and accumulators is the crossed-out wheeled bin.

The end user within the EU is legally obligated to return used batteries. Outside the validity of the EU Directive 2006/66/EC keep the stipulated directives.

Used batteries can contain hazardous substances, which can harm the environment or the people's health when they are improperly stored or disposed of.

After use, the batteries or accumulators contained in Rexroth products have to be properly disposed of according to the country-specific collection.

Recycling

Most of the products can be recycled due to their high content of metal. In order to recycle the metal in the best possible way, the products must be disassembled into individual modules.

Metals contained in electric and electronic modules can also be recycled by means of special separation processes.

Products made of plastics can contain flame retardants. These plastic parts are labeled according to EN ISO 1043. They have to be recycled separately or disposed of according to the valid legal requirements.

15 Service and Support

Our worldwide service network provides an optimized and efficient support. Our experts offer you advice and assistance should you have any queries. You can contact us **24/7**.

Service Germany

Our technology-oriented Competence Center in Lohr, Germany, is responsible for all your service-related queries for electric drive and controls.

Contact the **Service Helpdesk & Hotline** under:

Phone: **+49 9352 40 5060**
Fax: **+49 9352 18 4941**
E-mail: service.svc@boschrexroth.de
Internet: <http://www.boschrexroth.com>

Additional information on service, repair (e.g. delivery addresses) and training can be found on our internet sites.

Service worldwide

Outside Germany, please contact your local service office first. For hotline numbers, refer to the sales office addresses on the internet.

Preparing information

To be able to help you more quickly and efficiently, please have the following information ready:

- Detailed description of malfunction and circumstances resulting in the malfunction
- Type plate name of the affected products, in particular type codes and serial numbers
- Your contact data (phone and fax number as well as your email address)

Index

A

Acceleration.....	11
Acceleration capability.....	106
Acceleration force.....	106
Accessory.....	85
Accessory delivery.....	88
Accumulators.....	190
Active height.....	105
Additional components.....	13
Air freight.....	123
Air gap.....	55, 107, 167
Air humidity.....	121
Air temperature.....	121
Alignment.....	58
Allowed ambient temperature T_{UM}	30
Ambient temperature.....	31, 120
Arrangement motor components	
Primary parts in a row, parallel	110
Secondary parts	114
Several motor per axis	108
Arrangement of Motor Components	
Double comb arrangement	110
Gantry arrangement	113
Parallel arrangement	109
Single arrangement	108
Assembly	
Connection cable power	93
Hall unit connection cable	99
Attractive forces.....	10
Axis construction.....	103
Axis covering systems	
Bellow covers	127
Roller covers	127
Telescopic covers	127
Axis Cover Systems.....	127

B

back electromotive force.....	28
Batteries.....	190
Baulängen.....	105
BGR B11.....	123
Body aids.....	123
Braking Devices.....	126

C

Cable outlet.....	95
Cable output.....	111
CESign.....	122
Checking the Motor Components	
Factory-checked	161
Check of motor components	
On the customer side	188
Cinematic chains.....	106
Coil body.....	103

C

Commissioning	
Drive limitations	175
Length Measuring System Paramete	174
Motor parameter	174
Requirements	171
Tools	172
Commutation.....	85
Commutation adjustment.....	171, 177
Hall sensor procedure	179
Measuring principle	181
Sinusoidal procedure	179
Commutation offset angle.....	85
Connect	
Length measuring system	101
Connection	
Analog Hall unit	101
Digital Hall unit	100
Hall unit	98
Motor parallel arrangement	95
Motor single arrangement	94
Power	94
Power connection	91
Temperature sensor	97
Connection assignment	
Connection cable Hall unit	99
Connection cable.....	91
Allowed bending radius	91
Cable break	92
Cross section control wires	91
Cross section power wires	91
Diameter	91
Fixed installation	92
fix installation	91
flexible installation	91
Installation	91
Connection cable Hall unit.....	98
Allowed bending radius	98
Cross section control wires	98
Diameter	98
fix installation	98
flexible installation	98
Connection power cable.....	113
Contained substances	
see "Significant components"	189
Continuous nominal force F_N	29
Continuous rated force.....	28
Controller.....	85
Controller optimization.....	171
Control quality.....	106
Control systems.....	128
Cooling.....	72, 103
Power loss	116
Cooling down.....	118
Corrosion protection.....	104

Index

C

Cross-table..... 106

D

DC bus capacity..... 131

DC bus short-circuit..... 132

DC bus voltage..... 27, 28

Deactivation..... 129

Deceleration force..... 106, 115

Degree of protection..... 30, 31

Delivery Status..... 161

Design..... 72

Detent force..... 10

Dimensions..... 58

Dimension sheets

MCP015 60

MCP020 62

MCP030 64

MCP040 66

MCP070 68

MCS015 61

MCS020 63

MCS030 65

MCS040 67

MCS070 69

Disposal..... 189

Drive controller..... 28, 128

Drive Power..... 152

Drive system..... 17

Duty cycle..... 151

Duty cycle; relative duty cycle..... 30

Duty cycle (ED)..... 28

Dynamic..... 10

E

Effektive values..... 27

Efficiency..... 154

E-file number..... 30, 31

Electrical connection..... 72

Electric drive system..... 17

EMC..... 123

Emergency Stop..... 129

Encoder polarity..... 171

End Position Shock Absorber..... 127

Environmental conditions..... 27, 107, 121

Environmental protection..... 189

ESD..... 97, 98, 119

ESD protection..... 98, 119

Protective foil 97

Excitation of vibrations..... 106

Symbols

-Fields of Application..... 9

F

Fastening holes..... 58

Fastening rail..... 104

Fastening screws..... 88

Fastening type primary part..... 169

Fastening types secondary part 168

Feed force..... 11, 105, 137, 151

Inserted force reduction 115

Reduced covering 115

Feed forces..... 108

Final over temperature..... 118

Flange socket..... 91

Flange socket power..... 93

Force constant..... 27

Force constant K_{FN} 29

Force density..... 10

Force generation..... 103

Force reduction..... 115

Forces

Reactive forces 106

Foreign bodies..... 103

Frame length..... 72, 105

Frame size..... 72, 73, 105

Friction..... 107

G

Gantry arrangement..... 85, 109

Gantry-Arrangement..... 135

Gantry axes

Parameterization and optimization 185

Gantry structure..... 106

Grid size..... 110, 111

Grinding traces..... 107

Grounding..... 92

H

Hall unit..... 10, 72, 85, 98

Assembly 88

Disassembly 88

ESD protection 88

Installation space 88

Hall unit adapter box..... 89

Hall unit analog..... 72

Hall unit digital..... 72

Hall unit functional principle..... 85

Hall unit ordering designations..... 89

Handling..... 159

Hazardous substances..... 189

Heating Up..... 117

High rigidity..... 106

Holding devices..... 126

Humidity..... 103

I

IATA 953..... 123, 163

Identification of the Motor Components..... 159

I

I form.....	104
IndraDrive Cs.....	136
IndraWorks.....	172
Induced motor voltage.....	29
Inductivity.....	27
Initial start-up.....	85
Installation dimensions.....	55, 58
Installation dimensions and tolerances frame size MCL015.....	56
Installation mode	
Installation mode A	156
Installation mode B	156
Installation mode C	157
Installation mode D	157
Installation modes.....	156
Installation size.....	165
Installation tolerances.....	27, 55
Instructions on use.....	15
Appropriate use	15
Inappropriate use	16
Insulation system.....	189
Iron yoke.....	10
Isolation resistance	188

K

KTY84-130; see also temperature sensor.....	97
---	----

L

Length Measuring System	
Measuring System Cables	125
Length measuring system.....	101, 103, 107, 124
Length Measuring Systems	
Selection criteria	124
Linear guide.....	103
Linear guiding.....	126
Loop bandwidth.....	106

M

Machine base deformation.....	107
Machine construction	
Integrating linear scale	107
Mass reduction	106
Mechanically coupled axes	106
Rigidity	106
Magnetic field.....	85
Magnetic Fields.....	123
Mains failure.....	130
Malfunction.....	129
Maschine construction	
Requirements	106
Mass primary part m_p	30
Mass secondary part m_s	30
Maximum current I_{max}	29
Maximum DC bus voltage.....	135

M

Maximum DC bus voltage MCP015.....	31
Maximum DC bus voltage MCP020 ... 070.....	31
Maximum feed force.....	28, 29
Maximum force.....	28
Maximum force F_{max}	29
Maximum velocity v_{Fmax}	29
MCL - Motor Coreless Linear.....	10
MCP - Motor Coreless Primary part.....	10
MCS - Motor Coreless Secondary part.....	10
Mechanical braking devices.....	130
Mechanical design.....	73
Mechanical force effect.....	107
Mechanical protection.....	73
Minimum distances between primary parts	
.....	111, 112, 113
Mode of functioning.....	103
Modular system.....	105
Mold.....	103
Motor breakdown.....	107
Motor characteristic curve.....	28
Motor characteristic curves	
Characteristic curve	27
Motor component arrangement.....	165
Motor-Controller-Combinations.....	135
Motor coupling.....	106
Motor damage.....	107
Motor design	
Primary part	103
Secondary part	104
Motor dimensioning.....	137
Trapezoidal velocity profile	143
Triangle-shaped velocity profile	147
Motor Dimensioning	
Average velocity	142
Feed Forces	139
Movement Equations	138
Sinusoidal velocity profile	148
Motor installation space.....	107
Motor parameter.....	174
Motor temperature monitoring.....	119
Motor variants.....	71
Motor winding temperature.....	27
Mounting method.....	27
Mounting Sizes and Tolerances Frame Size	
MCL020 ...070.....	57
Moved mass.....	106
Moving masses.....	171

N

Natural convection.....	103, 155
Natural frequencies.....	106
Natural Frequency.....	106
Noise emission.....	124
Nominal velocity.....	28
Nominal Velocity v_N	29
NYCe 4000.....	135

Index

O

Operating behavior	27
Operation mode	28
Operation with third-party controllers	189
Options	85
Ordering Designations	71
Ordering designations Hall unit	89
Other design	72, 73
Output	
Maximum Output	153
Rated Output	152

P

Packaging	161, 189
Parallel arrangement	109
Motor parameter	174
Parallel arrangement, collective power cables	97
Parallel arrangement, separate power cables	96
Parallelism	55, 58, 166
Parameters	171
Parasitic effects	10
PELV	21
Permanent magnets	10, 104
Phase position	85
Pin assignment	
Connection cable length measuring system	102
Polarity of the Linear Scale	176
Pole pair	85
Pole pair width	85
Pole width t_p	29
Position Accuracy	132
Position accuracy	133
Position information	85
Position offset	109
Position Resolution	132
Position resolution	132, 133
Power	
Power loss	154
Power cable	93
Collective power cable	96
Installation	96
Parallel power cable	96
Power connector	93
Power loss	116
Power loss dissipation	155
Utilization capacity	155
Power spectrum	11
Power supply modules	128
Precision	10
Primary part	10
Primary part carrier	103
Process forces	106
Production processes	189
Product ordering	71
Product selection	71
Projections	106

P

Protection mode	107, 122
Protection of motor installation space	107
Protective conductor	92
Protective extra-low voltage	21
Protective foil	119
PWM-Frequency	30

R

Rated current I_N	29
Rated feed force	116
Rated force	151
Rated power loss P_{VN}	29
Recycling	190
Repairs	71
Resistor	27
Resonant frequency	106, 184
Return of products	189
RoHS conformity	123

S

Safety Instructions for Electric Drives and Controls	17
Saturation effect	10
Saturation effects	29
Scope of delivery	103
Scratch-formation	107
Screw-in depth	168, 169, 170
Secondary part	10
Segment length	73
Serial number MCP	159
Serial number MCS	160
Setting and Optimizing the Control Loop	183
Setup elevation	120
SHL03.1	100
SHL03.1 adapter box	100
Shock absorber	127
Short-circuit loss	116
Shutdown temperature	31
Significant components	189
Skeleton structures	106
Skilled personnel	165
Spare parts	71
Specifications	55
Standards	13
Start-Up	
Mass definition	186
Parameterization	173
Procedure	172
Storage	163
Storage temperature	31
Storage time	164
Strain relief	92
Support	
See service hotline	191
Symmetry	55, 58, 166

Index

T

Technical data	
Frame size MCL015	32
Frame size MCL020	34
Frame size MCL030	38
Frame size MCL040	42
Frame size MCL070	48
Temperature class	30, 31
Temperature model	97
Temperature monitoring	
Prewarning temperature	119
Shut-off temperature	119
Temperature sensor KTY84-130	119
Temperature sensor	97
Polarity	97
T form	104
Thermal connection	137, 155
Thermal coupling	28, 103
Thermal motor connection	107
Thermal time constant	117
Thermal time constant T_{th}	29
Tightening torque	168, 169, 170
Tightening torque Hall unit	88
Tolerances	58
Tool	88
Total duty cycle time	151
Touch of electrically active parts	103
Transport	162
Transport temperature	31
Travel path	55
travel velocity	29

T

Traverse path length	103
Type Codes	71
Type designation MCP	159
Type designation MCS	160
Type plates	159, 160

U

UL authorization	123
------------------	-----

V

Velocity	11, 28, 137
Velocity resolution	132, 133
Vertical axes	85
Vertical Axis	114
Vibrations	106
Voltage constant K_{EMK}	29

W

Warnings	161
Warning temperature	31
Weight Compensation	114
Winding	72
Winding inductivity L_{12}	29
Winding inductivity $L_{23/31}$	29
Winding protection	97
Winding resistance R_{12}	29
Winding temperature	116, 119
Wire end ferrules	91

Notes

Bosch Rexroth AG
Electric Drives and Controls
P.O. Box 13 57
97803 Lohr, Germany
Bgm.-Dr.-Nebel-Str. 2
97816 Lohr, Germany
Tel. +49 9352 18 0
Fax +49 9352 18 8400
www.boschrexroth.com/electrics



R911330592

DOK-MOTOR*-MCL*****-PR02-EN-P